



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI20002474/Eda3q2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 14-04-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|---------------------|-----------------|-----------------------|------------|
| Insured Veh. | SHC 3240T | Veh. Inspected | SKX 7318G |
| Policy No. | D-20094922MFSH | Coverage (\$) | 0.00 |
| Claim No. | D20000931MFSH/1 | Excess (\$) | 0.00 |
| Assign From | MAY CHUA | Assign Date | 11/02/2020 |

2. Vehicle Particulars & Condition

| | | | |
|-------------------------|--------------------|---------------------|------------|
| Make & Model | MITSUBISHI ATTRAGE | c.c | 1193 |
| Engine No. | HIDDEN | Year of Reg. | 2015 |
| Chassis No. | MMBSTA13AFH018828 | Colour | GREY |
| Odometer | 95878 | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | SPORTS RIM |
| General | GOOD | | |

3. Conditions of Tyres

| | | | |
|-----------------------|-------------|-------------|----------------|
| | Size | Make | Balance |
| R/H Front Tyre | 195/50 R15 | GOODYEAR | 5 mm |
| L/H Front Tyre | 195/50 R15 | GOODYEAR | 5 mm |
| R/H Rear Tyre | 195/50 R15 | GOODYEAR | 5 mm |
| L/H Rear Tyre | 195/50 R15 | GOODYEAR | 5 mm |

4. Description of Damages

| |
|--|
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. |
|--|

5. General Information

| | | | |
|-----------------------|--|------------------------|------------|
| Accident Date | 09/02/2020 | Inspection Date | 19/02/2020 |
| Survey held at | CYCLE & CARRIAGE AUTOMOTIVE PTE LTD 209 PANDAN GARDENS SINGAPORE 609339 | | |

5a. Remarks

| |
|--|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|--|

5b. Estimate Days of Repair

| | |
|-------------------------------------|-----------------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 4 Working Days |
|-------------------------------------|-----------------------|