



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2004301
INV Date 04/06/2020
Reference CC4/FCI20002475/Eda3s2
Code FCI2



PROFESSIONAL SERVICE FEE

Vehicle No. SJU 3988B
Insured Veh. SH 8290J
Claim No. D20000947MFSH
Policy No. D-20094922MFSH
Accident Date 02/02/2020
Inspection Date 25/02/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD	Ref : CC4/FCI20002475/Eda3s2
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877	Date : 04-06-2020
	Code : FCI2



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 8290J	Veh. Inspected	SJU 3988B
Policy No.	D-20094922MFSH	Coverage (\$)	0.00
Claim No.	D20000947MFSH	Excess (\$)	0.00
Assign From	MAY CHUA	Assign Date	12/02/2020

2. Vehicle Particulars & Condition

Make & Model	B.M.W. 420I	c.c	1997
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WBA3V12010PX80919	Colour	WHITE
Odometer	59732	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R18	GOODYEAR	5 mm
L/H Front Tyre	225/45 R18	GOODYEAR	5 mm
R/H Rear Tyre	225/45 R18	GOODYEAR	5 mm
L/H Rear Tyre	225/45 R18	GOODYEAR	5 mm

4. Description of Damages

	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.
--	--

5. General Information

Accident Date	02/02/2020	Inspection Date	25/02/2020
Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 SINGAPORE 159722		

5a. Remarks

	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--	--

5b. Estimate Days of Repair

	ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
--	-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJU 3988B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT FENDER LH (NPA)	NOT NECESSARY	-	-
1	FRONT FENDER EMBLEM LH (SPORT)	NOT NECESSARY	76.55	-
10	FRONT COWLING CLIPS @ \$5.00	NOT NECESSARY	50.00	-
1	FRONT SIDE MIRROR LH	MALFUNCTION	986.70	986.70
1	FRONT DOOR LH	DENTED	1,792.30	1,792.30
1	FRONT DOOR WEATHERSTRIP LH	NECESSARY	124.45	124.45
10	FRONT DOOR TRIM RIVET LH @ \$5.00	NECESSARY	50.00	30.00
	LESS 5% DISCOUNT		-154.00	-
	LESS 10% DISCOUNT		-	-293.34
			2,926.00	2,640.11
	<u>LABOUR</u>			
	TO REPAIR FRONT FENDER LH. TO REMOVE & REPLACE ALL ACCIDENT DAMAGED PARTS & STRAIGHTEN ON ACCIDENT DAMAGED PARTS.		400.00	300.00
	TO SPRAY PAINT ON ACCIDENT DAMAGED PARTS.		550.00	300.00
	TO REMOVE & TRANSFER FRONT DOOR MECHANISM POWER WINDOW MOTOR, DOOR LOCK & OTHER ATTACHMENT PARTS.		150.00	50.00
			1,100.00	650.00
	GRAND TOTAL		4,026.00	3,290.11
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,650.00

Report Ref No. CC4/FCI20002475/Eda3s2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJU 3988B

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJU 3988B

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJU 3988B

RE-INSPECTION

