

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20002480/AEA3Q2

Date: 28/05/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900082209

Claimant
Vehicle No : SMH3830E **Insured Vehicle No :** SLZ212B

Date of Loss: 07/02/2020 Nature of Claim: TP Claim No: 0266309362SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH3830E		
Make & Model:	TOYOTA VOXY HYBRID, 1.8 X CVT (A)	Engine No:	2ZR0C50860
Reg. Date:	21/01/2019 (Man. Year: 2018)	Chassis No:	ZWR800350220
Colour:	Black	Odometer:	88821 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,942.95	6,955.22	9,987.73	58.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,440.00	1,890.00	3,550.00	65.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,382.95	8,845.22	13,537.73	60.48
Approved Total (Overridden) (S\$)		7,000.00		
(S\$)	22,382.95	7,000.00	15,382.95	68.73
+ GST 7.00/7.00% (S\$)	1,566.81	490.00	1,076.81	68.73
Nett Amount (S\$)	23,949.76	7,490.00	16,459.76	68.73
+ Loss of Use (5.0 x S\$80.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		7,897.45		

INSPECTION

Date of Assignment: 11/02/2020

Date Inspected: 17/02/2020 Inspected At:

Vision Autowork Pte Ltd (HQ)
8 KAKI BUKIT AVE 4,, #08-09
PREMIER @ KAKI BUKIT
Singapore 415875

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,404.70 FL	*1,404.70 FL
2	1		*FRONT BUMPER FOG LAMP COVER C/W CHROME LH	Not Necessary	220.40 FL	*- FL
3	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	279.40 FL	*- FL
4	1		*FRONT BUMPER SIDE RETAINER	N/S Necessary	205.00 FL	*102.50 FL
5	1		*FRONT BUMPER SPONGE	Cracked	179.70 FL	*179.70 FL
6	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	438.60 FL	*- FL
7	1		*FRONT BUMPER UNDER COVER GARNISH	Not Necessary	396.10 FL	*- FL
8	1		*FRONT UPPER GRILLE	Not Necessary	787.90 FL	*- FL
9	1		*HEADLAMP LH (HID)	Cracked	3,382.40 FL	*3,001.00 FL
10	1		*FRONT SUPPORT PANEL	Repair	1,650.50 FL	*- FL
11	2		*AIR CON CONDENSER SIDE GARNISH	Not Necessary	120.20 FL	*- FL
12	1		*FRONT FENDER LH	Dented	978.60 FL	*978.60 FL
13	1		*FRONT FENDER EMBLEM HYBRIC LH	Necessary	98.10 FL	*98.10 FL
14	2		*FRONT FENDER INNER COWLING	Torn (1 PCS ONLY)	582.40 FL	*291.20 FL
15	1		*FRONT FENDER SUPPORT PANEL LH	Not Necessary	67.30 FL	*- FL
16	1		*FRONT WHEEL RIM LH	Cut	1,098.90 FS	*550.00 FS
17	1		*FRONT ABS SENSOR LH	Not Necessary	498.30 FL	*- FL
18	1		*FRONT DRIVESHAFT	Not Necessary	1,521.10 FL	*- FL
19	1		*FRONT CROSSMEMBER	Not Necessary	2,351.40 FL	*- FL
20	1		*FRONT STEERING RACK AND PINION	Bent	1,667.30 FL	*1,667.30 FL
21	1		*FRONT KNUCKLE ARM BEARING LH	Damaged	197.40 FL	*197.40 FL
22	1		*FRONT STABILIZER BAR LINKAGE LH	Not Necessary	173.70 FL	*- FL
23	1		*FRONT SHOCK ABSORBER LH	Not Necessary	721.60 FL	*- FL
24	1		*FRONT KNUCKLE ARM LH	Not Necessary	565.70 FL	*- FL
25	1		*FRONT LOWER ARM LH	Bent	997.60 FL	*579.80 FL
26	1		*FRONT NUMBER PLATE	Not Necessary	50.00 FS	*- FS
27	1		*SET FRONT BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
28	1		*SET FRONT BUMPER UNDER COVER GARNISH CLIP	Not Necessary	50.00 FS	*- FS
29	1		*SET FRONT UPPER GRILLE CLIP	Not Necessary	60.00 FS	*- FS
30	1		*FRONT SUPPORT PANEL SEALANT	Not Necessary	60.00 FS	*- FS
31	1		*SET FRONT SUPPORT PANEL COVER GARNISH CLIP	Not Necessary	60.00 FS	*- FS
32	1		*SET AIR CON CONDENSER SIDE GARNISH CLIP	Not Necessary	50.00 FS	*- FS
33	1		*SET FRONT FENDER COWLING CLIPS	Not Necessary	80.00 FS	*- FS
34	1		*FRONT WHEEL TYRE LH	Not Necessary	650.00 FS	*- FS
35	1		*BRAKE OIL	Not Necessary	30.00 FS	*- FS
36	1		*RADIATOR COOLANT	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 21,814.30 **9,080.30**
- List Item Discount on L Items 25.00/25.00% (\$\$) 4,871.35 2,125.08

Total Parts (\$\$) 16,942.95 **6,955.22**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,REMOVING AND REPLACING PARTS	New	1,600.00	600.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,600.00	800.00
3	TUFF COAT	New	250.00	30.00
4	WIRING CHECK	New	80.00	30.00
5	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	New	120.00	0.00
6	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	80.00	0.00
7	REFOCUS HEADLAMP BEAM	New	60.00	0.00
8	REMOVE AND REFIX STEERING RACK PINION	New	350.00	0.00
9	REMOVE AND REFIX FRONT UNDERCARRIAGE	New	650.00	350.00
10	FOUR WHEEL ALIGNMENT	New	120.00	80.00
11	RESET ABS LIGHT	New	350.00	0.00
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$\$)			5,440.00	1,890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >