

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20002505/ESF3E2

Date: 05/08/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	B29085088MKC
Claimant Vehicle No : GBH7313K	Insured Vehicle No :	GBG2541G
Date of Loss: 04/02/2020	Nature of Claim:	TP
		Claim No: 619288

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH7313K	Engine No:	YD25426138A
Make & Model:	NISSAN NV350, 2.5 PANEL VAN 5MT 5DR (M)	Chassis No:	JN1MC2E26Z0009084
Reg. Date:	13/09/2018 (Man. Year: 2017)	Odometer:	73772 km
Colour:	White		
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Yokohama 4 mm	Rear Left Side:	Yokohama 4 mm
Front Right Side:	Yokohama 4 mm	Rear Right Side:	Yokohama 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,855.71	2,107.40	2,748.31	56.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,350.00	960.00	1,390.00	59.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,205.71	3,067.40	4,138.31	57.43
Approved Total (Overridden) (S\$)		2,450.00		
(S\$)	7,205.71	2,450.00	4,755.71	66.00
+ GST 7.00/7.00% (S\$)	504.40	171.50	332.90	66.00
Nett Amount (S\$)	7,710.11	2,621.50	5,088.61	66.00

INSPECTION

Date of Assignment: 13/02/2020
Date Inspected: 27/07/2020 Inspected At:

Efficient Motor & Engineering Works Pte
Ltd (HQ)
56 Loyang Way #06-07, Loyang Enterprise
Building
Singapore 508775

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 05 Aug 2020)	
Parts:	N/A	NISSAN NV350 2.5 PANEL VAN 5MT 5DR (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH7313K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	514.79 FL	*- FL
2	1		*FRONT BUMPER SIDE RETAINER LH	Broken	146.00 FL	*146.00 FL
3	1		*HEADLAMP ASSY LH	Not Necessary	468.00 FL	*- FL
4	1		*FRONT CORNER PANEL LH	Not Necessary	477.00 FL	*- FL
5	1		*FRONT DOOR LH	Repair	1,015.00 FL	*- FL
6	2		*FRONT DOOR HINGE LH	Not Necessary	158.00 FL	*- FL
7	1		*FRONT DOOR GLASS LH	Broken	936.00 FL	*760.00 FL
8	1		*FRONT DOOR GLASS COVER LH	Cut	228.00 FL	*228.00 FL
9	1		*FRONT DOOR SIDE MIRROR LH	Broken	912.00 FL	*912.00 FL
10	1		*FRONT DOOR RUN CHANNEL LH	Not Necessary	156.00 FL	*- FL
11	1		*FRONT DOOR OUTER MOULDING LH	Cut	240.00 FL	*240.00 FL
12	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*20.00 FS
13	1		*FRT DOOR CO. REG. STICKER	Necessary	80.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,380.79	2,336.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	525.08	228.60
Total Parts (\$\$)	4,855.71	2,107.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT & ALIGN DOOR, REMOVE & REPLACE DAMAGED PARTS	New	800.00	300.00
2	TO APPLY ANTI RUST COAT AND TUFF KOTE REPAIRED AREAS	New	100.00	30.00
3	TO CHECK AND RECTIFY LIGHTING & WIRING	New	50.00	30.00
4	TO SPRAY PAINTING FOR FRONT LH PORTIONS, & OTHER AFFECTED AREAS	New	800.00	500.00
5	TO TRANSFER FRONT DOOR GLASS & COMPONENTS	New	150.00	0.00
6	TO DO ARTWORK COMPANY STICKER	New	350.00	100.00
7	TO DO TYRE BALANCING & WHEEL ALIGNMENT	New	100.00	0.00
			Gross Labour Cost (S\$)	960.00
			2,350.00	960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >