

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/AIG20002536/QBS3Q2

Date:

27/06/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1900082209

Claimant Vehicle No : SLR2481U**Insured Vehicle No :**

SLZ212B

Date of Loss: 07/02/2020

Nature of Claim:

TP

Claim No:

0266309362SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLR2481U**

Make & Model: TOYOTA SIENTA, 1.5 X (A)

Engine No: 1NZR440858

Reg. Date: 04/08/2017 (Man. Year: 2016)

Chassis No: NHP1707060128

Colour: Silver

Odometer: 235353 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60R15

Rear Tyre Size:

185/60R15

Front Left Side: Firenza 5 mm

Rear Left Side:

Firenza 5 mm

Front Right Side: Firenza 5 mm

Rear Right Side:

Firenza 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,605.50	1,131.75	1,473.75	56.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,100.00	1,110.00	990.00	47.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,705.50	2,241.75	2,463.75	52.36
+ GST 7.00/7.00% (S\$)	329.39	156.92	172.47	52.36

Nett Amount (S\$)	5,034.89	2,398.67	2,636.22	52.36
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 13/02/2020

Date Inspected: 13/02/2020

Estimated Period of Repair: 3.0 days

Inspected At: 60 JALAN LAM HUAT# 04-35/36
Repairer:Lion City Rentals Pte Ltd (HQ)

Adjuster: OI SUN PIN**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*R/R DOOR	Dented	1,404.00 FL	*1,279.00 FL
2	1		*F/R DOOR	Repair	1,840.00 FL	*- FL
3	1		*R/R FENDER OUTER RUBBER MOULDING	Scratched	80.00 FL	*80.00 FL
4	1		*R/R DOOR OUTER RUBBER MOULDING	Scratched	150.00 FL	*150.00 FL
					Sub Total (\$)	3,474.00
					- List Item Discount on L Items 25.00/25.00% (\$)	868.50
					Total Parts (\$)	2,605.50
						1,131.75

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO LABOUR CHARGE FOR REMOVING R/R DOOR AND F/R DOOR OUT TO FACILITATE REPLACEMENT OF DAMAGED PART,REPAIR FENDER	New	1,000.00	450.00
2	TO RESPRAY R/R FENDER,R/R DOOR AND F/R DOOR	New	1,000.00	600.00
3	TRANSFER BOTH DOORS MECHANISM	New	100.00	60.00
Gross Labour Cost (S\$)			2,100.00	1,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >