

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile	
	-

ALLIED WORLD ASSURANCE COMPANY LTD Ref: CS/AWA20002537/Eyd3e2

(SINGAPORE BRANCH)

60 ANSON ROAD #08-01 (8th FLOOR)

MAPLETREE ANSON SINGAPORE 079914

Date: 17-04-2020



			Code: AWA				
1. Policy Particulars :- OWN DAMAGE							
	Insured Veh.		Veh. Inspected	XE 1354L			
	Policy No.	BVFCSB0013471900	Coverage (\$)	0.00			
	Claim No.	NSV200062/KW	Excess (\$)	2,500.00			
	Assign From	WONG KIN	Assign Date	13/02/2020			
2.	2. Vehicle Particulars & Condition						
	Make & Model	MITSUBISHI FUSO FP51	c.c	11967			
	Engine No.	HIDDEN	Year of Reg.	2016			
	Chassis No.	FP51SDA10171	Colour	WHITE			
	Odometer	158935	Steering	IN ORDER			
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM			
	General	FAIR					
3.		Condit	ons of Tyres				
		Size	Make	Balance			
	R/H Front Tyre	11 R22.5	BRIDGESTONE	5 mm			
	L/H Front Tyre	11 R22.5	BRIDGESTONE	5 mm			
	R/H Rear Tyre	11 R22.5	BRIDGESTONE	5 mm			
	L/H Rear Tyre	11 R22.5	BRIDGESTONE	5 mm			
4.	. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S, N/S BODY AND FRONT PORTION.						
	DAMAGES SEE DETAILS.						
5.	General Information						
	Accident Date	09/02/2020	Inspection Date	13/02/2020			
	Survey held at	8 TUAS AVE 18					
	Repairer GOLDBELL ENGINEERING PTE LTD						
5a.		R	emarks				
	A)THE MARKET VALUE IS \$\$90,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.						
5b.	Estimate Days of Repair						
	ESTIMATED NORMAL PERIOD FOR REPAIR: 25 Working Days						