



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 9570X

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER (CONSISTENT)	BUCKLED / DENTED	1,202.00	1,202.00
1	FRONT BUMPER RETAINER LH (CONSISTENT)	NECESSARY	102.00	102.00
1	FRONT HEADLAMP LH (CONSISTENT)	CUT	816.00	816.00
1	FRONT FENDER LH (CONSISTENT)	BENT	837.60	837.60
1	FRONT FENDER LINER LH (CONSISTENT)	CRACKED	47.00	47.00
1	FRONT SHOCK ABSORBER ASSY LH(CONSISTENT)	SERVICEABLE	216.17	-
1	FRONT LOWER ARM LH (CONSISTENT)	SERVICEABLE	283.00	-
1	FRONT KNUCKLE ARM LH (CONSISTENT)	BENT	230.00	230.00
	LESS 10% DISCOUNT		-373.38	-323.46
			3,360.39	2,911.14
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT BUMPER FASTENER CLIP (SN) (CONSISTENT)	NECESSARY	30.00	30.00
1	SET FRONT FENDER LINER CLIP (SN) (CONSISTENT)	NECESSARY	30.00	30.00
1	FRONT TYRE LH (LOCAL PURCHASE) (\$180) (50%) (SN) (CONSISTENT)	PUNCTURE	360.00	90.00
1	FRONT WHEEL RIM LH (SN) (CONSISTENT)	BENT	254.00	50.00
1	HUB CUP RIM (SN) (CONSISTENT)	CRACKED	35.00	35.00
			709.00	235.00
<u>LABOUR</u>				
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.		2,800.00	400.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		220.00	30.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		2,700.00	400.00
	TOWING FEE.		120.00	50.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE AND REFIT FRONT END SUSPENSION, UNDERCARRIAGE PARTS, FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	140.00
	TO CHECK ABS BRAKE EFFICIENCY, FINAL CHECKING AND TESTING.		380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		220.00	60.00
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.		170.00	20.00
			7,540.00	1,120.00
GRAND TOTAL			11,609.39	4,266.14
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,400.00

Report Ref No. CC3/AXA14009032/Kha3s2

KONG SENG CHEONG

Licensed Appraiser

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.