



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC3/AXA14009032/Kha3s2-1

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 20-04-2020



ATTN: YVONNE ANG

Code : AXA2

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|-----------|----------------|------------|
| Insured Veh. | SKC 1964R | Veh. Inspected | SHD 9570X |
| Policy No. | P1106684 | Coverage (\$) | 0.00 |
| Claim No. | | Excess (\$) | 0.00 |
| Assign From | | Assign Date | 12/05/2014 |

2. Vehicle Particulars & Condition

| | | | |
|--------------|---------------------|--------------|-------------|
| Make & Model | CHEVROLET EPICA (A) | c.c | 1991 |
| Engine No. | HIDDEN | Year of Reg. | 2012 |
| Chassis No. | KL1LA69RJBB107701 | Colour | WHITE / RED |
| Odometer | 282328 | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | NIL |
| General | GOOD | | |

3. Conditions of Tyres

| | | | |
|----------------|-----------|--------|---------|
| | Size | Make | Balance |
| R/H Front Tyre | 195/65R15 | FALKEN | 6 mm |
| L/H Front Tyre | 195/65R15 | FALKEN | 6 mm |
| R/H Rear Tyre | 195/65R15 | FALKEN | 7 mm |
| L/H Rear Tyre | 195/65R15 | FALKEN | 7 mm |

4. Description of Damages

| |
|---|
| THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS. |
|---|

5. General Information

| | | | |
|----------------|--|-----------------|------------|
| Accident Date | 11/05/2014 | Inspection Date | 12/05/2014 |
| Survey held at | TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111 | | |

5a. Remarks

| |
|--|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|--|

5b. Estimate Days of Repair

| | |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 3 Working Days |
|-------------------------------------|----------------|