

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/FWD20002545/UPS3Q2  
**Date:** 16/04/2020REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2019-00003606  
**Claimant**  
**Vehicle No :** SJK6175M **Insured Vehicle No :** SMH2515Y  
Date of Loss: 08/02/2020 Nature of Claim: TP Claim No: 1202000007884

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJK6175M**  
Make & Model: TOYOTA VIOS, 1.5 E (A) Engine No: 1NZX800721  
Reg. Date: 29/10/2008 (Man. Year: 2008) Chassis No: MR053HY9305082255  
Colour: Beige Odometer: 325013 km  
Engine Capacity: 1497 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15  
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm  
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	9,283.25	5,571.91	3,711.34	39.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,630.00	3,530.00	1,100.00	23.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>13,913.25</b>	<b>9,101.91</b>	<b>4,811.34</b>	<b>34.58</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>7,200.00</b>		
<b>Nett Amount (S\$)</b>	<b>13,913.25</b>	<b>7,200.00</b>	<b>6,713.25</b>	<b>48.25</b>
<b>+ Loss of Use (12.0 x S\$60.00/day) (S\$)</b>		720.00		
<b>+ Doc/Search Fee (S\$)</b>		36.45		
<b>+ Other Costs (S\$)</b>		50.00		
<b>Nett Liability (S\$)</b>		<b>8,006.45</b>		
<b>Global Sum Settlement (S\$)</b>		<b>7,900.00</b>		

INSPECTION

Date of Assignment: 13/02/2020  
Date Inspected: 13/02/2020 Inspected At: T K Lee Automotive Pte Ltd (HQ)  
NO. 1 KAKI BUKIT AVE 6 #02-47  
AUTOBAY  
Singapore 417883

Estimated Period of Repair: 12.0 days

---

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 14 Apr 2020)
<b>Parts:</b> 143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SJK6175M)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	79.30 FL	*79.30 FL
2	1		*REAR BOOT	Buckled	665.90 FL	*665.90 FL
3	2		*REAR BOOT HINGE RH /LH	Repair	137.00 FL	*- FL
4	1		*REAR BOOT RUBBER	Torn	162.84 FL	*162.84 FL
5	1		*REAR BOOT LOCK	Twisted	289.50 FL	*145.00 FL
6	1		*REAR BOOT LOCK CATCH	Not Necessary	48.85 FL	*- FL
7	2		*REAR BOOT STOPPER	Necessary	17.80 FL	*17.80 FL
8	1		*REAR BOOT MOULDING	Not Necessary	286.95 FL	*- FL
9	1		*REAR BOOT EMBLEM LOGO	Necessary	42.60 FL	*42.60 FL
10	1		*REAR BOOT EMBLEM VIOS	Necessary	48.85 FL	*48.85 FL
11	1		*REAR BOOT EMBLEM E	Necessary	30.94 FL	*30.94 FL
12	2		*REAR TAILLAMP LH/RH	Cracked	963.30 FL	*963.30 FL
13	2		*REAR TAILLAMP SIDE HOLDER CLIP	Not Necessary	19.60 FL	*- FL
14	1		*REAR TAILLAMP PANEL HOUSING RH/LH	N/S Repair / O/S Dented	231.20 FL	*115.60 FL
15	1		*REAR BUMPER	Distorted	459.75 FL	*459.75 FL
16	2		*REAR BUMPER REFLECTOR LH/RH	Cracked	212.50 FL	*212.50 FL
17	2		*REAR BUMPER BRACKET RH/LH	Bent	191.00 FL	*191.00 FL
18	2		*REAR BUMPER SIDE HOLDER RH/LH	Bent	165.00 FL	*165.00 FL
19	2		*REAR BUMPER SIDE RETAINER RH/LH	Not Necessary	179.30 FL	*- FL
20	1		*CENTRE EXHAUST PIPE	Repair	899.50 FL	*- FL
21	1		*REAR EXHAUST BOX	Repair	569.05 FL	*- FL
22	1		*REAR EXHAUST BOX HEAT SHIELD	Not Necessary	162.80 FL	*- FL
23	1		*REAR EXHAUST BOX CHROME PIPE	Dented	199.80 FL	*199.80 FL
24	5		*REAR EXHAUST MOUNTING	Torn (2 PCS ONLY)	213.00 FL	*85.20 FL
25	1		*REAR END PANEL	Badly Dented	777.25 FL	*645.00 FL
26	1		*REAR END PANEL GARNISH	Deformed	89.65 FL	*89.65 FL
27	1		*REAR SPARE TYRE PANEL	Crumpled / Buckled	781.65 FL	*781.65 FL
28	1		*REAR SPARE TYRE PANEL SIDE EXTENSION RH/LH	O/S Buckled	429.30 FL	*214.65 FL
29	1		*REAR SPARE TYRE PANEL FOAM CENTRE	Cracked	110.35 FL	*110.35 FL
30	2		*REAR SPARE TYRE PANEL FOAM RH/LH	Torn	252.40 FL	*252.40 FL
31	1		*REAR SOARE TYRE PANEL CARDBOARD	Torn	202.60 FL	*202.60 FL
32	1		*REAR SPARE TYRE SCREW CARRIER	Twisted	39.20 FL	*39.20 FL
33	1		*REAR CHASSIS MEMBER RH	Repair	458.60 FL	*- FL
34	1		*REAR FENDER RH/LH	N/S Repair / O/S Buckled	1,657.00 FL	*828.50 FL
35	1		*REAR FENDER INNER TRIM RH/LH	O/S Deformed	573.00 FL	*286.50 FL
36	2		*REAR FENDER LOWER SHIELD RH/LH	Not Necessary	117.00 FL	*- FL
37	1		*SET REAR WINDSCREEN SPONGE TAPE	Necessary	20.00 FS	*20.00 FS
38	1		*SET REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
39	1		*SET REAR INNER TRIM CLIP	Not Necessary	45.00 FS	*- FS
40	1		*SET REAR BUMPER REVERSE SENSOR	Cracked	280.00 FS	*200.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	1		<b>*SET REAR BUMPER CLIP</b>	Necessary	35.00 FS	*35.00 FS
					<b>Sub Total (\$)</b>	<b>12,224.33    7,330.88</b>
					<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	<b>2,941.08    1,758.97</b>
					<b>Total Parts (\$)</b>	<b>9,283.25    5,571.91</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO KNOCK OUT DENT ,CUT /WELD REAR PANEL ,REAR SPARE TYRE PANEL ,REAR CHASSIS MEMBER RH ,REAR FENDER RH/LH AND REPLACE ACCIDENT PARTS	New	2,500.00	2,000.00
2	TO SPRAY PAINTING ON ACCIDENT PORTION	New	1,300.00	1,100.00
3	TO CHECK WIRING	New	30.00	30.00
4	TO REMOVE,REFIX REAR WINDSCREEN	New	120.00	120.00
5	TO REMOVE,REFIX CUSHION AND INNER TRIM	New	120.00	80.00
6	TO REMOVE,REPLACE REVERSE SENSOR	New	80.00	50.00
7	TO REMOVE,REPLACE CENTRE EXHAUST PIPE AND REAR EXHAUST BOX	New	180.00	60.00
8	TO TUFF KOTE	New	150.00	90.00
9	TO REMOVE,REFIX FUEL TANK	New	150.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>4,630.00</b>	<b>3,530.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >