

51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: MCT18110676 Date: 18th February 2020

Our Ref: CS1/III20002548/Esf3s2

M/s India International Insurance Pte Ltd

64 Cecil Street #05-02 IOB Building Singapore 049711

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: YL 5443M INSURED VEHICLE: SHA 7081U ACCIDENT DATE: 21/11/2018

We thank you for your instruction on 13/02/2020.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of YL 5443M from M/s Carlink Consultancy.
- b) Final Repair Bill of YL 5443M from M/s TwinCar Automotive Pte Ltd.
- c) Singapore Accident Statement of Vehicle YL 5443M.
- d) Colour damaged vehicle photographs of YL 5443M.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : YL 5443M

Make & Model : Isuzu NHR690U3ES

Year of Registration : 2003

Chassis Number : JAANHR69E37100200

Engine Capacity : 3059 cc

- We recommend that the repairs of the entire damage require about 6 (Six) working days to complete.
- We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.