

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/III15020588/KGA3Q2-1  
**Date:** 26/06/2020REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	M474641
<b>Claimant</b>		
<b>Vehicle No :</b> SHC5408P	<b>Insured Vehicle No :</b>	SDQ7900U
Date of Loss: 01/12/2015	Nature of Claim: TP	Claim No: MC2015/3633/KL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHC5408P</b>		
Make & Model:	RENAULT LATITUDE, 2.0 D dCi (A)	Engine No:	M9R8839C002045
Reg. Date:	04/11/2014 (Man. Year: 2014)	Chassis No:	VF1ABL15AUC279611
Colour:	Metallic White/Red	Odometer:	100460 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Rovelo 7 mm	Rear Left Side:	Rovelo 9 mm
Front Right Side:	Rovelo 7 mm	Rear Right Side:	Rovelo 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	14,801.55	1,464.66	13,336.89	90.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,410.00	480.00	2,930.00	85.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>18,211.55</b>	<b>1,944.66</b>	<b>16,266.89</b>	<b>89.32</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,274.81</b>	<b>136.13</b>	<b>1,138.68</b>	<b>89.32</b>
<b>Nett Amount (S\$)</b>	<b>19,486.36</b>	<b>2,080.79</b>	<b>17,405.57</b>	<b>89.32</b>
<b>+ Loss of Use (2.0 x S\$40.00/day) (S\$)</b>		80.00		
<b>+ Car Rental (2.0 x S\$132.68/day) (S\$)</b>		265.36		
		<b>(S\$) 2,426.15</b>		
<b>Liabile Amount (50.00%) (S\$)</b>		<b>1,213.08</b>		
<b>+ Doc/Search Fee (S\$)</b>		6.00		
<b>Nett Liability (S\$)</b>		<b>1,219.08</b>		
<b>Global Sum Settlement (S\$)</b>		<b>1,210.00</b>		

INSPECTION

Date of Assignment:	01/12/2015	
Date Inspected:	01/12/2015 Inspected At:	Trans-cab Auto Services Pte Ltd (HQ) No. 42 Sungei Kadut St 1 Singapore 729346
Estimated Period of Repair:	2.0 days	

---

**Adjuster:** KENNETH KONG

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 02 Mar 2017)
<b>Parts:</b> 143	RENAULT LATITUDE 2.0 D dCi (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SHC5408P)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Buckled / Dented	852.66 FL	*852.66 FL
2	1		*BUMPER LOWER REAR	Dented / Cut	591.41 FL	*591.41 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	87.29 FL	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR (TAILLAMP LOWER)	Serviceable	104.59 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	34.61 FL	*- FL
6	1		*BUMPER REFLECTOR RH	Serviceable	33.55 FL	*- FL
7	1		*BUMPER BRACKET SIDE LH REAR (TAILLAMP LOWER)	Serviceable	104.59 FL	*- FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	34.61 FL	*- FL
9	1		*BUMPER REFLECTOR LH	Serviceable	33.55 FL	*- FL
10	1		*BUMPER BEAM REAR	Repair	598.09 FL	*- FL
11	1		*BUMPER BEAM BRACKET LH REAR	Repair	173.81 FL	*- FL
12	1		*BUMPER BEAM BRACKET RH REAR	Repair	173.81 FL	*- FL
13	1		*BOOT REAR	Repair	2,209.75 FL	*- FL
14	1		*BOOT FINISHER (MOULDING)	Serviceable	429.90 FL	*- FL
15	1		*BOOT WEATHERSTRIP	Serviceable	248.50 FL	*- FL
16	1		*BOOT REFLECTOR LAMP RH	Serviceable	379.50 FL	*- FL
17	1		*BOOT REFLECTOR LAMP LH	Serviceable	379.50 FL	*- FL
18	1		*BOOT BADGE RENAULT	Not Necessary	173.35 FL	*- FL
19	1		*BOOT BADGE	Not Necessary	173.35 FL	*- FL
20	1		*BOOT SWITCH	Serviceable	107.78 FL	*- FL
21	1		*BOOT LOCK	Repair	155.90 FL	*- FL
22	1		*BOOT LOCK CATCH	Repair	72.00 FL	*- FL
23	1		*TAILLAMP RH	Serviceable	425.04 FL	*- FL
24	1		*TAILLAMP LH	Serviceable	425.04 FL	*- FL
25	1		*OUTER PANEL REAR (END PANEL)	Repair	1,132.13 FL	*- FL
26	1		*OUTER PANEL REAR (END PANEL) TRIM	Serviceable	311.20 FL	*- FL
27	1		*EXHAUST REAR	Repair	5,760.00 FL	*- FL
28	1		*EXHAUST CAP REAR	Repair	177.30 FL	*- FL
29	1		*SET PARKING AID	Serviceable	600.00 FS	*- FS
30	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
31	1		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
32	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
33	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
34	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
35	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
36	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
37	1		*EXHAUST MOUNTING REAR	Serviceable	17.82 FS	*- FS
38	1		*SET OUTER PANEL REAR (END PANEL) TRIM CLIP	Not Necessary	30.00 FS	*- FS
39	1		*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*- FS
40	1		*BOOT STICKER TRANS-CAB	Not Necessary	30.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
41	1		<b>*BOOT STICKER 6555-3333</b>	Not Necessary	30.00 FS	*-FS	
			F=Franchise part. S=SpcNett. L=ListItemDisc.				
					<b>Sub Total (\$)</b>	<b>16,339.83</b>	<b>1,609.07</b>
					<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	1,538.28	144.41
					<b>Total Parts (\$)</b>	<b>14,801.55</b>	<b>1,464.66</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,500.00	220.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	1,400.00	200.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
5	TO DROP REAR EXHAUST BOX ,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>3,410.00</b>	<b>480.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >