

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20002550/URA3Q2
Date: 23/09/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900004947
Claimant Vehicle No :	SKQ7188B	Insured Vehicle No :	SKB8523P
Date of Loss:	09/02/2020	Nature of Claim:	TP
		Claim No:	6807875557SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKQ7188B		
Make & Model:	OPEL INSIGNIA, 2.0 AT (A)	Engine No:	A20NHT0N015916
Reg. Date:	23/12/2010 (Man. Year: 2010)	Chassis No:	W0LGM5EE2A1130974
Colour:	Black	Odometer:	190015 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/45 R18	Rear Tyre Size:	245/45 R18
Front Left Side:	Linglong 6 mm	Rear Left Side:	Linglong 6 mm
Front Right Side:	Linglong 6 mm	Rear Right Side:	Linglong 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,008.20	600.00	13,408.20	95.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,700.00	360.00	3,340.00	90.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	17,708.20	960.00	16,748.20	94.58
+ Car Rental (5.0 x S\$120.00/day) (S\$)		600.00		

(S\$)	1,560.00
Liable Amount (50.00%) (S\$)	780.00

INSPECTION

Date of Assignment: 13/02/2020

Date Inspected: 13/02/2020

Estimated Period of Repair: 3.0 days

Inspected At:

Zoom Autowerks Pte Ltd (HQ)
15 Kaki Bukit Road 4, #01-53
Singapore 417808

Adjuster: MARCUS CHUA**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Not Necessary	2,860.00 FL	*- FL
2	1		*FRONT BUMPER FOG LAMP BRACKET RH	Not Necessary	180.00 FL	*- FL
3	1		*FRONT BUMPER FOG LAMP RH	Not Necessary	380.00 FL	*- FL
4	1		*FRONT BUMPER GARNISH RH	Not Necessary	270.00 FL	*- FL
5	1		*FRONT BUMPER INNER SPONGE	Not Necessary	280.00 FL	*- FL
6	1		*FRONT BUMPER LOWER ARM	Not Necessary	240.00 FL	*- FL
7	1		*FRONT BUMPER LOWER CENTRE GRILLE	Not Necessary	320.00 FL	*- FL
8	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	850.00 FL	*- FL
9	1		*FRONT BUMPER RETAINER RH	Not Necessary	150.00 FL	*- FL
10	1		*FRONT BUMPER TOW HOOK GARNISH	Not Necessary	68.00 FL	*- FL
11	1		*FRONT BUMPER CLIPS	Not Necessary	60.00 FL	*- FL
12	1		*FRONT FENDER RH	Repair	1,480.00 FL	*- FL
13	1		*FRONT FENDER INNER SHIELD RH	Not Necessary	320.00 FL	*- FL
14	1		*FRONT FENDER INNER SHIELD CLIPS	Not Necessary	60.00 FL	*- FL
15	1		*FRONT FENDER LAMP RH	Not Necessary	140.00 FL	*- FL
16	1		*FRONT FENDER BRACKET RH	Not Necessary	110.00 FL	*- FL
17	1		*FRONT HEADLAMP RH	Not Necessary	2,680.00 FL	*- FL
18	1		*FRONT SUPPORT PANEL	Not Necessary	1,450.00 FL	*- FL
19	1		*FRONT DOOR RH (NPA)	Not Necessary	0.00 FL	*- FL
20	1		*FRONT RIM RH	Cut / Bent	1,680.00 FS	*600.00 FS
21	1		*FRONT TYRE RH	Not Necessary	650.00 FS	*- FS
22	1		*FRONT SENSOR RH	Not Necessary	420.00 FS	*- FS
23	1		*FRONT ANGLE SENSOR RH	Not Necessary	370.00 FS	*- FS
24	1		*RADIATOR COOLANT	Not Necessary	180.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	15,198.00	600.00
- List Item Discount on L Items 10.00/10.00% (\$)	1,189.80	0.00
Total Parts (\$)	14,008.20	600.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,REPAIR & RENEW AFFECTED ACCIDENT AREAS	New	1,200.00	100.00
2	TO PUTTY ,SPRAY PAINT ON AFFECTED ACCIDENT AREAS	New	1,100.00	200.00
3	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	0.00
4	TO REMOVE,INSTALL & CONDUCT RADIATOR PRESSURE LEAKAGE TEST	New	200.00	0.00
5	TO REMOVE,INSTALL AC CONDENSER & TOP UP GAS	New	200.00	0.00
6	TO CONDUCT WHEEL ALIGNMENT	New	150.00	60.00
7	TO CONDUCT DIAGNOSTIC & RESET ENGINE MANGEMENT	New	450.00	0.00
8	TO RE-POSITION FRONT SENSOR & ANGLE SENSOR	New	200.00	0.00
9	TO RUST PROOF AFFECTED AREAS	New	150.00	0.00
Gross Labour Cost (\$\$)			3,700.00	360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >