

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20002552/HSD3E2

Date: 26/08/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00000111900	
Claimant Vehicle No :	SCX7973J	Insured Vehicle No :	GBJ9152J	
Date of Loss:	08/02/2020	Nature of Claim:	TP	Claim No: SNM20D200800/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCX7973J	Engine No:	1ZZ1554370
Make & Model:	TOYOTA WISH, 1.8 (A)	Chassis No:	ZNE100084363
Reg. Date:	18/10/2003 (Man. Year: 2003)	Odometer:	275758 km
Colour:	Silver		
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Firestone 6 mm	Rear Left Side:	Firestone 6 mm
Front Right Side:	Firestone 6 mm	Rear Right Side:	Firestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,661.31	1,132.33	1,528.98	57.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,650.00	830.00	820.00	49.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,311.31	1,962.33	2,348.98	54.48
Approved Total (Overridden) (S\$)		1,550.00		
(S\$)	4,311.31	1,550.00	2,761.31	64.05
+ GST 7.00/7.00% (S\$)	301.79	108.50	193.29	64.05
Nett Amount (S\$)	4,613.10	1,658.50	2,954.60	64.05

INSPECTION

Date of Assignment:	13/02/2020	
Date Inspected:	17/02/2020 Inspected At:	ComfortDelGro Engineering Pte Ltd (Ubi)
		320 UBI ROAD 3
		Singapore 408649
Estimated Period of Repair:	3.0 days	

Adjuster: LEE HOCK ANN**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Aug 2020)

Parts: M1-MPV TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SCX7973J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH HEADLAMP	Cracked	930.55 FL	*798.00 FL
2	1		*RH HEADLAMP LOWER BRACKET (NPA)	Serviceable	0.00 FL	*- FL
3	1		*FRONT BUMPER	Crumpled	1,878.79 FL	*565.00 FL
4	1		*SET FRONT BUMPER CLIPS	Necessary	60.00 FL	*25.00 FL
5	1		*FRONT BUMPER SIDE RETAINER RH	Cracked	79.78 FL	*79.78 FL
6	1		*FRONT BUMPER REINFORCEMENT	Repair	395.15 FL	*- FL
7	1		*FRONT BUMPER SPONGE	Serviceable	162.14 FL	*- FL
8	1		*FOG LAMP COVER RH	Missing	42.00 FL	*42.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	3,548.41	1,509.78
- List Item Discount on L Items 25.00/25.00% (S\$)	887.10	377.45

Total Parts (S\$)	2,661.31	1,132.33
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING,WIRE SOCKET ETC,REMOVE AND REINSTALL DAMAGE PARTS,TEST AND RETIFY FOR PROPER FUNCTIONING	New	100.00	30.00
2	TO KNOCK & REPAIR RH FENDER INNER PANEL,FRONT BONNET,RADIATOR SUPPORT PANEL AND AFFECTED AREA	New	550.00	400.00
3	TO PUTTY & SPRAY PAINT RH FENDER,INNER PANEL,FRONT BONNET,RADIATOR SUPPORT PANEL,FRONT BUMPER AND AFFECTED AREA	New	1,000.00	400.00
Gross Labour Cost (S\$)			1,650.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >