

Spark Car Care

ComfortDelGro Engineering Pte Ltd
320 UBI ROAD 3 SINGAPORE 408649
TEL :68438723/68438736 Fax:67436072

Spare Parts

Vehicle No : SCX7973J Case Owner : JOHARI

Make & Model : TOYOTA WISH Year Manufacture : 2003

Chassis No : ZNE100084363 Engine No : 1ZZ1554370

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N
1	RH HEADLAMP ✓ <i>CRU</i>	1		\$ 930.55		
2	RH HEADLAMP LOWER BRACKET X (<i>not use</i>)	1				
3	FRONT BUMPER ✓ <i>CRU</i>	1		\$ 1,878.79		
4	FRONT BUMPER CLIPS ✓ <i>new</i>	<i>25 / set</i>		\$ 60.00	<i>25</i>	
5	FRONT BUMPER SIDE RETAINER RH ?	1		\$ 79.78	<i>CRU</i>	<i>11/8/20</i>
6	FRONT BUMPER REINFORCEMENT X (<i>R</i>)	1		\$ ✓ 395.15		<i>24/11</i>
7	FRONT BUMPER SPONGE X (<i>svl</i>)	1		\$ ✓ 162.14		
8	FOG LAMP COVER RH ✓ <i>mts</i>	1		\$ 42.00		
9						
10						
11						
12						
13						
14						
15						
16						
17						
18						
19						
20						
21						
22						
23						
24						
25						
26						
27						
28						
29						
30						

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge

Spark Car Care

ComfortDelGro Engineering Pte Ltd

320 UBI ROAD 3 SINGAPORE 408649

Tel: 68438723/68438736 FAX : 67436072

Labour

Vehicle No. : SCX7973J Case Owner : JOHARI
 Make & Model : TOYOTA WISH Year of Manufacture : 2003

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING , WIRE SOCKET ETC , REMOVE AND REINSTALL DAMAGE PARTS , TEST AND RETIFY FOR PROPER FUNCTIONING .	\$100.00	30
2	TO KNOCK & REPAIR RH FENDER INNER PANEL , FRONT BONNET , RADIATOR SUPPORT PANEL AND AFFECTED AREA.	\$550.00	300
3	TO PUTTY & SPRAY PAINT RH FENDER , INNER PANEL , FRONT BONNET , RADIATOR SUPPORT PANEL , FRONT BUMPER AND AFFECTED AREA .	\$1,000.00	400
<p><i>Handwritten notes:</i></p> <p>2/5 repair wheel propellers resinger after paint 3 July (11:45) H. ANN 8531883 H/2/00 4.15pm Hark ANN @ HarkAuto.com HarkAuto.com</p>			

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.