

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20002554/KBA3Q2

Date: 30/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800011783
Claimant
Vehicle No : SLH2772H **Insured Vehicle No :** SLW2303A
Date of Loss: 22/01/2020 **Nature of Claim:** TP **Claim No:** 1078901537SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLH2772H**
 Make & Model: MAZDA 3, 1.5 SEDAN L SP.6EAT (A) Engine No: P520376950
 Reg. Date: 28/10/2016 (Man. Year: 2016) Chassis No: JM6BM42A8G0347199
 Colour: Metallic Grey Odometer: 31259 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
 Front Left Side: Toyo 6 mm Rear Left Side: Toyo 8 mm
 Front Right Side: Toyo 6 mm Rear Right Side: Toyo 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,996.99	3,022.96	974.03	24.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	895.00	720.00	175.00	19.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,891.99	3,742.96	1,149.03	23.49
+ GST 7.00/7.00% (S\$)	342.44	262.01	80.43	23.49
Nett Amount (S\$)	5,234.43	4,004.97	1,229.46	23.49
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,406.97		
Global Sum Settlement (S\$)		4,400.00		

INSPECTION

Date of Assignment: 13/02/2020
 Date Inspected: 13/02/2020 Inspected At: S & H Motor Pte Ltd (Sin Ming)
 160 Sin Ming Drive #07-02, Sin Ming
 AutoCity
 Singapore 575722
 Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH FENDER	Repair	433.90 FL	*- FL
2	1		*FRONT RH FENDER COWLING	Serviceable	97.00 FL	*- FL
3	1		*SET FRONT RH FENDER COWLING CLIPS	Not Necessary	22.00 FL	*- FL
4	1		*FRONT BUMPER	Buckled	1,080.50 FL	*1,031.70 FL
5	1		*FRONT BUMPER RH RETAINER	Serviceable	28.70 FL	*- FL
6	1		*FRONT BUMPER RH FOG LAMP COVER	Scratched	197.00 FL	*165.00 FL
7	1		*FRONT BUMPER RH FOG LAMP COVER CHROME RIM	Scratched	225.00 FL	*225.00 FL
8	1		*FRONT RH HEADLAMP	Cracked	2,357.00 FL	*2,357.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	4,441.10	3,778.70
- List Item Discount on L Items 10.00/20.00% (\$\$)	444.11	755.74

Total Parts (\$\$)	3,996.99	3,022.96
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO SPRAY PAINT AFFECTED FRONT AND INNER DAMAGED PORTION INCLUSIVE OF PREPARATORY WORKS AND MATERIAL	New	450.00	400.00
2	TO REMOVE FRONT DAMAGED PARTS ,TO JACK OUT FRONT FENDER ,PANEL ,FRONT BODY ,AND CUT OUT DAMAGED PARTS,REINSTALL FRONT FENDER AND INNER PANEL ,HEAD LAMP INNER PANEL ,FRONT SUPPORT PANEL,FRONT CHASSIS MEMBER AND ADJUST BODY PANEL ALIGNMENT	New	420.00	300.00
3	TO DISCONNECT WIRE HARNESS TO FACILITATE REPAIRS AND CHECK FOR DAMAGES AND RECONNECT WIRING SYSTEM AND CHECK FOR FULL FUNCTIONALITY ,TO FOCUS HEADLAMP	New	25.00	20.00
Gross Labour Cost (\$\$)			895.00	720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >