



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2104076

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 10/06/2021
Reference CC4/FCI20002556/Kra3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SBT 3189R
Insured Veh. SHC 164A
Claim No. D20000954MFSH
Policy No. D-20094921MFSH
Accident Date 12/02/2020
Inspection Date 13/02/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI20002556/Kra3q2	
			Date: 10/06/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 164A	Veh. Inspected	SBT 3189R	
Policy No.	D-20094921MFSH	Coverage (\$)	0.00	
Claim No.	D20000954MFSH	Excess (\$)	0.00	
Assign From	MERINA CHIA	Assign Date	13/02/2020	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	RU11019281	Colour	METALLIC BLACK	
Odometer	123549 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	8 mm	
L/H Front Tyre	215/60 R16	DUNLOP	8 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	7 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/02/2020	Inspection Date	13/02/2020	
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBT 3189R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	BENT	508.20	508.20
6	REAR BUMPER CLIPS @\$3.90	NECESSARY	23.40	23.40
1	TAILGATE EMBLEM (VEZEL)	NECESSARY	75.00	75.00
1	TAILGATE INNER LOCK	DENTED	189.10	189.10
1	TAILGATE INNER RUBBER	CUT	96.80	96.80
1	REAR END PANEL	BENT	411.90	411.90
1	SMART KEY SENSOR	CRACKED	85.00	85.00
1	REAR WINDSCREEN GLASS MOULDING	NECESSARY	131.80	131.80
1	REAR TAILGATE	BENT	1,100.90	1,100.90
	LESS 20% DISCOUNT		-524.42	-524.42
			2,097.68	2,097.68
	<u>SPECIAL NETT ITEMS</u>			
1	REAR WINDSCREEN GLASS GUM (SN)	NECESSARY	40.00	40.00
1	SET REVERSE SENSOR (SN)	DENTED	200.00	200.00
1	REAR BUMPER BODY STICKER (SN)	NECESSARY	80.00	80.00
1	TAILGATE FRAME RUBBER (SN)	NECESSARY	40.00	40.00
			360.00	360.00
	<u>LABOUR</u>			
	REMOVE AND REFIX REAR WINDSCREEN GLASS .		100.00	100.00
	REMOVE & REFIX REAR BUMPER ASSY ,TAILGATE ASSY ,REAR TOP SPOILER ,REAR WIPER ,LOCK ASSY ,CUT ,WELD & RENEW REAR END PANEL ,KNOCK & REPAIR REAR SPARE TYRE COMPARTMENT & REALIGN THE SAME.		800.00	650.00
	PUTTY & RESPRAY ON REAR END PANEL,REAR SPARE TYRE COMPARTMENT ,TAILGATE ,REAR BUMPER SIDE PADS.		800.00	700.00
	REMOVE & REFIX REVERSE CAMERA & RESET SYSTEM .		40.00	40.00
	REMOVE & REFIX SMART KEY SENSOR & RESET LOCKING .		80.00	60.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	RUSTPROOFING.		60.00	60.00
			1,880.00	1,610.00
GRAND TOTAL			4,337.68	4,067.68
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,250.00

Report Ref No. CC4/FCI20002556/Kra3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SBT 3189R

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SBT 3189R

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SBT 3189R

RE-INSPECTION

