

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20002565/QGA3Q2

Date: 04/02/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100463880
Claimant
Vehicle No : SLL9056A **Insured Vehicle No :** SDX899A
Date of Loss: 11/02/2020 Nature of Claim: TP Claim No: 6089778238SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLL9056A**
Make & Model: TOYOTA SIENTA HYBRID, 1.5 G (A) Engine No: 1NZR462181
Reg. Date: 15/03/2017 (Man. Year: 2016) Chassis No: NHP1707068403
Colour: Blue Odometer: 173346 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15
Front Left Side: Firenza 5 mm Rear Left Side: Firenza 5 mm
Front Right Side: Firenza 5 mm Rear Right Side: Firenza 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,199.12	1,400.25	1,798.87	56.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,100.00	1,160.00	940.00	44.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,299.12	2,560.25	2,738.87	51.69
Approved Total (Overridden) (S\$)		2,050.00		
(S\$)	5,299.12	2,050.00	3,249.12	61.31
+ GST 7.00/7.00% (S\$)	370.94	143.50	227.44	61.31
Nett Amount (S\$)	5,670.06	2,193.50	3,476.56	61.31
+ Loss of Use (5.0 x S\$50.00/day) (S\$)		250.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,445.50		
Global Sum Settlement (S\$)		2,440.00		

INSPECTION

Date of Assignment: 13/02/2020
Date Inspected: 13/02/2020 Inspected At: Lion City Rentals Pte Ltd (HQ)
60 Jalan Lam Huat, #04-35/36 Carros
Centre
Singapore 737569
Estimated Period of Repair: 3.0 days

Adjuster: OI SUN PIN

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*F/R FENDER	Dented	750.00 FL	*550.00 FL	
2	1		*F/R FENDER HYBRID EMBLEM	Necessary	84.00 FL	*84.00 FL	
3	1		*F/R FENDER INNER LINER	Serviceable	187.50 FL	* - FL	
4	1		*F/R DOOR	Dented	1,840.00 FL	*1,233.00 FL	
5	1		*R/R DOOR	Repair	1,404.00 FL	* - FL	
					Sub Total (S\$)	4,265.50	1,867.00
					- List Item Discount on L Items 25.00/25.00% (S\$)	1,066.38	466.75
					Total Parts (S\$)	3,199.12	1,400.25

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO LABOUR CHARGE FOR REMOVING R/R DOOR ,F/R FENDER AND F/R DOOR OUT TO FACILITATE REPLACEMENT OF DAMAGED PART	New	1,000.00	500.00
2	TO RESPRAY R/R FENDER ,R/R DOOR ,F/R FENDERAND F/R DOOR	New	1,000.00	600.00
3	TRANSFER BOTH DOORS MECHANISM /FRONT DOOR	New	100.00	60.00
			Gross Labour Cost (\$\$)	1,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >