



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2100018

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 04/01/2021
Reference CC6/CTI20002571/Aka3s2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SLK 2825Z
Insured Veh. GBH 5946Y
Claim No. SNM20D200849
Policy No. DMCVSN3019261900
Accident Date 11/02/2020
Inspection Date 12/02/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

NSA



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI20002571/Aka3s2	
			Date: 04/01/2021	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBH 5946Y	Veh. Inspected	SLK 2825Z	
Policy No.	DMCVSN3019261900	Coverage (\$)	0.00	
Claim No.	SNM20D200849	Excess (\$)	0.00	
Assign From		Assign Date	12/02/2020	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CIVIC	c.c	1597	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	MRHFC5650GT000862	Colour	WHITE	
Odometer	94587 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/55 R16	YOKOHAMA	6 mm	
L/H Front Tyre	215/55 R16	YOKOHAMA	6 mm	
R/H Rear Tyre	215/55 R16	YOKOHAMA	6 mm	
L/H Rear Tyre	215/55 R16	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/02/2020	Inspection Date	12/02/2020	
Survey held at	MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 #01-61 SINGAPORE 408717			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 2825Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DISTORTED	668.20	668.20
1	SET REAR BUMPER CLIPS	NECESSARY	30.00	30.00
2	REAR BUMPER SIDE HOLDER - LH & RH	NECESSARY	49.00	49.00
1	REAR BUMPER LOWER GARNISH	DEFORMED	275.30	275.30
2	REAR BUMPER SIDE COVER - LH & RH	NOT NECESSARY	156.60	-
1	REAR BUMPER TOWING COVER	MISSING	22.10	22.10
1	REAR END PANEL	DENTED	385.70	385.70
1	REAR END PANEL TOP GARNISH	DEFORMED	98.40	98.40
2	TAIL LAMP - LH & RH	CUT	546.20	546.20
1	BOOTLID	DENTED	572.10	572.10
1	BOOTLID LOCK	DAMAGED	74.30	74.30
1	BOOTLID WEATHERSTRIP	CUT	79.00	79.00
2	BOOTLID REFLECTOR - LH & RH	NOT NECESSARY	237.40	-
1	BOOTLID OUTER GARNISH	CRACKED	102.70	102.70
1	SET BOOTLID OUTER GARNISH CLIPS	NECESSARY	22.00	22.00
2	BOOTLID HINGES - LH & RH	NOT NECESSARY	124.20	-
2	BOOTLID HINGES COVER - LH & RH	NOT NECESSARY	76.40	-
1	HONDA LOGO	NECESSARY	53.90	53.90
1	CIVIC WORDING	NECESSARY	46.20	46.20
1	I-VTEC WORDING	NECESSARY	48.90	48.90
1	REAR BUZZER	DAMAGED	46.00	46.00
1	REAR LOCK ANTENNA	CRACKED	45.00	45.00
1	SPARE TYRE PANEL TOP COVER	NOT NECESSARY	246.20	-
	LESS 20% DISCOUNT		-801.16	-633.00
			3,204.64	2,532.00
<u>SPECIAL NETT ITEMS</u>				
1	REVERSE SENSOR (SN)	DAMAGED	380.00	280.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	60.00	60.00
1	REAR CAMERA (SN)	NOT NECESSARY	480.00	-
			920.00	340.00

Report Ref No. CC6/CTI20002571/Aka3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO KNOCKING OUT REAR PORTION & RENEW ABOVE PARTS.		1,200.00	800.00
	TO PUTTY & SPRAY UP PAINT WORKS.		1,200.00	950.00
	TO CHECK WIRING SYSTEM.		50.00	30.00
	TO REMOVE REVERSE SENSOR.		100.00	60.00
	TO REMOVE AND REAR CAMERA.		100.00	50.00
	TO TRANSFER BOOTLID FITTINGS.		150.00	80.00
	TO REMOVE UPHOLSTERY.		150.00	60.00
			2,950.00	2,030.00
	GRAND TOTAL		7,074.64	4,902.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,900.00

Report Ref No. CC6/CTI20002571/Aka3s2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.