

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20002572/AEA3Q2

Date: 07/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800067061

Claimant
Vehicle No : SLS8204J **Insured Vehicle No :** SJD1968L

Date of Loss: 08/02/2020 Nature of Claim: TP Claim No: 0142209271SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS8204J		
Make & Model:	OPEL MOKKA X, 1.6 CDTI 6AT (LED) (A)	Engine No:	A3163125GU7X0816
Reg. Date:	06/10/2017 (Man. Year: 2017)	Chassis No:	27091031269694
Colour:	Blue	Odometer:	152405 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R18	Rear Tyre Size:	215/55 R18
Front Left Side:	Comforser 6 mm	Rear Left Side:	Comforser 6 mm
Front Right Side:	Comforser 6 mm	Rear Right Side:	Comforser 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,248.20	4,174.40	8,073.80	65.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,970.00	940.00	2,030.00	68.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	15,218.20	5,114.40	10,103.80	66.39
+ Car Rental (4.0 x S\$80.00/day) (S\$)		320.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,441.85		
Global Sum Settlement (S\$)		5,440.00		

INSPECTION

Date of Assignment: 13/02/2020

Date Inspected: 13/02/2020 Inspected At:

Ace Auto Solution (kaki Bukit) (HQ)
23 KAKI BUKIT AVE 4, #04-01
(SOUTH WING)
Singapore 415933

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Not Necessary	1,840.00 FL	*- FL
2	1		*REAR TAILGATE OUTER HANDLE	Not Necessary	270.00 FL	*- FL
3	1		*REAR TAILGATE OPEL LOGO	Not Necessary	216.00 FL	*- FL
4	1		*LETTERING MOKKA X	Not Necessary	146.00 FL	*- FL
5	1		*LETTERING CDTI	Not Necessary	110.00 FL	*- FL
6	1		*REAR WINDSCREEN WITH MOULDING	Not Necessary	1,258.00 FL	*- FL
7	1		*TAILGATE INNER TRIM BOARD	Not Necessary	314.00 FL	*- FL
8	1		*LHR TAILLAMP	Not Necessary	564.00 FL	*- FL
9	1		*RHR TAILLAMP	Not Necessary	564.00 FL	*- FL
10	1		*REAR BUMPER UPPER	Deformed	1,487.00 FL	*1,487.00 FL
11	1		*REAR BUMPER LOWER	Deformed	990.00 FL	*990.00 FL
12	1		*REAR BUMPER TOWING COVER	Deformed	90.00 FL	*90.00 FL
13	1		*REAR BUMPER SILL PLATE	Deformed	344.00 FL	*344.00 FL
14	1		*LHF BUMPER REFLECTOR	Cracked	150.00 FL	*150.00 FL
15	1		*RHF BUMPER REFLECTOR	Cracked	150.00 FL	*150.00 FL
16	1		*LHR FENDER PROTECTOR	Not Necessary	190.00 FL	*- FL
17	1		*RHR FENDER PROTECTOR	Not Necessary	190.00 FL	*- FL
18	1		*LHR BUMPER BRACKET ,GUIDE	Cracked	70.00 FL	*70.00 FL
19	1		*RHR BUMPER BRACKET ,GUIDE	Cracked	70.00 FL	*70.00 FL
20	1		*LHR BUMPER BRACKET	Bent	65.00 FL	*65.00 FL
21	1		*RHR BUMPER BRACKET	Bent	65.00 FL	*65.00 FL
22	1		*REAR BUMPER CENTRE BRACKET	Not Necessary	85.00 FL	*- FL
23	1		*REAR BUMPER ABSORBER -RH	Cracked	82.00 FL	*82.00 FL
24	1		*REAR BUMPER ABSORBER -LH	Cracked	82.00 FL	*82.00 FL
25	1		*REAR BUMPER REINFORCEMENT BAR	Bent	671.00 FL	*671.00 FL
26	1		*REAR BUMPER AIR VENTILATOR	Not Necessary	80.00 FL	*- FL
27	1		*REAR END PANEL	Repair	1,241.00 FL	*- FL
28	1		*REAR END PANEL TRIM	Not Necessary	164.00 FL	*- FL
29	1		*REVERSE SENSOR WIRING HARNESS	Not Necessary	450.00 FL	*- FL
30	1		*REAR NUMBER PLATE	Not Necessary	45.00 FS	*- FS
31	1		*SET REAR BUMPER UPPER CLIP	Necessary	65.00 FS	*20.00 FS
32	1		*SET REAR BUMPER LOWER CLIP	Necessary	65.00 FS	*20.00 FS
33	1		*SET REAR FENDER PROTECTOR CLIP	Not Necessary	78.00 FS	*- FS
34	1		*SET REAR END PANEL TRIM CLIP	Not Necessary	52.00 FS	*- FS
35	1		*SET REVERSE SENSOR WITH REVERSE SENSOR SEAL	Damaged (1 PCS ONLY)	660.00 FS	*250.00 FS
36	1		*REAR END PANEL INSULATION SEAL	Not Necessary	120.00 FS	*- FS
37	1		*SET TAIL GATE INNER TRIM BOARD CLIP	Not Necessary	65.00 FS	*- FS
38	1		*TAILGATE WINDSCREEN SOLAR FILM	Not Necessary	180.00 FS	*- FS
39	1		*TAILGATE WINDSCREEN SEALANT	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 13,448.00 4,606.00
- List Item Discount on L Items 10.00/10.00% (\$\$) 1,199.80 431.60

Total Parts (\$\$) 12,248.20 4,174.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION ,TO PANEL BEATING ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	1,200.00	400.00
2	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA	New	1,200.00	400.00
3	TO CONDUCT ANTI RUST OF UNDER CARRIAGE TUFF COAT	New	100.00	50.00
4	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS ,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	30.00	30.00
5	TO REMOVE AND REFIX REVERSE CAMERA AND CONDUCT TEST	New	80.00	0.00
6	TO REMOVE AND REFIX REVERSE SENSOR AND CONDUCT TEST	New	80.00	60.00
7	TO CONDUCT TRANSFER OF PARTS FROM OLD TAILGATE TO NEW TAILGATE	New	80.00	0.00
8	TO CONDUCT WATER LEAKAGE TEST AFTER REPAIRS OF VEHICLE	New	80.00	0.00
9	TO REMOVE AND REFIX REAR TAIL GATE WINDSCREEN	New	120.00	0.00
Gross Labour Cost (\$\$)			2,970.00	940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >