114

Veh No. SH 8 354 P Yr Regrit 2014, June Type: M.Car / M.Cycle / Bus / Van / Lorry / Total Prime Mover / Truck / Trailer or Make: Hywdici I 40	RM6.712G BY	ASSIGNMENT COE 2022 June
Type: M. Car I M. Car		8487243 2014 June
Truck Trailer or Maile: Truck Trailer or Maile: Huwdin: I to acc 685 To inspect Vehicle No: at Workshop mile and the state of	The state of the s	Veh No. STOST VY Regn.
To Inspect Vehicle Not all Workshop miles Make: Hywydd: 140 cc 1685 Colour 3 Not insured is sid in in in in insured is sid in in in in in insured is sid in in in in in insured is sid in	Estimated Cost:	
AC: Insured (Std INI NA Sp. Reading 85 42 43 TiRadic Insured 1399 No. 201399	OD / TP / WS / TP RES / OD RES / EVA / INV / MV	System Discharges
Sp. Reading 85 42 43 TiRadio: Insured Std Ni NA Eng/No: Design Sp. Reading S	To Inspect Vehicle No:	7.1 as bound out but he
Enghlo: D4FDDU391399 Choice Seed Fair Poor Burnt Steering: Industri Leaked Burnt or Steering: Industri Leaked Burnt or Steering: Industri Leaked Burnt or Mode of Veh: Policy Condition Remark: The veh had commenced its repair at the time of inspection. Policy Condition Remark: The veh had commenced its repair at the time of inspection. Policy Condition Remark: The veh had commenced its repair at the time of inspection. Policy Condition Remark: The veh had commenced its repair at the time of inspection. Policy Condition Remark: The veh had commenced its repair at the time of inspection. Policy Condition Remark: The veh had commenced its repair at the time of inspection. Policy Condition Remark: The veh had commenced its repair at the time of inspection. Policy Condition Remark: The veh had commenced its repair at the time of inspection. Policy Condition Remark: The veh had commenced its repair at the time of inspection. Policy Condition Policy Condition Remark: The veh had commenced its repair at the time of inspection. Policy Condition Remark: The veh had commenced its repair at the time of inspection. Policy Condition Remark: The veh had commenced its repair at the time of inspection. Policy Condition Remark: The veh had commenced its repair at the time of inspection. Policy Condition Remark: The veh had commenced its repair at the time of inspection. Policy Condition Remark: The veh had commenced its repair at the time of inspection. Policy Condition repair at the time of inspection. Poli	ut Workshop m/s	0.01
CNo: Claims No. Claims No. Sum Insured: Excess: Cleint's Record) Make of Veh: (Cleint's Record) Make of Veh: (Policy Condition) Remark: The veh had commenced its repair at the time of inspection. (Policy Condition) Bal. or Market Value: IDAC Accident Rport: Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No CIA / REV / REP. / 2 4 HRS Vehicle: IN / OUT Date: Person Contacted: Vehicle: IN / OUT The UIC / Chassis frame / Body Structure affected due to collision. REOEIVED 2 3 Mars 2020 Date/Time. File Paston No. CREDITION: File Paston No.	of	7,1622,1261366
Gen. Cond. Good: Fair I Poor I Burnt Sum insured: Sum in	Insured	Later to the same
Steering: Incider Jammed J Leaked J Burnt or Brake: Inhauder J Jammed J Leaked J Burnt or Modi Inhauder J Jammed J Leaked J Burnt or Modi Inhauder J Jammed J Leaked J Burnt or Modi Inhauder J Jammed J Leaked J Burnt or Modi Inhauder J Jammed J Leaked J Burnt or Modi Inhauder J Jammed J Leaked Jammed J Leaked J Jammed J Leake	Policy No.	
Collect's Record) Make of Veh:	Claims No.	×
Make of Veh: Modified String STD AIRing or Tyre Size: F: Jo 5 6 o R 6 R: L Repair at the time of inspection. Sal. or Market Value: IDAC Accident Rport: Consistent? Yes or No GIA PR Seen: Consistent? Yes or No GIA PR Seen: Consistent? Yes or No Carl Repairs: Jac Gays Res.: Yes or No Survey held at Do. A. Lo 2 Jac Do. J. Let Do. J. Let Jac Do. J. Let	Sum Insured: Excess:	
(Policy Condition) Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value: Ba	(Client's Record)	70
Policy Condition Remark: The veh had commenced its repair at the time of inspection. N/S O/S S JUNI/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PR/SUMI/TOYO/YOKO or Ws.3+La.Co. Front Rear R/Bal. S mm R/	Make of Veh:	
Remark: The veh had commenced its repair at the time of inspection. Ball or Market Value: IDAC Accident Rport: Consistent?: Yes or No Ball or Market Value: IDAC Accident Rport: Consistent?: Yes or No Ball or Market Value: IDAC Accident Rport: Consistent?: Yes or No Ball or Market Value: IDAC Accident Rport: Consistent?: Yes or No Ball or Market Value: IDAC Accident Rport: Consistent?: Yes or No Ball or Market Value: IDAC Accident Rport: Consistent?: Yes or No Ball or Market Value: IDAC Accident Rport: Consistent?: Yes or No Ball or Market Value: IDAC Accident Rport: Consistent?: Yes or No Ball or Market Value: IDAC Accident Rport: Consistent?: Yes or No Ball or Market Value: IDAC Accident Rport: Consistent?: Yes or No Ball or Market Value: IDAC Accident Rport: Consistent?: Yes or No Ball or Market Value: IDAC Accident Rport: Consistent?: Yes or No Ball or Market Value: IDAC Accident Rport: Consistent?: Yes or No Ball or Market Value: Ball or Market Value: Ball or Market Value: IDAC Accident Rport: Consistent?: Yes or No Ball or Market Value:		Tyre Size: F: 205 60 R 16
repair at the time of inspection. Ball or Market Value: IDAC Accident Rport: Consistent?: Yes or No Consistent?: Yes or No Est. Repairs: Ball or Market Value: IDAC Accident Rport: Consistent?: Yes or No Consistent?: Yes or No Est. Repairs: Ball or Market Value: IDAC Accident Rport: Consistent?: Yes or No Consistent?: Yes or No LUBall. Somm LUBall. Somm LUBall. Somm LUBall. Somm LUBall. Som Ming DOA 10 2 2020 The U/C / Chassis frame / Body Structure affected due to collision. REOEIVED 2 3 Marx 2020 DOA 10 2 2020 The U/C / Chassis frame / Body Structure affected due to collision. REOEIVED 2 3 Marx 2020 DOA 10 2 2020 The U/C / Chassis frame / Body Structure affected due to collision. REOEIVED 2 3 Marx 2020 DOA 10 2 2020 The U/C / Chassis frame / Body Structure affected due to collision. REOEIVED 2 3 Marx 2020 DOA 10 2 2020 The U/C / Chassis frame / Body Structure affected due to collision. REOEIVED 2 3 Marx 2020 DOA 10 2 2020 The U/C / Chassis frame / Body Structure affected due to collision. REOEIVED 2 3 Marx 2020 DOA 10 2 2020 REOEIVED 2 3 Marx 2020 DOA 10 2 2020 REOEIVED 2 3 Marx 2020 DOA 10 2 2020 The U/C / Chassis frame / Body Structure affected due to coll	(Policy Condition)	R:(
Ball or Market Value: IDAC Accident Rport: Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No Est. Repairs: Ball S mm RBall S mm LBall S mm LBa	Remark: The veh had commenced its N/S	
DIDAG Accident Root: Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No Est. Repairs: 6 days Res.: Yes or No Lum Sum: 20 % 3 Val.: Yes or No CA / REV / REP. / 24 HRS Date: Person Contacted: N/OUT Date / Time	repair at the time of inspection.	TOYO/YOKO OF Westlake
GIA / PR Seen: Consistent? Yes or No Est. Repairs: 6 days Res.: Yes or No Lum Sum: 20 % 3 Val.: Yes or No CA / REV / REP. / 24 HRS Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or Person Contacted: Date / Time	Bal. or Market Value:	Front Rear
Est. Repairs: 68 days Res.: Yes or No Lum Sum: 20 % 3 Val.: Yes or No CA / REV / REP. / 24 HRS Date: Person Contacted: Vehicle: IN/OUT Date / Time	IDAC Accident Rport. Consistent? : Yes or No	
Lum Sum: 30 % 3 Val. Yes or No CA / REV / REP. / 24 HRS Date: Person Contacted: Vehicle: IN/OUT Date / Time	GIA / PR Seen: Consistent? : Yes or No	L/Bal. S mm
Date: Person Contacted: Vehicle: IN / OUT Date / Time Action / Instruction MS G S Z 8 (9 8 E) (8 2 Sent Reli Weiner S S S S S S S S S	Est Repairs: 6 days Res.: Yes or No	D.O.A. 10 02 2020 D.O.I. 14 02 220
Date: Person Contacted: IN/OUT Date: Person Contacted: Person Con	Lum Sum: 20 % 3 Val.: Yes or No	Survey held at DT 184 sin Ming
Date: Person Contacted: The U/C / Chassis frame / Body Structure affected due to collision. Date / Time Action / Instruction MS (G BL 7869 & E 18 2 Sent Reeli by Meinen 20 03 2025 Tyrology L 5 8300 6 Jags of row (Red \$ 7059-00, 45%) RECEIVED 2 3 Mars 2020 Date/Time. File Pass 107 : Final Report Days Of Repair: 6 10 Contertine. File Pasture 107 : Final Report Resurvey No. of Trip: 3 Survey Fee: Transportation: 200 20 23 3 20 Typist Action Fee: Site Insep (\$ Site Insep (\$ Final Report Site Insep (\$ Final Report Site Insep (\$ Final Report Site Insep (\$ Site In	SAME PERSONAL STATES	
Date / Time Action / Instruction MSIG BLZ8698E 18 2 Seat Preli by Meinen Sector	CA / REV / REP. / 24 HRS Vehicle	e: IN/OUT Row
NSIG BLZ8698E 18 2 Sent Reli by Meinen 20 03 2020 Junday 1 5 8300 - 1 6 Jap y my (Red \$ 7059-00, 45% RECEIVED 2 3 Mars 2020 RECEIVED 2 3 Mars 2020 Results File Pass 107 Prell. Report Days Of Repair: 6 Resurvey No. of Trip: 3 Survey Fee: Transportation: 200 25 3 20 Typist Add Fee: Site Insp (\$) 5 + R8 51 11 Report Forth 1072 11 11 11 11 11 11 11	Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
18 2 Sent Preli by Meiner		
RECEIVED 2 3 Man, 2020 Red \$ 7059-00, 45%	W319 2758648	<u> </u>
RECEIVED 2 3 Man, 2020 Red \$ 7059-00, 45%	sta SIPII Mina	
RECEIVED 2 3 Man, 2020 Date/Time, File Pass to? : Prett. Report Days Of Repair: 6 Final Report Resurvey No. of Trip: 3 Survey Fee: Transportation: 200 25 25 3 20 Typist Add Fee: Site Insp (\$ 11 Interview (\$ Ftwee File I		
RECEIVED 2 3 Man, 2020 Date/Time, File Pass to? : Prett. Report Days Of Repair: 6 Final Report Resurvey No. of Trip: 3 Survey Fee: Transportation: 200 25 25 3 20 Typist Add Fee: Site Insp (\$ 11 Interview (\$ Ftwee File I	20/03/2020 Truston 1 4/5 83	1001: + 6 Jas of man (Red \$ 7059-00, 45%
Date/Time. File Pass to? Preti. Report Days Of Repair: 6	1. () bit of	
Date/Time. File Pass to? Preti. Report Days Of Repair: 6		
	REO	EIVED 2 3 Mar. 2020
	Date/Taxe Fie Pass to? Profit Report	Days Of Repair:
Dollaffirm, File Esturn In? Zeo Typist Acid Fee: Site Insp. (\$ 5+R\$_SI 11 11 12 12 13 14 15 15 15 15 15 15 15		
25 25 3 20 Typist Add Fee: Site Insp (\$) _ \$+F8_5I	Dosla/Time, File Return In?	TARS STORE AND ADDRESS OF THE STORE
Peport Forms: Lump 210 17 LEU: \$8300 = 250cl enc. (2)	3 23 3 20 Tunist	Add Fee: : Site Insp (\$)5+F85
Empt Forms: Lung 2 m / LEU: 12 \$8300 = 25		: Interview (\$) Press
(Ming 21) 17 (EU: 12 \$8300 = 200=1 400 0	Renest Forms:	the state of the s
	40,000	The state of the s

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Monica Chung Pei Zhen

Date:

18 Feb 2020

Preliminary Advice

Insured Vehicle No

: SLZ8698E

TP Vehicle No

: SH8254P

Accident Date

: 10/02/2020

Make

Assignment Date

: 18/02/2020

: HYUNDAI 140

Date of Inspection

: 14/02/2020

Est. Duration of Repair

: 5.00

Inspection At

: BIFROST AUTO PTE LTD (SIN MING) (HQ)

BLK 9 SECTOR C, #01-42 SIN MING INDUSTRIAL ESTATE

SINGAPORE 575644

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,359.00
Revised Amount	:S\$	11,270.28
Check Items (Estimated)	:S\$	0.00
Total	:S\$	11,270.28

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:5\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

) The	vehicle is	economical/not	economical	for repair.
-------	------------	----------------	------------	-------------

(X) The above survey was conducted on a 'without prejudice' basis.

Nivitha (LKK Auto)

From:

Crystal Lee <crystal_lee@sg.msig-asia.com>

Sent:

Thursday, 13 February 2020 4:20 PM

To:

Admin-D (LKKAuto); assignments

Cc

Ong Zi Hui

Subject:

Survey Request - Manual Assigned

Attachments:

SH 8254P - GIA Report.pdf

PRS our client's vehicle SH 8254 P and your insured's vehicle SLZ8698E (MSIG) on 10.02.2020.

Manual Assigned

Dear LKK,

Refer to the email below, please arrange survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment.

Thank you & Best regards,

Crystal Lee

Admin Officer, Claims Services (In-House Survey)

D: +65 6594 2535 | F: +65 6643 1349 | crystal_lee@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg









A Member of MS&AD INSURANCE GROUP

From: Helene Phua <helene_phua@sg.msig-asia.com>

Sent: Thursday, 13 February 2020 3:33 PM

To: Crystal Lee <crystal_lee@sg.msig-asia.com>; Ong Zi Hui <zihui_ong@sg.msig-asia.com>

Subject: FW: PRS our client's vehicle SH 8254 P and your insured's vehicle SLZ8698E (MSIG) on 10.02.2020.

Have a great week ahead!

Helene Phua

Admin Assistant, Claims Services

D: +65 6594 2493 | F: +65 6225 7402 | helene_phua@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of MS&AD INSURANCE GROUP

From: Helene Phua

Sent: Thursday, 13 February 2020 3:33 PM To: 'Claims Dept' <claims ltm@bifrostauto.com>

Cc: Winnie Chua <pingping chua@sg.msig-asia.com>

Subject: RE: PRS our client's vehicle SH 8254 P and your insured's vehicle SLZ8698E (MSIG) on 10.02.2020.

Hi,

Thank you for your selection.

We will proceed to assign LKK Auto Consultants Pte Ltd via Merimen at our end and update you upon confirmation.

Please do not contact them directly to prevent confusion. Any arrangement or appointment of surveyor must come from MSIG.

Please be informed that our surveyor will also be conducting a post repair inspection within the stipulated timeline under the protocol.

Have a great week ahead!

Helene Phua

Admin Assistant, Claims Services

D: +65 6594 2493 | F: +65 6225 7402 | helene_phua@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg 🕡 🎯 🗓 🖸









A Member of MS&AD INSURANCE GROUP

From: Claims Dept <claims | Itm@bifrostauto.com>

Sent: Thursday, 13 February 2020 2:56 PM

To: Helene Phua <helene phua@sg.msig-asia.com>

Cc: Winnie Chua chua@sg.msig-asia.com; Assessment <claims@bifrostauto.com</pre>; Regina

<assessment ltc@bifrostauto.com>; Claims Dept <claims ltv@bifrostauto.com>; claims ltr@bifrostauto.com

Subject: Re: PRS our client's vehicle SH 8254 P and your insured's vehicle SLZ8698E (MSIG) on 10.02.2020.

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

WITHOUT PREJUDICE

Hi,

Pls ass	ign them immediately.
Bifrost	s & Regards, t Auto Pte Ltd ent Claims Dept
On Th	u, 13 Feb 2020 at 14:12, Helene Phua < helene phua@sg.msig-asia.com > wrote:
Hi,	
We re	efer to your email dated 13/02/2020.
Pleas	e choose one surveyor from the list that you wish for us to appoint to conduct the pre-repair inspection:
1)	LKK Auto Consultants Pte Ltd
2)	Formteam Consultancy Pte Ltd
3)	A-Pac Adjusters & Surveyors Pte Ltd
4)	STA Inspection Pte Ltd
5)	Appraisal VP Pte Ltd
6)	AutoProbe Consultants
7)	MSIG In-House Surveyors
	Fast-Lane settlement option is for clear-cut liability which MSIG will expedite offer @ 100% with express nent. Priority will be given to those opted for our in-house surveyor*
	cilitate an expeditious claim settlement, we hope you are agreeable for the above surveyor to be the SJE le Joint Expert).
If not	, you may wish to nominate any of the 10 surveyors listed below as the SJE, depending on their availability

We selected LKK Auto Consultants Pte Ltd .

 Xing Guo Qiang 	6) Chow Bo Xiong	
2. Kenneth Kong	7) Siew Meng Hui	
3. Marcus Chua	8) Daniel Chan	
4. Ng You Han	9) Victor Png	
5. Gary Soon	10) Samuel Phun	

In your response, please also provide us a list of 10 surveyors as your nominated SJE, regardless of whether you agree or disagree to our above nominated SJE. We may consider appointing one of your nominated SJE in case of any of our nominated SJE is not available.

NB:

- a. *Fast lane settlement is not applicable for cases that liability is in dispute*
- b. If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

We have created a dedicated motor survey mailbox for your motor survey request and pre-repair inspection. Please contact us (MSIG) by clicking this link: motorsurvey@sg.msig-asia.com

Have a great week ahead!

Helene Phua

Admin Assistant, Claims Services

D: +65 6594 2493 | F: +65 6225 7402 | helene_phua@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg

From: Claims Dept < claims Itm@bifrostauto.com > Sent: Thursday, 13 February 2020 12:46 PM

To: Winnie Chua <pingping chua@sg.msig-asia.com>; Helene Phua <helene phua@sg.msig-asia.com>

Cc: Regina <assessment Itc@bifrostauto.com>; claims Itr@bifrostauto.com; Assessment

<claims@bifrostauto.com>

Subject: Re: PRS our client's vehicle SH 8254 P and your insured's vehicle SLZ 8698 E on 10.02.2020.

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).
Without Prejudice
Dear Sir/ Mdm,
We refer to the above matter.
We represent our client, Wong Ying Wai Peter, to notify you of the aforesaid accident involving our client's vehicle SH 8254 P and your insured's vehicle SLZ 8698 E on 10.02.2020.
Please find enclose our client's GIA report for your necessary action.
This serves as a NOTICE that we are claiming against SLZ 8698 E for damages, costs and disbursements.
Please let us know within 2 working days from today, your client's and your intention to conduct a pre-repair surve of our client's vehicle.
PLEASE LET US HAVE A LIST OF YOUR EXTERNAL SURVEYORS FOR OUR SELECTION AS A SINGLE JOINT EXPERT.

If we do not receive any reply from you within the stipulated timeline, we shall proceed to appoint our own surveyor and proceed with the necessary repair for our client's vehicle without further reference to your insured or you.

Premises for the Pre-repair inspection: Blk 9 Sector C #01-42, Sin Ming Industrial Estate, Singapore 575644

Contact Person: Ms Lim / Ms Lee

Contact Email: claims | Itv@bifrostauto.com / claims | Itm@bifrostauto.com

VEH IN (Date & Time)

: 13.02.2020

PRS ARRANGEMENT (Date & Time)

: AS SOON AS POSSIBLE

Kindly cc a copy of this letter to your insured for his/her acknowledgement.

We look forward to hearing from you soon.

To avoid incurrence of any unnecessary cost on both our end, kindly confirm liability status within 7 days from this to minimize time wastage and incurrence of any unnecessary cost(s) on both our end, we seek your kind advice, within 7 days working days, on liability status for subject claim. If we do not hear from you within the stipulated period, we shall proceed with the purchase of your insured GIA report and this cost or any other cost incurred for confirmation of liability status shall be included in our LOD for reimbursement purpose.

Thank you.

You can protect our environment. Think before you print.

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential.

The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Thanks & Regards,

Bifrost Auto Pte Ltd

Accident Claims Dept

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	ACC	DISTRICT OF THE PARTY.	TOTA		Test 1	
TO STORE THE PARTY OF THE PARTY	AGG	DI-IV	01/4	11-11	n-ix	ш

Date Of Report

10/02/2020 16:37

Date Of Accident

10/02/2020 08:30

Exact Location Of Accident

AYE TWDS TUAS AFTER EXIT 8

Country/State of Loss

SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SH8254P

Insured/Policyholder

Name Of Registered Owner

COMFORT TRANSPORTATION PTE LTD

Co Reg No

1XXXXXX821R

Email Address

FLEETSAFETY@CDGTAXI.COM.SG

Mobile Phone No.

Alternative Phone No

OFFICE-65508768

Vehicle Particulars

Manufacturer

HYUNDAI

Model

140

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

TAXI

Insurance Company

Name of Insurance Company

INDIA INTERNATIONAL INSURANCE PTE LTD

Type Of Coverage

THIRD PARTY FIRE AND/OR THEFT

Fleet Policy

YES

Policy Number

MCOM0015

Cover Note Number

Driver

Name of Driver

WONG YING WAI PETER

NRIC No

SXXXX391F

Date Of Birth

27/12/1960

Occupation

Date Of Driving Pass

OUTDOOR

15/02/1989

Driving Experience

30 YEARS AND 11 MONTHS

Gender

MALE

Mobile Number

(LOCAL) +65-97670280

Fax Number

Contact Number

EMail Address

PETER.WONG@OUTLOOK.SG

Address

BLK 15 MINBU ROAD

#12-15

Postcode

308166

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - TAXI DRIVER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

.

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

2

involved in the accident

NO

Was any body injured in the Accident?

1.00

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

....

soliciting/offering accident claims assistance. Number of Passengers (Including Driver) NO

3

Passenger 1

NAME:

3.

GENDER:

MALE

Passenger 2

NAME:

- 53

GENDER:

FEMALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLZ8698E

Vehicle Make/Model/Colour

Details Of Properties

PRIVATE CAR

Vehicle Category Name of Driver

RAMACHANDRAN THIRUKUMASAN


NRIC/Passport Number

Contact Number

Address

Postcode Insurance Company Name Nature Of Damage No. Of Passenger (Including Driver)

FRONT



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

A+ 0831) N3 , (Mor?	activity	34 8 23	str an	d trav	elling	alary
AYE (Tu	is) ape	er exit	8. To	ene I wa	s on	the fi	Pt 10	nee
with 2	passeng	ers ih	my to	axi. See	D) 48 -	the co	v in	Hon
braked	immed	rolely.	svdde	nly weh	ide B	lost	curto	ol ma
f the 1	war af	my -	tooci -	That's	all.			
	0				100			

DECLARATION

/We declare the foregoing particulars are true in every respect.

OMFORT TRANSPORTATION PTE LTD CO. REG. NO. 199303821R

olicyholder's Signature

ate & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE:

12-Feb-20

INSURANCE: MSIG

MODEL:

HYUNDAI 140

VEHICLE NO.: SH8254P

DESCRIPTION	QTY	LIST PRICE	AMOUNT
BOOTLID 154	1	\$2,174.90	\$2,174.90
BOOTLID RUBBER of word	1	\$96.50	\$96.50
BOOTLID HINGE (LH/RH) □□	2	\$284.60	\$569.20
BOOTLID LOCK UPPER Down	1	\$114.90	\$114.90
BOOTLID LOCK LOWER	1	\$23.20	\$23.20
BOOTLID 'H' EMBLEM Hac	1	\$22.70	\$22.70
BOOTLID CRDI PLATE	1	\$27.90	\$27.90
BOOTLID LAMP (LH/RH) WENC 565.60 x 2	2	\$1,131.20	\$2,262.40
BOOTLID ABSORBER	1	\$54.70	\$54.70
BOOTLID TRIMBOARD TOWN	1	\$143.90	\$143.90
BOOTLID TRIMBOARD CLIPS (11 PCS) Her	1	\$11.00	\$11.00
BOOTLID LOWER GARNISH (I40)	1	\$227.90	\$227.90
REAR BUMPER Dead 553.00	1	\$1,106.00	\$1,108.00
REAR BUMPER REINFORCEMENT BRACKET Declar 0/5	180.30	\$160.60	\$160.60
REAR BUMPER REINFORCEMENT Waster Will	1	\$428.40	\$428.40
REAR BUMPER CLIP	1	\$22.00	\$22.00
REAR BUMPER SPONGE	1	\$119.50	\$119.50
REAR BUMPER RUBBER MAT / 140 PLATE	1 SH	\$50.00	\$50.00
REAR BUMPER REFLECTOR LAMP (140) HIS 0 S CALC	- 2	\$32.00	\$64.00
TAIL LAMP (LH/RH) Chat with	2	\$697.80	\$1,395.60
TAIL LAMP QUARTER PANEL (LH/RH)	2	\$453.00	\$906.00
REAR PANEL Deady	1	\$526.70	\$526.70
REAR PANEL GARNISH defund	1	\$57.70	\$57.70
SPARE TYRE HOLDER Was keen	1	\$223.10	\$223.10
TAIL LAMP PANEL TOP (LH/RH)	2	\$189.10	\$378.20
SPARE TYRE PANEL Deuhin	1	\$852.80	\$852.80
SPARE TYRE PANEL CUSHION # 14 HOVN 209-50	1	\$223.10	\$223.10
REAR PANEL INNER PANEL (140)	1	\$380.00	\$380.00
EXHAUST SILENCER	42	\$1,935.40	\$1,935.40
XHAUST PIPE HANGER	1	\$117.10	\$117.10
XHAUST PIPE CENTRE	1	\$730.10	\$730.10

SUB TOTAL 10539.60			\$15,405.50
LE33 20%			\$3,081.10
DISCOUNTED TOTAL 8431.20			\$12,324.40
REAR BUMPER RESERVE SENSOR SN	1	\$118.00	\$118.00
BOOTLID COMFORT LOGO & TEL NO. STICKER No. SN	1	\$16.60	\$16.60
SUB TOTAL 184-60			\$134.60
Labour Charge			
Panel Beating	1	\$1,200.00	\$1,200.00
Spray Painting Charge	1	\$1,200.00	\$1,200.00
Wiring Charge	1	\$100.00	\$100.00
Tuff Kote	- 1	\$150.00	\$150.00
Towing Charge	1	\$50.00	\$50.00
Remove/Refix Reverse Sensor	1	\$120.00	\$120.00
Remove/Refix Exhaust Pipe	1	\$80.00	-\$80.00
TOTAL LABOUR			\$2,900.00
ESTIMATE TOTAL			\$15,359.00
quantum will be prepared after the vehicle is surveyed by			15369

14/02/2000 @ 1600 m HA ANTINY 1/2ml 6 days.

10385-8i

2KK Awto

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- * Parts prices are subject to confirmation
- * Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary liam(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date:

LKK Auto Consultants Pte Ltd (Co,Reg,No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/MSG20002578/DYF3N2

Date:

30/03/2020

REFERENCE

Handling Insurer:

MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

30001272163

Claimant Vehicle

SH8254P

Insured Vehicle No:

SLZ8698E

No: Date of Loss:

10/02/2020

Nature of Claim:

TP

Claim No: 238945

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SH8254P

Make & Model:

HYUNDAI 140, 1.7 L CRDI AT ABS AIRBAG 4DR (A)

Engine No:

D4FDDU391399

Reg. Date:

03/06/2014 (Man. Year: 2014)

Chassis No:

KMHLB41UMEU053920

Colour: Engine Capacity:

1685 cc

Odometer: 854243 km

Market Value/New Car Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Engine Modification:

Pre-accident Condition: No

CONDITION OF TYRES

Front Tyre Size:

205/60R16

Rear Tyre Size:

205/60R16

Front Left Side:

West Lake 5 mm

Rear Left Side: Rear Right Side: West Lake 5 mm West Lake 5 mm

Front Right Side: West Lake 5 mm The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		12,469.00	8,615.80	3,853.20	30.90
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,900.00	1,770.00	1,130.00	38.97
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	15,369.00	10,385.80	4,983.20	32,42
	Approved Total (Overridden) (S\$)		8,300.00		
	(S\$)	15,369.00	8,300.00	7,069.00	46.00
	+ GST 7.00/7.00% (S\$)	1,075.83	581.00	494.83	46.00
	Nett Amount (S\$)	16,444.83	8,881.00	7,563.83	46.00
		1/11/2/2017			

INSPECTION

Date of Assignment:

18/02/2020

Date Inspected:

14/02/2020 Inspected At:

Bifrost Auto Pte Ltd (sin Ming) (HQ)

Blk 9 Sector C, #01-42 Sin Ming Industrial Estate

Singapore 575644

Estimated Period of Repair:

6.0 days

Adjuster: **BRYAN TANI** Manager:

YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 Mar 2020)

Parts: HYUNDAI I40 1.7 L CRDI AT ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0) 143

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SH8254P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*BOOTLID	Bent	2,174.90 FL	*2,174.90 FL
2	1	*BOOTLID RUBBER	Deformed	96.50 FL	*96.50 FL
3	2	*BOOTLID HINGE (LH/RH)	Not Necessary	569.20 FL	*-FL
4	1	*BOOTLID LOCK UPPER	Damaged	114.90 FL	*114.90 FL
5	1	*BOOTLID LOCK LOWER	Repair	23.20 FL	*-FL
6	1	*BOOTLID H EMBLEM	Necessary	22.70 FL	*22.70 FL
7	1	*BOOTLID CRDI PLATE	Necessary	27.90 FL	*27.90 FL
8	2	*BOOTLID LAMP (LH/RH)	Cracked	2,262,40 FL	*1,131.20 FL
9	1	*BOOTLID ABSORBER	Not Necessary	54.70 FL	*-FL
10	1	*BOOTLID TRIMBOARD	Torn	143.90 FL	*143,90 FL
11	11	*BOOTLID TRIMBOARD CLIPS	Necessary	11.00 FL	*11.00 FL
12	1	*BOOTLID LOWER GARNISH (I40)	Not Necessary	227.90 FL	*-FL
13	1	*REAR BUMPER	Dented	1,106.00 FL	*553.00 FL
14	1	*REAR BUMPER REINFORCEMENT BRACKET O/S	Dented	160.60 FL	*80.30 FL
15	1	*REAR BUMPER REINFORCEMENT	Dented/Cracked	428.40 FL	*428.40 FL
16	10	*REAR BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
17	1	*REAR BUMPER SPONGE	Torn	119.50 FL	*119.50 FL
18	1	*REAR BUMPER REFLECTOR LAMP (I40)	O/s Cracked/N/s Not Necessary	64.00 FL	*32.00 FL
19	2	*TAIL LAMP (LH/RH)	Mounting Cracked	1,395.60 FL	*1,395.60 FL
20	2	*TAIL LAMP QUARTER PANEL (LH/RH)	Not Necessary	906.00 FL	*-FL
21	1	*REAR PANEL	Dented	526.70 FL	*526.70 FL
22	1	*REAR PANEL GARNISH	Deformed	57.70 FL	*57.70 FL
23	1	*SPARE TYRE HOLDER	Broken	223,10 FL	*223.10 FL
24	2	*TAIL LAMP PANEL TOP (LH/RH)	Not Necessary	378.20 FL	*-FL
25	1	*SPARE TYRE PANEL	Dented	852.80 FL	*852.80 FL
26	1	*SPARE TYRE PANEL CUSHION	Bent/Torn	223.10 FL	*209.50 FL
27	1	*REAR PANEL LOWER PANEL (I40)	Dented	380.00 FL	*380.00 FL
28	2	*EXHAUST SILENCER	Bent/Dented	1,935.40 FL	*1,935.40 FL
29	1	*EXHAUST PIPE HANGER	Not Necessary	117,10 FL	*-FL
30	1	*EXHAUST PIPE CENTRE	Not Necessary	730,10 FL	*-FL
31	1	*REAR BUMPER RUBBER MAT	Deformed	50.00 FS	*50.00 FS
32	1	*REAR BUMPER REVERSE SENSOR	Damaged	118.00 FS	*118.00 FS
33 F=Fn	1 anchise part. S=	*BOOTLID COMFORT LOGO & TEL NO STICKER SpcNett. L=ListItemDisc.	Necessary	16.60 FS	*16.60 FS

Sub Total (S\$) 15,540.10 10,723.60

- List Item Discount on L Items 20.00/20.00% (S\$) 3,071,10 2,107.80

> 8,615.80 Total Parts (S\$) 12,469.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recomm	mended	Lat	oour
LICCOLLI	11011404		2001

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	1,200.00	800.00
2	SPRAY PAINTING CHARGE	New	1,200.00	800.00
3	WIRING CHARGE	New	100.00	30.00
4	TUFF KOTE	New	150.00	40.00
5	TOWING CHARGE	New	50.00	0.00
6	REMOVE/REFIX REVERSE SENSOR	New	120.00	40.00
7	REMOVE/REFIX EXHAUST PIPE	New	80.00	60.00
		Gross Labour Cost (S\$)	2,900.00	1,770.00
	Report was	s unsubmitted during this print-out.		

< END OF ESTIMATES >