



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS3/CTI17023429/Qvd3e2-1

C/O : COMLAW LLC*

64 CECIL ST #06-01 IOB BLDG SINGAPORE
049711

Date : 04-03-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBE 459K	Veh. Inspected	JRE 8188
Policy No.	DMCVSN3063121700	Coverage (\$)	0.00
Claim No.	PCS/AR/219926/19	Excess (\$)	0.00
Assign From	JEAN KOH	Assign Date	13/02/2020

2. Vehicle Particulars & Condition

Make & Model	FORD RANGER XLT	c.c	2198
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	MNBLMFF80GW482850	Colour	DARK GREY
Odometer	84953	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	265/70 R16	MICHELIN	4 mm
L/H Front Tyre	265/70 R16	MICHELIN	4 mm
R/H Rear Tyre	265/70 R16	MICHELIN	4 mm
L/H Rear Tyre	265/70 R16	MICHELIN	4 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	30/11/2017	Inspection Date	12/12/2017
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. JRE 8188

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	CRUMPLED	960.00	960.00
1	FRONT BUMPER LOWER DIFFUSER	SCRATCHED	156.00	156.00
1	FRONT BUMPER RH FOGLAMP	SERVICEABLE	214.00	-
1	FRONT BUMPER RH FOGLAMP GARNISH	SCRATCHED	87.50	87.50
2	FRONT BUMPER SIDE RETAINER L/R	O/S BROKEN	76.00	38.00
1	FRONT GRILLE	SERVICEABLE	450.00	-
1	FRONT GRILLE "LOGO" EMBLEM	SERVICEABLE	75.00	-
1	FRONT RH ABS SENSOR	SERVICEABLE	160.00	-
1	FRONT RH DRIVE SHAFT ASSY	SERVICEABLE	1,400.00	-
2	FRONT RH DRUMPET HORN	SERVICEABLE	220.00	-
1	FRONT RH FENDER	BENT	557.00	557.00
1	FRONT RH FENDER "2.2" EMBLEM	NECESSARY	55.00	55.00
1	FRONT RH FENDER INNER SHIELD	CUT	180.00	180.00
1	FRONT RH FENDER MUDFLAP	SERVICEABLE	78.00	-
3	FRONT RH FENDER MUDFLAP CLIPS	SERVICEABLE	19.50	-
1	FRONT RH HEADLAMP	SCRATCHED	1,180.00	1,180.00
4	FRONT RH HEADLAMP CLIPS	SERVICEABLE	26.00	-
1	FRONT RH KNUCKLE ARM	SERVICEABLE	379.00	-
1	FRONT RH KNUCKLE ARM BEARING	SERVICEABLE	145.00	-
1	FRONT RH LOWER ARM	SERVICEABLE	480.00	-
1	FRONT RH POWER STEERING RACK END	SERVICEABLE	185.00	-
1	FRONT RH RADIATOR AIR GUIDE	SERVICEABLE	125.10	-
3	FRONT RH RADIATOR AIR GUIDE CLIPS	SERVICEABLE	19.50	-
1	FRONT RH SHOCK ABSORBER	SERVICEABLE	350.00	-
1	FRONT RH SHOCK ABSORBER TOP MOUNTING	SERVICEABLE	33.90	-
1	FRONT RH STABILIZER BAR LINK	SERVICEABLE	150.00	-
1	FRONT RH UPPER ARM	SERVICEABLE	320.00	-
1	FRONT SUPPORT PANEL	SERVICEABLE	870.00	-
1	FRONT SUPPORT PANEL TOP GARNISH	SERVICEABLE	68.00	-
5	FRONT SUPPORT PANEL TOP GARNISH CLIPS	SERVICEABLE	32.50	-
	LESS 20% DISCOUNT		-1,810.40	-642.70
			7,241.60	2,570.80

Report Ref No. CS3/CTI17023429/Qvd3e2-1

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	FRONT BUMPER SIDE ARCH GARNISH (SN)	SCRATCHED	280.00	150.00
1	FRONT RH 16" SPORT RIM (SN)	SERVICEABLE	750.00	-
1	FRONT RH 205/70R16 TYRE (SN)	SERVICEABLE	580.00	-
1	FRONT RH FENDER ARCH GARNISH (SN)	SCRATCHED	500.00	250.00
1	SET FRONT RH FENDER INNER SHIELD CLIPS (SN)	NECESSARY	30.00	30.00
1	BOT RADIATOR COOLANT (SN)	SERVICEABLE	80.00	-
			2,250.00	460.00
	<u>LABOUR</u>			
	TO REMOVE,REINSTALL AIR CON PARTS,VACUUMS,REFILL AIR CON GAS (TO FR).	NOT NECESSARY	180.00	-
	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS,CHECK LIGHTING,RESETTING HEADLAMP FOCUSING AND REWIRE FOR PARKING SENSOR.		200.00	30.00
	TO REMOVE,CHANGE FRONT SUSPENSION PARTS,ABSORBER,LOWER ARM,KNUCKLE ARM,WHEEL BEARING,BEARING HUB,DRIVE SHAFT,ANTI-ROLL BAR,TOP-ARM AND STEERING RACK AND PINION.	NOT NECESSARY	550.00	-
	TO ROAD TEST DRIVING,CHECK AND RESETTNG WHEEL ALIGNMENTS SYSTEM.		180.00	60.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS,REPAIR PORTION,AND WHERE CONSISTENT TO THE ACCIDENT.		1,000.00	400.00
	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.		1,500.00	400.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		120.00	30.00
			3,730.00	920.00
GRAND TOTAL			13,221.60	3,950.80

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,150.00
---	--	--	-----------------

Report Ref No. CS3/CTI17023429/Qvd3e2-1


OI SUN PIN

Asst. Automotive Assessor


ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.