



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2102731

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 19/04/2021
Reference CC6/CTI20002592/Kpa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. GBF 2595G
Insured Veh. GBE 1849L
Claim No. SNM20D200827
Policy No. DMCVSN3064531900
Accident Date 12/02/2020
Inspection Date 14/02/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Ref: CC6/CTI20002592/Kpa3q2	
			Date: 19/04/2021	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBE 1849L	Veh. Inspected	GBF 2595G	
Policy No.	DMCVSN3064531900	Coverage (\$)	0.00	
Claim No.	SNM20D200827	Excess (\$)	0.00	
Assign From		Assign Date	14/02/2020	
2. Vehicle Particulars & Condition				
Make & Model	FIAT DOBLO (M)	c.c	1248	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	ZFA26300006C58109	Colour	WHITE	
Odometer	145916 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/65 R15	TOYO	5 mm	
L/H Front Tyre	185/65 R15	TOYO	5 mm	
R/H Rear Tyre	185/65 R15	TOYO	7 mm	
L/H Rear Tyre	185/65 R15	TOYO	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/02/2020	Inspection Date	14/02/2020	
Survey held at	MOTORVIVA PTE LTD 10 TUAS AVENUE 18 SINGAPORE 638894			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 2595G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SIDE MIRROR SWITCH RH	MISSING	285.00	285.00
1	SIDE MIRROR CAP RH	MISSING	30.50	30.50
1	SIDE MIRROR COVER RH	BROKEN	134.53	134.53
1	SIDE MIRROR RH	BROKEN	749.36	749.36
1	SIDE MIRROR SIGNAL LAMP RH	MISSING	47.42	47.42
1	SIDE MIRROR GLASS UPPER RH	MISSING	93.45	93.45
1	SIDE MIRROR GLASS BOTTOM RH	MISSING	88.37	88.37
1	FRONT FENDER RH	BENT	246.24	246.24
1	FRONT FENDER BRACKET RH	TO REPAIR SEE LABOUR	33.44	-
1	FRONT FENDER INNER SHIELD	DISTORTED	151.03	151.03
10	FRONT FENDER CLIPS @\$3.00	NECESSARY	30.00	30.00
1	FRONT BUMPER	BUCKLED	781.28	781.28
1	FRONT BUMPER RETAINER LH	SERVICEABLE	35.00	-
1	FRONT BUMPER RETAINER RH	DISTORTED	35.00	35.00
1	FRONT BUMPER LOWER	BUCKLED	665.76	665.76
10	FRONT BUMPER CLIPS @\$3.00	NECESSARY	30.00	30.00
1	HEADLAMP RH	SERVICEABLE	749.55	-
1	FOG LAMP COVER	SERVICEABLE	52.90	-
	LESS 10% DISCOUNT		-	-336.79
			4,238.83	3,031.15
	<u>LABOUR</u>			
	TO REMOVE,REFIX & REPAIR AFFECTED DAMAGED PARTS,INCLUDING KNOCK OUT,WELD AND STRAIGHTEN ON THE AFFECTED PARTS.INCLUSIVE OF THE REPAIR OF FRONT FENDER BRACKET RH.		2,000.00	1,200.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRING AND FUNCTIONALITY.		100.00	20.00
	TO PUTTY,CLEAN,SPRAY PAINT AND POLISH,ETC.		1,300.00	800.00
	TO ALIGN,REPAIR AND PATTY FRONT DOOR RH.	NOT NECESSARY	380.00	-
			3,780.00	2,020.00
	GRAND TOTAL		8,018.83	5,051.15



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,000.00
---	--	--	-----------------

Report Ref No. CC6/CTI20002592/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBF 2595G

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBF 2595G

RE-INSPECTION

