

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG20002605/EVF3E2

Date: 20/04/2020

REFERENCE

Insured/Claimant: CHITTARANJANESHWAR JHA

Policy No: 2100387227

Date of Loss: 05/09/2019

Nature of Claim: OD

Claim No: 4727367726SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKP6078Y**

Make & Model: AUDI A4, 1.8 TFSI MU (EU6) (A)

Engine No: CJE083506

Reg. Date: 25/09/2014 (Man. Year: 2014)

Chassis No: WAUZZZ8KXEA158707

Colour: Black

Odometer: 56070 km

Engine Capacity: 1798 cc

Market Value/New Car Price: S\$66,000.00

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/50Z R17

Rear Tyre Size: 215/50Z R17

Front Left Side: Nexen 5 mm

Rear Left Side: Nexen 5 mm

Front Right Side: Nexen 5 mm

Rear Right Side: Nexen 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,958.00	3,004.00	7,954.00	72.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,832.00	2,652.00	4,180.00	61.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	17,790.00	5,656.00	12,134.00	68.21
- Excess (\$\$)	3,000.00	3,000.00	0.00	0.00
(\$\$)	14,790.00	2,656.00	12,134.00	82.04
+ GST 7.00/7.00% (\$\$)	1,035.30	185.92	849.38	82.04
Nett Amount (\$\$)	15,825.30	2,841.92	12,983.38	82.04

INSPECTION

Date of Assignment: 14/02/2020

Date Inspected: 14/02/2020 Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Please be informed that the car owner decided to withdraw the claim of OD.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$3,547.00 NETT)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented	2,100.00 FS	*2,100.00 FS
2	1		*FRONT BUMPER FIXING PARTS	* Check	234.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	207.00 FS	*- FS
4	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Not Necessary	123.00 FS	*- FS
5	1		*FRONT WHEEL SPOILER - LH	* Check	45.00 FS	*- FS
6	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	113.00 FS	*- FS
7	1		*FRONT BUMPER SIDE REINFORCEMENT	Not Necessary	802.00 FS	*- FS
8	1		*FRONT BUMPER GUIDE SECTION - LH	* Check	33.00 FS	*- FS
9	2		*FRONT BUMPER SUPPORT	* Check	23.00 FS	*- FS
10	1		*FRONT FENDER - LH	Dented	904.00 FS	*904.00 FS
11	1		*FRONT FENDER ATTACHMENT PARTS	* Check	52.00 FS	*- FS
12	1		*FENDER BRACKET - LH FRONT	* Check	48.00 FS	*- FS
13	1		*FENDER DEFORMATION ELEMENT BRACKET - LH REAR	* Check	45.00 FS	*- FS
14	1		*FRONT FENDER WHEEL HOUSING LINER	* Check	223.00 FS	*- FS
15	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	* Check	41.00 FS	*- FS
16	1		*HEADLAMP BRACE - LH	* Check	41.00 FS	*- FS
17	1		*MAIN BEAM HEADLIGHT MOUNTING - LH	* Check	107.00 FS	*- FS
18	1		*HEADLAMP BRACKET - LH	* Check	96.00 FS	*- FS
19	1		*GAS DISCHARGE LAMP HEAD LIGHT - LH	* Check	2,152.00 FS	*- FS
20	1		*HEADLIGHT WASHER SYSTEM LIFT CYLINDER - LH	Not Necessary	192.00 FS	*- FS
21	1		*HALOGEN FOG LAMP - LH	Not Necessary	242.00 FS	*- FS
22	1		*EXTERIOR MIRROR MOUNTING - LH	Not Necessary	1,226.00 FS	*- FS
23	1		*MIRROR CAP - LH	Not Necessary	522.00 FS	*- FS
24	1		*TURN SIGNAL INDICATOR	Not Necessary	92.00 FS	*- FS
25	1		*MIRROR GLASS	Not Necessary	209.00 FS	*- FS
26	4		*FRONT ALUMINIUM RIM - LH	Not Necessary	666.00 FS	*- FS
27	1		*ALUMINIUM RIM RUBBER VALVE	Not Necessary	13.00 FS	*- FS
28	1		*SUNDRIES	* Check	300.00 FS	*- FS
29	1		*FRONT FENDER BRACE - LH LOWER	* Check	107.00 FS	*- FS
Total Parts (\$\$)						10,958.00 3,004.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORN, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS WING MIRROR ASSY. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,800.00	1,000.00
3	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER, LHS FRONT DOOR AND LHS WING MIRROR COVER	New	3,200.00	1,100.00
4	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
5	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
Gross Labour Cost (\$\$)			6,832.00	2,652.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >