

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20002617/UGS3Q2

Date: 07/04/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015	
Claimant			
Vehicle No : SMA3541B	Insured Vehicle No :	SHA4061Y	
Date of Loss: 01/02/2020	Nature of Claim: TP	Claim No: MCT20020019	

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA3541B		
Make & Model:	HONDA JAZZ, 1.5 VTIR CVT (A)	Engine No:	L15B31190662
Reg. Date:	02/02/2017 (Man. Year: 2016)	Chassis No:	JHMGK5850HX200934
Colour:	Red	Odometer:	75861 km
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Comforest 8 mm	Rear Left Side:	Comforest 8 mm
Front Right Side:	Comforest 8 mm	Rear Right Side:	Comforest 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,006.20	1,898.64	24,107.56	92.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,050.00	720.00	6,330.00	89.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	33,056.20	2,618.64	30,437.56	92.08
Approved Total (Overridden) (\$\$)		2,050.00		
(\$\$)	33,056.20	2,050.00	31,006.20	93.80
+ GST 7.00/7.00% (\$\$)	2,313.93	143.50	2,170.43	93.80
Nett Amount (\$\$)	35,370.13	2,193.50	33,176.63	93.80
+ Loss of Use (6.0 x S\$50.00/day) (\$\$)		300.00		
Nett Liability (\$\$)		2,493.50		
Global Sum Settlement (\$\$)		2,490.00		

INSPECTION

Date of Assignment:	14/02/2020	
Date Inspected:	14/02/2020 Inspected At:	RICO 60 AUTO SERVICES PTE LTD (HQ) 8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT Singapore 415875
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Mar 2020)
Parts:	144	HONDA JAZZ 1.5 VTIR CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMA3541B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP (RH)	Holder Cracked	897.20 F	*897.20 FL
2	1		*HEADLAMP BRACKET (RH)	Not Necessary	82.90 F	*- FL
3	1		*FRONT BUMPER	Distorted	796.00 F	*517.70 FL
4	1		*FRONT BUMPER RETAINER	O/S Bent	142.40 F	*30.50 FL
5	1		*FRONT BUMPER REINFORCEMENT BAR	Not Necessary	591.90 F	*- FL
6	2		*FRONT BUMPER BRACKET (RH)	Not Necessary	301.80 F	*- FL
7	1		*FRONT BUMPER BEAM (NPA)	Not Necessary	0.00 F	*- FL
8	1		*FRONT BUMPER SPONGE	No such part	204.10 F	*- FL
9	1		*FRONT BUMPER GRILLE	Not Necessary	434.70 F	*- FL
10	1		*FRONT BUMPER FOG LAMP (RH)	Cracked	421.20 F	*274.00 FL
11	1		*FRONT BUMPER FOG LAMP GARNISH (RH)	Twisted	195.90 F	*85.50 FL
12	1		*FRONT BUMPER UNDERCOVER	Not Necessary	287.40 F	*- FL
13	1		*FRONT FENDER (RH)	Repair	476.50 F	*- FL
14	1		*FRONT FENDER INNER PANEL (RH)	Repair	399.10 F	*- FL
15	1		*FRONT FENDER QUARTER WINDOW MOULDING (RH)	Not Necessary	123.80 F	*- FL
16	1		*FRONT FENDER COWLING (RH)	Torn	92.70 F	*92.70 FL
17	1		*FRONT SUPPORT PANEL	Not Necessary	517.80 F	*- FL
18	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	282.10 F	*- FL
19	1		*WIPER WASHER TANK	Deformed	134.90 F	*134.90 FL
20	1		*WIPER WASHER MOTOR	Not Necessary	300.50 F	*- FL
21	1		*FRONT ABSORBER (RH)	Not Necessary	496.70 F	*- FL
22	1		*FRONT LOWER ARM (RH)	Not Necessary	483.90 F	*- FL
23	1		*FRONT KNUCKLE (RH)	Not Necessary	415.10 F	*- FL
24	1		*FRONT KNUCKLE BEARING (RH)	Not Necessary	298.70 F	*- FL
25	1		*FRONT BEARING HUB (RH)	Not Necessary	271.50 F	*- FL
26	1		*FRONT CROSSMEMBER	Not Necessary	2,041.00 F	*- FL
27	1		*FRONT STEERING RACK & PINION ASSY	Not Necessary	1,897.10 F	*- FL
28	1		*FRONT DRIVE SHAFT (RH)	Not Necessary	1,083.10 F	*- FL
29	1		*FRONT TIE ROD (RH)	Not Necessary	278.90 F	*- FL
30	1		*FRONT TIE ROD END (RH)	Not Necessary	142.50 F	*- FL
31	1		*FRONT STABILIZER BAR	Not Necessary	782.80 F	*- FL
32	1		*FRONT STABILIZER LINK (RH)	Not Necessary	201.20 F	*- FL
33	10		*BONNET INSULATOR CLIPS	Not Necessary	100.00 FS	*- FS
34	10		*FRONT BUMPER CLIPS	Necessary	100.00 FS	*40.00 FS
35	1		*FRONT CARPLATE	Not Necessary	120.00 FS	*- FS
36	1		*FRONT CARPLATE FRAME	Not Necessary	120.00 FS	*- FS
37	10		*FRONT FENDER COWLING CLIPS	Not Necessary	100.00 FS	*- FS
38	10		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	100.00 FS	*- FS
39	2		*SET FRONT TYRE	Not Necessary	2,000.00 FS	*- FS
40	2		*SET FRONT RIM	Not Necessary	8,000.00 FS	*- FS
41	1		*FRONT BUMPER FOG LAMP SIDE LAMP (RH)	Cracked	290.80 F	*290.80 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					26,006.20	2,363.30
- List Item Discount on L Items 0.00/20.00% (\$)					0.00	464.66
Total Parts (\$)					26,006.20	1,898.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RNR ACCIDENT DAMAGE PARTS ,CUT /WELD ,KNOCKING & REALIGN	New	2,100.00	300.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	New	2,100.00	400.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	New	250.00	0.00
4	TO RNR UPHOLSTERY ,GARNISH AND ATTACHMENT PARTS	New	400.00	0.00
5	TO RNR DOOR MECHANISM	New	400.00	0.00
6	TO RNR SIDE MIRROR ASSY	New	400.00	0.00
7	TO RNR UNDERCARRIAGE SYSTEM	New	250.00	0.00
8	TO CHECK WHEEL ALIGNMENT	New	250.00	0.00
9	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS }	New	150.00	20.00
10	TO RNR TYRE AND WHEEL BALANCING }	New	250.00	0.00
11	TO DO DIAGNOSIS AND RESET ,REPROGRAM OR CODING FAULT CODE	New	400.00	0.00
12	TO DO WATER LEAK TEST	New	100.00	0.00
Gross Labour Cost (\$\$)			7,050.00	720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >