



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMG 7385C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	BUCKLED	1,990.00	1,580.00
2	REAR BUMPER BRACKETS	TO REPAIR SEE LABOUR	98.00	-
2	REAR BUMPER RETAINERS	O/S DISTORTED	72.00	36.00
2	REAR BUMPER REFLECTORS	N/S CRACKED	280.00	140.00
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	520.00	-
2	REAR BUMPER REVESE SENSORS	SHORTED (1PC ONLY)	820.00	255.00
1	SET REAR BUMPER CLIPS	NECESSARY	40.00	40.00
1	REAR TAILGATE	CRACKED	2,190.00	2,190.00
1	REAR TAILGATE LOCK	DENTED	470.00	325.00
2	REAR TAILGATE HINGES	TO REPAIR SEE LABOUR	177.00	-
1	REAR TAILGATE "C4" EMBLEM	NECESSARY	99.00	99.00
1	REAR TAILGATE "CITROEN" EMBLEM	NECESSARY	82.00	82.00
1	REAR TAILGATE CENTRE LOGO	NECESSARY	63.00	63.00
1	REAR TAILGATE INNER TRIM	SERVICEABLE	1,680.00	-
1	REAR TAILGATE OUTER CHROME MOULDING	WARPED	320.00	320.00
1	REAR WINDSCREEN MOULDING	NECESSARY	120.00	120.00
2	TAILLAMPS	SERVICEABLE	1,340.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	890.00	-
1	REAR END PANEL TOP GARNISH	SERVICEABLE	430.00	-
1	REAR SPARE TYRE COMPARTMENT	TO REPAIR SEE LABOUR	920.00	-
1	REAR SPARE TYRE TOP BOARD	SERVICEABLE	430.00	-
1	REAR EXHAUST SILENCER	TO REPAIR SEE LABOUR	2,330.00	-
1	SET REAR EXHAUST SILENCER MOUNTING	SERVICEABLE	45.00	-
2	FRONT SEAT BELT @\$615.00	JAMMED	1,230.00	1,230.00
	LESS 10% DISCOUNT		-	-648.00
			16,636.00	5,832.00

Report Ref No. CS/TP20002638/Ksf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	REAR TAILGATE WEATHERSTRIP (SN) (50%)	CUT	290.00	145.00
1	REAR NUMBER PLATE (SN)	SERVICEABLE	60.00	-
			350.00	145.00
	<u>LABOUR</u>			
	TO CHECK WIRING AND LIGHTINGS.		80.00	20.00
	LABOUR CHARGE TO REMOVE, CUT OUT DAMAGE PORTION, JACK OUT, STRAIGHTEN, PANEL BEATING, WELDING, ALIGN AND RENEW REPLACED PARTS. INCLUSIVE OF THE REPAIR OF REAR BUMPER BRACKETS, REAR BUMPER REINFORCEMENT, REAR TAILGATE HINGES, REAR END PANEL, REAR SPARE TYRE COMPARTMENT AND REAR EXHAUST SILENCER		1,000.00	500.00
	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREAS.		900.00	600.00
	TO REMOVE, REPLACE REAR TAILGATE AND FENDER FITTINGS TO FACILITATE REPAIR.		350.00	60.00
	TO REMOVE, REPLACE REAR WINDSCREEN GLASS.		150.00	120.00
	TO REMOVE, REPLACE REAR REVERSE SENSOR.		150.00	60.00
	TO REMOVE, REPLACE REAR EXHAUST SILENCER.	NOT NECESSARY	150.00	-
			2,780.00	1,360.00
GRAND TOTAL			19,766.00	7,337.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,850.00

Report Ref No. CS/TP20002638/Ksf3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.