

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG20002644/R1TF3E2

**Date:** 24/08/2020

#### REFERENCE

Insured/Claimant:	MARTIN SURYADI	Policy No:	1800136944	
Date of Loss:	12/02/2020	Nature of Claim:	OD	Claim No: 0473560733SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMF7650S</b>		
Make & Model:	AUDI A4, 2.0 (A)	Engine No:	CVK051549
Reg. Date:	23/11/2018 (Man. Year: 2017)	Chassis No:	WAUZZZF41JA081451
Colour:	Black	Odometer:	28458 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$123,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	947.00	540.96	406.04	42.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,522.00	2,322.00	1,200.00	34.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,469.00</b>	<b>2,862.96</b>	<b>1,606.04</b>	<b>35.94</b>
<b>- Excess (S\$)</b>	<b>1,600.00</b>	<b>1,600.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>2,869.00</b>	<b>1,262.96</b>	<b>1,606.04</b>	<b>55.98</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>200.83</b>	<b>88.41</b>	<b>112.42</b>	<b>55.98</b>
<b>Nett Amount (S\$)</b>	<b>3,069.83</b>	<b>1,351.37</b>	<b>1,718.46</b>	<b>55.98</b>

#### INSPECTION

Date of Assignment: 17/02/2020

Date Inspected: 17/02/2020 Inspected At:

281 Alexandra Road

Repairer : Premium Automobiles Pte Ltd

Estimated Period of Repair: 5.0 days

**Adjuster:** MOHD RASUL

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*AIR LINE	Serviceable	37.00 FS	*- FS
2	1		*BREATHER LINE	Serviceable	109.00 FS	*- FS
3	1		*UNDER BODY TRIM	Missing	305.00 FS	*243.60 FS
4	1		*SUNDRIES	Necessary	200.00 FS	*1.36 FS
5	1		*FUEL LINE	Cut	296.00 FS	*296.00 FS
<b>Total Parts (S\$)</b>					<b>947.00</b>	<b>540.96</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REINSTALL REAR CARPET TO FACILITATE THE REPAIR	New	480.00	480.00
2	TO DISLODGE AND RENEW UNDERBODY TRIMS. TO RENEW BREATHER LINE AND AIR LINE FOR ACTIVATED CHARCOAL CONTAINER	New	600.00	600.00
3	TO REPAIR AND WELD THE BOTTOM PLATE	New	1,050.00	550.00
4	TO RESPRAY BOTTOM PLATE	New	1,200.00	500.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
			<b>Gross Labour Cost (S\$)</b>	<b>3,522.00</b>
				<b>2,322.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >