

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way, #21-01 SGX Centre 2  
Singapore 068807

**Our File No:** CS/MSG20002648/QSF3E2

**Date:** 10/12/2020

#### REFERENCE

Insured/Claimant:	Hooy Kok Wai	Policy No:	28968500MPQ
Date of Loss:	07/02/2020	Nature of Claim:	OD
		Claim No:	619562

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SGD333K</b>		
Make & Model:	PORSCHE CAYENNE, 4.8 TURBO (E2-II) TIP E5 S/R (A)	Engine No:	003346
Reg. Date:	10/06/2015 (Man. Year: 2015)	Chassis No:	WP1ZZZ92ZFLA82877
Colour:	White	Odometer:	11160 km
Engine Capacity:	0 cc		
Market Value/New Car Price:	S\$380,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	295/35 R21	Rear Tyre Size:	295/35 R21
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	100,541.50	76,373.20	24,168.30	24.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,010.00	3,190.00	4,820.00	60.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>108,551.50</b>	<b>79,563.20</b>	<b>28,988.30</b>	<b>26.70</b>
<b>- Excess (S\$)</b>	<b>3,000.00</b>	<b>3,000.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>105,551.50</b>	<b>76,563.20</b>	<b>28,988.30</b>	<b>27.46</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>7,388.61</b>	<b>5,359.42</b>	<b>2,029.19</b>	<b>27.46</b>
<b>Nett Amount (S\$)</b>	<b>112,940.11</b>	<b>81,922.62</b>	<b>31,017.49</b>	<b>27.46</b>

#### INSPECTION

Date of Assignment: 17/02/2020

Date Inspected: 17/02/2020 Inspected At:

23 Kaki Bukit Ave 4 Kaki Bukit #04-01  
Repairer : Automobile Integrated  
Management Pte Ltd (HQ)

Estimated Period of Repair: 12.0 days

**Adjuster:** OI SUN PIN

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 10 Dec 2020)
<b>Parts:</b> M1-SUV	PORSCHE CAYENNE 4.8 TURBO (E2-II) TIP E5 S/R (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SGD333K)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>*FRONT BONNET</b> (WCP)	Bent	4,200.00 F	*4,200.00 F
2	1		<b>*FRONT BONNET BADGE</b> (WCP)	Necessary	220.00 F	*220.00 F
3	1		<b>*FRONT BONNET LOCK</b> (WCP)	Repair	185.00 F	*- F
4	1		<b>*FRONT BONNET DAMPERS - L/R</b> (WCP)	O/S Jammed / N/S Serviceable	240.00 F	*120.00 F
5	1		<b>*FRONT BONNET HINGES - L/R</b> (WCP)	O/S Crumpled / N/S Repair	320.00 F	*160.00 F
6	1		<b>*FRONT BUMPER</b> (WCP)	Cracked	980.00 F	*980.00 F
7	1		<b>*FRONT BUMPER LOWER GUARD</b> (WCP)	Cracked	960.00 F	*960.00 F
8	1		<b>*FRONT BUMPER FOG LAMP - RH - LOWER</b> (WCP)	Missing	580.00 F	*580.00 F
9	1		<b>*FRONT BUMPER SIDE GRILLE</b> (WCP)	Serviceable	250.00 F	*- F
10	1		<b>*FRONT BUMPER SIDE COVER</b> (WCP)	Missing	250.00 F	*250.00 F
11	1		<b>*FRONT BUMPER L.E.D LIGHT</b> (WCP)	Cracked	750.00 F	*750.00 F
12	1		<b>*FRONT BUMPER CTR GRILLE</b> (WCP)	Crumpled	330.00 F	*330.00 F
13	1		<b>*FRONT BUMPER SIDE PAD</b> (WCP)	Serviceable	160.00 F	*- F
14	1		<b>*FRONT BUMPER FRAME PAD</b> (WCP)	Serviceable	295.00 F	*- F
15	1		<b>*FRONT BUMPER SIDE HOLDER</b> (WCP)	Broken	60.00 F	*60.00 F
16	1		<b>*FRONT BUMPER SIDE BRACKET</b> (WCP)	Bent	120.00 F	*120.00 F
17	1		<b>*FRONT BUMPER SIDE RETAINER</b> (WCP)	Crumpled	65.00 F	*65.00 F
18	1		<b>*FRONT BUMPER TOW COVER</b> (WCP)	Missing	95.00 F	*95.00 F
19	1		<b>*FRONT BUMPER PDC SENSORS</b> (WCP)	O/S Missing	570.00 F	*285.00 F
20	1		<b>*FRONT BUMPER PDC SENSOR WIRE HARNESS</b> (WCP)	Cracked	670.00 F	*670.00 F
21	1		<b>*FRONT BUMPER TOP BEAM</b> (WCP)	Serviceable	180.00 F	*- F
22	1		<b>*FRONT BUMPER REINFORCEMENT</b> (WCP)	Crumpled	750.00 F	*750.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
23	1		<b>*FRONT BUMPER TOP GUIDE</b> (WCP)	Cracked	230.00 F	*230.00 F
24	1		<b>*FRONT BUMPER STAY</b> (WCP)	Serviceable	120.00 F	*- F
25	1		<b>*FRONT FENDER - RH</b> (WCP)	Cut	1,500.00 F	*1,500.00 F
26	1		<b>*FRONT FENDER WHEEL ARCH GARNISH</b> (WCP)	Missing	430.00 F	*430.00 F
27	1		<b>*FRONT FENDER INNER SHIELD</b> (WCP)	Cracked	350.00 F	*350.00 F
28	10		<b>*FRONT FENDER INNER SHIELD CLIPS</b> (WCP)	Serviceable	60.00 F	*- F
29	1		<b>*FRONT FENDER INNER TOP COVER</b> (WCP)	Scratched	310.00 F	*310.00 F
30	1		<b>*FRONT FENDER INNER PANEL</b> (WCP)	Cut	1,800.00 F	*1,265.00 F
31	1		<b>*FRONT FENDER WHEEL HOUSING</b> (WCP)	Repair	3,200.00 F	*- F
32	1		<b>*FRONT FENDER WHEEL HOUSING ETENSION</b> (WCP)	Repair	450.00 F	*- F
33	1		<b>*FRONT HEADLAMP - RH</b> (WCP)	Cracked	5,200.00 F	*5,200.00 F
34	1		<b>*FRONT HEADLAMP SEAL</b> (WCP)	Necessary	220.00 F	*220.00 F
35	1		<b>*FRONT HEADLAMP LOWER BRACKET</b> (WCP)	Cracked	185.00 F	*185.00 F
36	1		<b>*FRONT HEADLAMP BULB</b> (WCP)	Serviceable	650.00 F	*- F
37	1		<b>*FRONT HEADLAMP BULB COVER</b> (WCP)	Crumpled	120.00 F	*120.00 F
38	1		<b>*FRONT HEADLAMP CONTROL UNIT - NO.1</b> (WCP)	Crumpled	600.00 F	*600.00 F
39	1		<b>*FRONT HEADLAMP CONTROL UNIT - NO.2</b> (WCP)	Crumpled	1,150.00 F	*1,150.00 F
40	1		<b>*FRONT HEADLAMP SPRAY NOZZLE PEN</b> (WCP)	Cracked	280.00 F	*280.00 F
41	1		<b>*SET FRONT HEADLAMP KIT</b> (WCP)	Serviceable	250.00 F	*- F
42	1		<b>*FRONT SUPPORT PANEL</b> (WCP)	Cracked	750.00 F	*750.00 F
43	1		<b>*FRONT SUPPORT TOP GARNISH</b> (WCP)	Repeated	210.00 F	*- F
44	20		<b>*FRONT SUPPORT TOP GARNISH CLIPS</b> (WCP)	Serviceable	120.00 F	*- F
45	1		<b>*FRONT SHOCK ABSORBER ASSY - RH</b> (WCP)	Bent	3,500.00 F	*3,500.00 F
46	1		<b>*FRONT SUB FRAME ASSY</b> (WCP)	Serviceable	3,200.00 F	*- F
47	1		<b>*FRONT SPORT WHEEL - RH</b> (WCP)	Scratched	4,200.00 F	*4,200.00 F
48	1		<b>*FRONT TOP ARM</b> (WCP)	Serviceable	980.00 F	*- F
49	1		<b>*FRONT LOWER ARM</b> (WCP)	Bent	1,550.00 F	*1,550.00 F
50	1		<b>*FRONT KNUCKLE ARM</b> (WCP)	Serviceable	1,200.00 F	*- F
51	1		<b>*FRONT WHEEL HUB BEARING</b> (WCP)	Jammed	750.00 F	*750.00 F
52	1		<b>*WASHER TANK</b> (WCP)	Cracked	280.00 F	*280.00 F
53	1		<b>*WASHER TANK NECK</b> (WCP)	Cracked	95.00 F	*95.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	1		<b>*WASHER TANK MOTOR</b> (WCP)	Serviceable	195.00 F	*- F
55	1		<b>*AIR CLEANER BOX ASSY</b> (WCP)	Cracked	780.00 F	*780.00 F
56	1		<b>*AIR CLEANER DUCT - INLET</b> (WCP)	Crumpled	180.00 F	*180.00 F
57	1		<b>*AIR CLEANER DUCT - OUTLET</b> (WCP)	Crumpled	180.00 F	*180.00 F
58	1		<b>*AIR INTERCOOLER</b> (WCP)	Cracked	2,600.00 F	*2,600.00 F
59	1		<b>*AIR INTERCOOLER INTAKE DUCT</b> (WCP)	Crumpled	210.00 F	*210.00 F
60	1		<b>*AIR INTERCOOLER HOSE - INLET</b> (WCP)	Crumpled	450.00 F	*450.00 F
61	1		<b>*AIR INTERCOOLER HOSE - OUTLET</b> (WCP)	Crumpled	450.00 F	*450.00 F
62	1		<b>*AIR CON CONDENSER</b> (WCP)	Serviceable	1,600.00 F	*- F
63	1		<b>*AIR CON CONDENSER INTAKE DUCT</b> (WCP)	Serviceable	280.00 F	*- F
64	1		<b>*RADIATOR ASSY</b> (WCP)	Cracked	1,200.00 F	*1,200.00 F
65	1		<b>*FRONT WINDSHIELD ASSY</b> (WCP)	Cracked	1,250.00 F	*1,250.00 F
66	2		<b>*FRONT WINDSHIELD SIDE MOULDINGS - L/R</b> (WCP)	Serviceable	360.00 F	*- F
67	1		<b>*STEERING WHEEL</b> (WCP)	Serviceable	4,500.00 F	*- F
68	1		<b>*STEERING WHEEL S.R.S</b> (WCP)	Burst	3,500.00 F	*3,500.00 F
69	1		<b>*STEERING WHEEL CLOCK SENSOR</b> (WCP)	Jammed	750.00 F	*750.00 F
70	1		<b>*PASSENGER S.R.S</b> (WCP)	Burst	3,600.00 F	*3,600.00 F
71	1		<b>*DASHBOARD ASSY</b> (WCP)	Cracked	8,300.00 F	*8,300.00 F
72	1		<b>*S.R.S CONTROL UNIT</b> (WCP)	Necessary	2,600.00 F	*2,600.00 F
73	2		<b>*FRONT SAFETY BELTS</b> (WCP)	Jammed	1,700.00 F	*1,700.00 F
74	2		<b>*REAR SAFETY BELTS</b> (WCP)	Jammed	1,700.00 F	*1,700.00 F
75	1		<b>*SET FRONT WINDSCREEN SEALANT</b>	Necessary	80.00 FS	*50.00 FS
76	1		<b>*FRONT TYRE - RH</b>	Cut	1,200.00 FS	*380.00 FS
77	1		<b>*I.U BRACKET</b>	Necessary	30.00 FS	*10.00 FS
78	1		<b>*BOT BRAKE FLUID</b>	Necessary	50.00 FS	*20.00 FS
79	1		<b>*SET FRONT BONNET BADGE BASE</b> (WCP)	Broken	40.00 F	*40.00 F
80	1		<b>*FRONT BUMPER SIDE MOULDING - RH - TOP</b> (WCP)	Cracked	80.00 F	*80.00 F
81	1		<b>*FRONT BUMPER SIDE MOULDING - RH - CTR</b> (WCP)	Cracked	85.00 F	*85.00 F
82	1		<b>*FRONT BUMPER SIDE MOULDING - RH - LOWER</b> (WCP)	Cracked	85.00 F	*85.00 F
83	1		<b>*FRONT BUMPER LOWER SEAL COVER - RH</b> (WCP)	Crumpled	70.00 F	*70.00 F
84	1		<b>*FRONT BUMPER FOG LAMP COVER - RH</b> (WCP)	Missing	60.00 F	*60.00 F
85	1			Crumpled	185.00 F	*185.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			<b>*FRONT HEADLAMP SPRAY NOZZLE COVER - RH</b> (WCP)			
86	1		<b>*FRONT HEADLAMP SPRAY NOZZLE BRACKET</b> (WCP)	Broken	95.00 F	*95.00 F
87	1		<b>*FRONT HEADLAMP SPRAY NOZZLE JOINT</b> (WCP)	Broken	60.00 F	*60.00 F
88	1		<b>*SET FRONT HEADLAMP WIRE HARNESS</b> (WCP)	Cracked	850.00 F	*202.00 F
89	1		<b>*AIR INTERCOOLER INTAKE DUCT - RH - REAR</b> (WCP)	Cracked	380.00 F	*380.00 F
90	1		<b>*HORN HIGH TONE</b> (WCP)	Scratched	150.00 F	*150.00 F
91	1		<b>*HORN LOW TONE</b> (WCP)	Cracked	150.00 F	*150.00 F
92	1		<b>*RADIATOR AIR GUIDE</b> (WCP)	Cracked	320.00 F	*320.00 F
93	1		<b>*RADIATOR TOP PIN</b> (WCP)	Necessary	10.00 F	*10.00 F
94	1		<b>*RADIATOR TOP STOPPER</b> (WCP)	Necessary	15.00 F	*15.00 F
95	1		<b>*RADIATOR TOP BUSHING</b> (WCP)	Necessary	20.00 F	*20.00 F
96	1		<b>*RADIATOR TOP BRACKET</b> (WCP)	Bent	30.00 F	*30.00 F
97	1		<b>*TURBO CUT OFF VALVE - RH</b> (WCP)	Crumpled	180.00 F	*180.00 F
98	1		<b>*TURBO CUT OFF VALVE HOSE</b> (WCP)	Cracked	200.00 F	*200.00 F
99	1		<b>*FRONT FENDER PROTECTOR</b> (WCP)	Missing	180.00 F	*180.00 F
100	1		<b>*SET FRONT FENDER WHEEL ARCH GARNISH CLIP</b> (WCP)	Necessary	50.00 F	*50.00 F
101	1		<b>*WASHER TANK NECK SEAL</b> (WCP)	Necessary	15.00 F	*15.00 F
102	1		<b>*WASHER TANK CAP</b> (WCP)	Necessary	25.00 F	*25.00 F
103	1		<b>*CRASH SENSOR</b> (WCP)	Necessary	380.00 F	*380.00 F
104	1		<b>*SUN VISOR - LH</b> (WCP)	Not Necessary	750.00 F	*- F
105	1		<b>*BATTERY TERMINAL</b> (WCP)	Shorted	150.00 F	*150.00 F
106	1		<b>*BATTERY FUSE</b> (WCP)	Shorted	450.00 F	*450.00 F
107	2		<b>*FRONT BONNET LOGO BASE NUT</b> (WCP)	Necessary	10.00 F	*10.00 F
108	1		<b>*FRONT WHEEL HUB - RH</b> (WCP)	Damaged	500.00 F	*500.00 F
109	1		<b>*FRONT HEADLAMP CONTROL UNIT - RH</b> (WCP)	Malfunction	400.00 F	*400.00 F
110	1		<b>*FRONT HEADLAMP CONTROL UNIT COVER</b> (WCP)	Deformed	40.00 F	*40.00 F
111	1		<b>*FRONT HEADLAMP FAN MOTOR - RH</b> (WCP)	Malfunction	350.00 F	*350.00 F
112	1		<b>*FRONT HEADLAMP FAN MOTOR COVER</b> (WCP)	Deformed	40.00 F	*40.00 F
113	1		<b>*FRONT HEADLAMP BACK COVER - RH</b> (WCP)	Deformed	40.00 F	*40.00 F

Report was unsubmitted during this print-out.
---

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
114	1		*FRONT WIPER NECK CAP (WCP)	Missing	20.00 F	*20.00 F
115	1		*AIR CLEANER HOSE LOWER JOINT - RH (WCP)	Deformed	120.00 F	*120.00 F
116	1		*TURBO PRESSURE HOSE (WCP)	Deformed	320.00 F	*320.00 F
117	1		*AIR PRESSURE HOSE (WCP)	Deformed	130.00 F	*130.00 F
118	1		*AIR PRESSURE PIPE (WCP)	Bent	125.00 F	*125.00 F
119	1		*AIR BAG WIRE (WCP)	Activated	185.00 F	*185.00 F
120	1		*BATTERY FUSE (WCP)	Damaged	55.00 F	*55.00 F
121	1		*AIR INTERCOOLER INTAKE DUCT (WCP)	Serviceable	210.00 F	*- F

F=Franchise part. S=SpcNett.

<b>Sub Total (\$)</b>	<b>91,525.00</b>	<b>69,472.00</b>
<b>+ Margin on L,N Items 10.00/10.00% (\$)</b>	9,016.50	6,901.20
<b>Total Parts (\$)</b>	<b>100,541.50</b>	<b>76,373.20</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK FRONT ELECTRICAL WIRING	New	180.00	30.00
2	TOWING CHARGES	New	200.00	70.00
3	TO REMOVE, REFIX FRONT UNDERCARRIAGE	New	650.00	200.00
4	TO CHECK WHEEL ALIGNMENT	New	120.00	40.00
5	TO REMOVE, REINSTALL & RESET A.B.S BRAKE SYSTEM	New	200.00	40.00
6	TO REMOVE, REFIX FRONT A/C CONDENSER & REFILL A/C GAS	New	180.00	80.00
7	TO REMOVE, REFIX FRONT DASHBOARD	New	450.00	180.00
8	TO DIAGNOS, ERASE FAULT MEMORY AFTER REPAIR }	New	450.00	250.00
9	TO REMOVE, REFIX & RESET S.R.S SYSTEMS }	New	580.00	0.00
10	TO RESPRAY PAINTING AND ETC	New	2,000.00	1,000.00
11	PANEL BEATING, CUT, WELD REMOVE & REPLACING ABOVE PARTS	New	3,000.00	1,300.00
			<b>Gross Labour Cost (\$\$)</b>	<b>3,190.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >