

REF: CS/C7120002654/ Evf302

Special Instruction:

Surveyor: Five

ASSIGNMENT (Office)

From (Person): Adeline Chng

of 671

Date/Time: 17.2.2020 10:10 a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

Sk W 8348T

Insured:

SSJ 11592

at Workshop m/s 60h Lee Hwa

Tel:

91454773

of BIC 5037 AMK AC 2 4101-285

Policy No: DMPCSR30753213000

Claim No: SNM 2012 200825/ SJJ 11592/ ADCUAB

Sum Insured:

Process

Make of Veh:
(Client's Record)

D.O.A. 13/21/2020

CA / REV / REP. / REV 24 HRS

$\ln p''$

Date/Time: 12/11/20 11:49 AM

Person Contacted:

Mr. Cui h

H.O.D. Soderstrom

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLW 32437 - X
	SLJ 11572 - X

ASS. REC. BY:

Steve

REF:

C11

ASSIGNMENT

From:

Date:

17/2/20

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SKW 8348T

at Workshop m/s

Goh Lee Hwa

of

BIL 5035 7101-351 AMK

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

myn

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKW 8348T

Yr Regn:

18/11/15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Vezel

C.C.

1496

Colour:

Red

A/C:

Insured / Std / NI / NA

Sp. Reading

78621

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

RUI-1195154

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

7

BS / DUN / EXNOVA / GY / FS / LIZA / MID / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

13/2/20

D.O.I.

17/2/20

Survey held at:

Goh Lee Hwa Automobile

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV-SSK

PV-39,502

NV-15,498

RECEIVED 24 FEB 2020

14/2/20

Finish \$8350, 9 days (A/Prod) (Red 12,626.70, 60%W)

Date/Time, File Pass to?



Prel. Report

1)



Final Report

Date/Time, File Return to?

2) 24/2 - typist

Days Of Repair:

9

Resurvey No. of Trip:

2

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

220

Transportation:

\$ + RS \$

Photos

Others

TOTAL

220

Report Format:

menmen

Lump Sum / I.B.I. (\$

8350/-

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Feb 2020		17 Feb 2020 10:22 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	TAN LYE LYE ROBERT, ID: S1466506D		
Vehicle Reg. No.:	SKW8348T	Date of Loss:	13/02/2020 13:00 - :59
Claim Type:	TP / SNM20D200823C02	Policy/Cover Note No.:	DMPCSN30755218000
Vehicle Reg. No. (Insured):	SJJ1159Z	Policy No. (Claimant):	5104550535-01
		Excess:	S\$750.00
Repairer:	Goh Lee Hwa Automobile Pte Ltd (HQ) Block 5033 Ang Mo Kio Industrial Park 2 #01-255, 569536 Ang Mo Kio - Tel: 64825168		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Adeline Chng Pei Wen]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 26/02/2020]		
Adj Asg. Remarks:	survey revert		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Summer Lee (LKK Auto)

From: Adeline Chng <adeline.chng@sg.cntaiping.com>
Sent: Monday, 17 February, 2020 10:10 AM
To: 'assignments'
Cc: Chee So Chow; Kuru & Co; Claims Dept of CTI
Subject: RE: OUR REF :SNM20D200823/SJJ1159Z/ADELINE & YOUR REF: L20.0221.cj(PRI-1) //ACCIDENT INVOLVING SKW 8348T & SJJ 1159Z ON 13/02/2020 ALONG ANG MO KIO AVENUE 3 NOTIFICATION OF ACCIDENT AND PRE-REPAIR SURVEY

Without Prejudice

Dear Lkk

Please refer to below email and liaise with Third Party workshop accordingly.

Thank you.

Adeline Chng
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6155 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

From: Kuru & Co [mailto:kurulegal@yahoo.com.sg]
Sent: Monday, 17 February 2020 9:07 AM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Adeline Chng <adeline.chng@sg.cntaiping.com>
Cc: Chee So Chow <sochow.chee@sg.cntaiping.com>
Subject: OUR REF :SNM20D200823/SJJ1159Z/ADELINE & YOUR REF: L20.0221.cj(PRI-1) //ACCIDENT INVOLVING SKW 8348T & SJJ 1159Z ON 13/02/2020 ALONG ANG MO KIO AVENUE 3 NOTIFICATION OF ACCIDENT AND PRE-REPAIR SURVEY

Dear Sirs

Our client is agreeable to the following surveyor as the SJE: **Kenneth Kong - LKK Auto Consultants Pte Ltd**

Please arrange for your surveyor to survey our client's vehicle at the following address:

GOH LEE HWA AUTOMOBILE PTE LTD
Blk 5033 Ang Mo Kio Ind Pk 2
#01-255

Singapore 569536

Contact: **Mr Quah/9145 4773**

Please instruct your surveyor to conduct the pre-repair survey **immediately** and complete the pre-repair survey within 2 working days of his appointment.

Kindly let us have the pre-repair and/or post repair survey report upon completion of the survey.

As solicitors on record, our client shall look to you for payment of our legal costs plus disbursements should you reach a direct settlement with our client's repairer.

Regards

Irene

Kuru & Co

150 South Bridge Road

#04-06 Fook Hai Building

Singapore 058727

Tel: 6532 2009

Fax: 6532 2007

CONFIDENTIALITY CAUTION: This message is intended for the addressee(s) only and may contain confidential information and/or may be subjected to legal privilege. If you have received in error, please notify us immediately by return email, delete this message and you shall not disseminate, distribute or copy any information contained herein.

On Friday, 14 February 2020, 5:23:16 pm SGT, Adeline Chng <adeline.chng@sg.cntaiping.com> wrote:

Without Prejudice

Dear Sirs

We refer to the above matter.

Attached PRS letter for your next action.

Thank you.

Adeline Chng

Executive

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6155 | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

From: Claims Dept of CTI

Sent: Friday, 14 February 2020 4:25 PM

To: Adeline Chng <adeline.chng@sg.cntaiping.com>; kurulegal@yahoo.com.sg

Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>

Subject: OUR REF :SNM20D200823/SJJ1159Z/ADELINE & YOUR REF: L20.0221.cj(PRI-1) //ACCIDENT INVOLVING SKW 8348T & SJJ 1159Z ON 13/02/2020 ALONG ANG MO KIO AVENUE 3 NOTIFICATION OF ACCIDENT AND PRE-REPAIR SURVEY

Dear Adeline,

Please conduct PRS for SKW8348T.

Note : officer in charge – Adeline 63896155.

*** Kindly quote our reference number when replying.

Thank you,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Kuru & Co <kurulegal@yahoo.com.sg>
Sent: Friday, February 14, 2020 9:52 AM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Ben Tang <Ben.Tang@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>
Subject: Our ref: L20.0221.cj(PRI-1) //ACCIDENT INVOLVING SKW 8348T & SJJ 1159Z ON 13/02/2020 ALONG ANG MO KIO AVENUE 3 NOTIFICATION OF ACCIDENT AND PRE-REPAIR SURVEY

Dear Sirs


ACCIDENT INVOLVING SKW 8348T & SJJ 1159Z ON 13/02/2020
ALONG ANG MO KIO AVENUE 3
NOTIFICATION OF ACCIDENT AND PRE-REPAIR SURVEY

We act for **TAN KIM TECK**, whose vehicle registration number **SKW 8348T** was damaged in the above accident.

A copy of the police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within **2 working days** of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle.

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.



Regards

Irene

Kuru & Co
150 South Bridge Road
#04-06 Fook Hai Building
Singapore 058727
Tel: 6532 2009

Fax: 6532 2007

CONFIDENTIALITY CAUTION: This message is intended for the addressee(s) only and may contain confidential information and/or may be subjected to legal privilege. If you have received in error, please notify us immediately by return email, delete this message and you shall not disseminate, distribute or copy any information contained herein.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	506D
Vehicle Details	
Vehicle No.:	SKW8348T
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Feb 2020
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	L15B4025169
Chassis No.:	RU11105154
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$19,736.00
Original Registration Date:	18 Nov 2015
First Registration Date:	18 Nov 2015
Transfer Count:	0
Actual ARF Paid:	\$9,736.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Nov 2025
PARF Rebate Amount:	\$7,302.00
Intended COE Rebate Details	
COE Expiry Date:	17 Nov 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,001.00
COE Rebate Amount:	\$32,200.00
Total Rebate Amount:	\$39,502.00

The information contained herein is correct as at 17 Feb 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/02/2020 09:56
Date Of Accident	13/02/2020 13:30
Exact Location Of Accident	FROM CTE SLIP ROAD TOWARDS ANG MO KIO AVE 3
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKW8348T
Insured/Policyholder	
Name Of Registered Owner	TAN LYE LYE ROBERT
NRIC No	SXXXX506D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-83488858
Alternative Phone No	OFFICE-83488858

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5104550535-01
Cover Note Number	

Driver

Name of Driver	TAN KIM TECK
NRIC No	SXXXX656A
Date Of Birth	25/05/1966
Occupation	INDOOR
Date Of Driving Pass	06/11/1986
Driving Experience	33 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83488858
Fax Number	
Contact Number	OFFICE-83488858
Email Address	STARAUTO28@GMAIL.COM

Address	BLK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-255 SINGAPORE
Postcode	569536
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	FRIEND
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	HOUGANG NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 60 HOUGANG AVE 9 . POSTCODE: 538775 . COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4890999 - FAX NO: 63128989
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO FOOTAGE SENT TO NTUC
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJJ1159Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	JOSHUA RAJAN S/O JONSON
NRIC/Passport Number	SXXXX720Z
Contact Number	85938315
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	TAN KIM TECK
Approximate Age	53
Injuries Sustain	REFER POLICE REPORT (5 DAYS OF MC)
Injured person in which vehicle?	SKW8348T
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	APT BLK 836 HOUGANG CENTRAL #10-549 SINGAPORE
Postcode	530836

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

A) 9KW 83 8T
B) SJS 1159 Z



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

AT 13/02/20 TIME 1339, I WAS ALONG ANG MO KIO SLIP ROAD TOWARDS ANG MO KIO AVE 3 TOWARDS ANG MO KIO INDUSTRIAL PARK 2 (MAIN ROAD). FRONT VEH STOP, I STOP. BEFORE I PROCEED DRIVE OUT TO MAIN ROAD, ON COMING MAIN ROAD COMES A BLACK CAR TOWARDS MY DIRECTION, SO I STOP FOR THE BLACK CAR TO CLEAR THE WAY. SUDDENLY I WAS HIT FROM BEHIND CAR (B) SJS 1159 Z. HAVE VIDEO FOOTAGE.

I ALSO WENT SEE DOCTOR & WAS GIVEN 5 DAYS MC AT THIS MOMENT.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20200213/2105

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

1 of 3

Report No. T/20200213/2105

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 13/02/2020 18:10	Vide Report No.:	Station Diary No.: 101
--	------------------	---------------------------

Informant's Particulars

Name of Informant: TAN KIM TECK			Address: APT BLK 836 HOUGANG CENTRAL #10-549 SINGAPORE 530836	
ID Type / ID No.: NRIC NO / S1774658A			Contact No.:	Mobile: 83488858
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 53	Date of Birth: 25/05/1966	Type of Informant: Driver	
Race: Chinese			Language: English	Institution / School Name:
Occupation: Company director			Driving Licence Information: Class: 2B,3	Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 13/02/2020 13:30	Type of Location: Bend
Location: Along Road 1 ANG MO KIO AVENUE 3				
Slip road before Ang Mo Kio Ave 3, next to Ang Mo Kio Industrial Park 2				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SJJ1159Z	Car					0
SKW8348T	Car	HONDA	VEZEL 1.5X CVT	Red	Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20200213/2105

2 of 3

Police Station Of Origin:

Hougang N.P.C

60 Hougang Avenue 9 SINGAPORE 538775

Tel No: 1800-4890999

Report No. T/20200213/2105

CONTINUATION OF REPORT

Driver			
Name	JOSHUA RAJAN S/O JONSON	ID No.	S8742720Z
Related Vehicle	SJJ1159Z (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	TAN KIM TECK	ID No.	S1774656A
Related Vehicle	SKW8348T (Car)	Contact No.	83488858
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	05	Degree of Injury	Slight

Brief Details.

On 13/02/2020 at about 1330hrs, I was turning left at the slip road before Ang Mo Kio Avenue 3, next to Ang Mo Kio Industrial Park 2. I stop before the stop line as there was oncoming traffic along the main road. All of a sudden, I felt an impact from the rear of my car. I discovered that it was another car that collided onto the rear of my car. I have rear-facing CCTV which captured footage of the incident. There was no need for ambulance or police and after we exchanged particulars and took some photos, I left the scene. Later on, I went to see a doctor for my injuries (stiff neck and shoulders and giddiness) and received 5 days MC. I also submitted the insurance claim and the footage to the insurance company.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999



T/20200213/2105

3 of 3

Report No. T/20200213/2105

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
F /
Sgt 2 MOHAMED ALI S/O MUBARAK HUSSAIN

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / AEIT /
SI MOHAMAD ZULFAZDLI BIN ABDULLAH
Contact No.: 65476204

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:
13/02/2020 18:10

Classification Of Case:

GOH LEE HWA AUTOMOBILE PTE LTD

Block 5033 Ang Mo Kio Industrial Park 2

#01-255 Singapore 569536

Tel No: (65) 6482 5168

Fax No. (65) 6482 4452

Co.reg no. 200808259H

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Reference No: 140220**Date: 14.02.2020****Tan Lye Lye Robert****Blk 419 #03-271 Pasir Ris Drive 6****Singapore 510419****Honda Vezel 1.5X CVT****Estimated Repair Cost for Vehicle Reg. No: SKW 8348 T****REPLACEMENT OF DAMAGED PANELS / PARTS**

1 Pc. Tail Gate	✓	DD		1,280.00	1100✓
1 Pc. Tail Gate Top Spoiler	×	NAI		699.80	X
10 Pcs. Tail Gate Top Spoiler Clips	×	NAI	@ 8.00	80.00	X
2 Pcs. Tail Gate Hinger	×	NAI	@ 65.00	130.00	X
2 Pcs. Tail Gate Absorber	×	NAI / Jemmed	@ 410.00	820.00	600✓
1 Pc. Tail Gate Auto Absorber Switch		DIS		288.00	175✓
1 Pc. Tail Gate Lock Assy	✓	DT		299.60	269✓
1 Pc. Tail Gate Inner Garnish	✓	CRA		598.80	276✓
10 Pcs. Tail Gate Inner Garnish Clips	✓	M	@ 6.00	60.00	70✓
1 Pcs. Tail Gate Windscreen Moulding	✓	M		299.80	277✓
2 Pcs. Tail Gate Windscreen Seal Top/Bottom	×	NAI	@ 80.00	160.00	X
1 Pc. Tail Gate Windscreen Sealant	✓	M		180.00	40✓
1 Pc. Tail Gate Logo	✓	M		32.30	✓
1 Pc. Tail Gate Vezel Emblem	✓	M		59.90	✓
1 Pc. Tail Gate Honda Emblem	✓	M		60.50	✓
2 Pcs. Tail Gate Lamp Assy	✓	CUT	@ 488.00	976.00	756✓
2 Pcs. Tail Gate Lamp Chrome	✓	M	@ 210.00	420.00	300✓
2 Pcs. Tail Gate No. Plate Lamp	×	NAI	@ 92.00	184.00	X
1 Pc. Tail Gate Centre Handle Opener	×	NAI		199.20	X
1 Pc. Tail gate Centre Handle Garnish	×	NAI		290.00	X
2 Pcs. Tail Gate Stopper	×	NAI	@ 28.00	56.00	X
2 Pcs. Tail Lamp Assy	×	CRA	@ 493.60	987.20	900✓
2 Pcs. Tail Lamp Chrome	×	NAI	@ 180.00	360.00	X
1 Pc. Rear Bumper	✓	DD		565.60	✓
1 Pc. Rear Bumper Beam	×	NAI		282.00	X
2 Pcs. Rear Bumper Bracket	×	NAI	@ 123.60	247.20	X

GOH LEE HWA AUTOMOBILE PTE LTD

Block 5033 Ang Mo Kio Industrial Park 2

#01-255 Singapore 569536

Tel No: (65) 6482 5168

Fax No. (65) 6482 4452

Co.reg no. 200808259H

1 Pc. Rear Bumper Centre Retainer	CR ? X NN	199.00 X	
1 Pc. Rear Bumper Stop Panel	X CR NN	398.00 X	
2 Pcs. Rear Bumper Reflector	? / CRA @ 158.50	317.00 /	
1 Set Rear Bumper Reverse Sensor	/ SL	388.00 200 /	
12 Pcs. Rear Bumper Clips	/ MC @ 6.00	72.00 30 /	
2 Pcs. Rear Bumper Side Pad	? / DR @ 156.80	313.60 /	
2 Pcs. Rear Bumper Side Retainer	/ DR @ 98.60	197.20 /	
10 Pcs. Rear Bumper Side Pad Clips	? / MC @ 6.00	60.00 20 /	
2 Pcs. Rear Fender Wheel Garnish	(RH) / DR @ 186.20	372.40 /	
20 Pcs. Rear Fender Wheel Garnish Clips	/ MC @ 6.00	120.00 30 /	
1 Pc. Rear End Panel	/ DP	499.30 /	
1 Pc. Rear End Panel Garnish	/ CR	228.50 /	
1 Pc. Rear End Panel Weather Strip	/ CR	299.00 /	
1 Pc. Rear Floor Spare Panel	X / R DO	1,098.00 /	
1 Pc. Rear Floor Board	/ CR	495.80 200 /	
1 Pc. Rear Spare Panel Garnish	? / DIS	310.00 197 /	
10 Pcs. Rear Spare Panel Garnish Clips	? X NN @ 6.00	60.00 X	
1 Pc. Rear Exhaust Muffler	X NN	598.00 X	
2 Pcs. Rear Exhaust Mounting	X NN @ 68.00	136.00 X	
1 Pc. Rear Exhaust Chrome Pipe	/ CH	196.20 /	

9619.50
- 20%
7695.60

Total (Panels / Parts): 15,973.90 (SGD)

LABOR CHARGES

To check wiring & remove refit camera, parking Sensor & reinstall.	200.00 50
To remove & refit rear windscreen.	180.00 120
To remove & refit interior garnish, side board, Cushion & all accident affected area.	280.00 50 100
To remove & refit exhaust system.	200.00 X

GOH LEE HWA AUTOMOBILE PTE LTD

Block 5033 Ang Mo Kio Industrial Park 2

#01-255 Singapore 569536

Tel No: (65) 6482 5168

Fax No. (65) 6482 4452

Co.reg no. 200808259H

To knocking, welding, straightening repair & renew All accident damage affected area.	1,600.00 800 1200
To respray painting inside, outside & all accident Damage affected area & parts.	1,800.00 700 800
To rust proof all accident affected area.	200.00 50

Total (Labor Charges):	4,460.00 (SGD) 2370 2370
-------------------------------	--

TOTAL COST SUMMARY

PANELS / PARTS	P - 7695.60	15,973.90
LABOR CHARGES	L - 2370	4,460.00
	Supp - 421.60	
	10437.20	
	L/S - 8349.76	
	= 8350	
	Grand Total:	20,433.90 (SGD)
		20,976.70 ✓

We shall be glad if you can forward the payment at your early convenience.

Cheque should be crossed and make payable to 'GOH LEE HWA AUTOMOBILE PTE LTD'

Alfred Quah

GOH LEE HWA AUTOMOBILE PTE LTD

Steve (LKK)
83228813

WL 16/6L

L/S

RJ AL SH

17/2/20, 12:00 pm

9 26 days

GOH LEE HWA AUTOMOBILE PTE LTD

- Block 5033 Ang Mo Kio Industrial Park 2
- #01-255 Singapore 569536
- Tel No: (65) 6482 5168
- Fax No. (65) 6482 4452
- Co.reg no. 200808259H

Reference No: 140220**Date: 14.02.2020**

Tan Lye Lye Robert
Blk 419 #03-271 Pasir Ris Drive 6
Singapore 510419
Honda Vezel 1.5X CVT

Estimated Repair Cost for Vehicle Reg. No: SKW 8348 T**REPLACEMENT OF DAMAGED PANELS / PARTS**

1 Pc. Tail Gate	✓ DO		1,280.00	1100 ✓
1 Pc. Tail Gate Top Spoiler	✓		699.80	X
10 Pcs. Tail Gate Top Spoiler Clips	✓	@ 8.00	80.00	X
2 Pcs. Tail Gate Hinger	✓	@ 65.00	130.00	X
2 Pcs. Tail Gate Absorber	✓ ? noisy	@ 410.00	820.00	600 ✓
1 Pc. Tail Gate Auto Absorber Switch	✓ ? DIS		288.00	175 ✓
1 Pc. Tail Gate Lock Assy	✓ OT		299.60	269 ✓
1 Pc. Tail Gate Inner Garnish	✓ CR4		598.80	276 ✓
10 Pcs. Tail Gate Inner Garnish Clips	✓ MC	@ 6.00	60.00	90 ✓
1 Pcs. Tail Gate Windscreen Moulding	✓ MC		299.80	227 ✓
2 Pcs. Tail Gate Windscreen Seal Top/Bottom	✓ X	@ 80.00	160.00	X
1 Pc. Tail Gate Windscreen Sealant	✓ MC		180.00	40 ✓
1 Pc. Tail Gate Logo	✓ MC		32.30	✓
1 Pc. Tail Gate Vezel Emblem	✓ MC		59.90	✓
1 Pc. Tail Gate Honda Emblem	✓ MC		60.50	✓
2 Pcs. Tail Gate Lamp Assy	✓ ? cut ✓	@ 488.00	976.00	750 ✓
2 Pcs. Tail Gate Lamp Chrome	✓ MC	@ 210.00	420.00	300 ✓
2 Pcs. Tail Gate No. Plate Lamp	✓	@ 92.00	184.00	X
1 Pc. Tail Gate Centre Handle Opener	✓		199.20	X
1 Pc. Tail gate Centre Handle Garnish	✓ ? X		290.00	X
2 Pcs. Tail Gate Stopper	✓	@ 28.00	56.00	X
2 Pcs. Tail Lamp Assy	✓ ? gra ✓	450 @ 493.60	987.20	900 ✓
2 Pcs. Tail Lamp Chrome	✓	@ 180.00	360.00	X
1 Pc. Rear Bumper	✓ DO		565.60	✓
1 Pc. Rear Bumper Beam	✓		282.00	X
2 Pcs. Rear Bumper Bracket	✓	@ 123.60	247.20	X

GOH LEE HWA AUTOMOBILE PTE LTD

Block 5033 Ang Mo Kio Industrial Park 2

#01-255 Singapore 569536

Tel No: (65) 6482 5168

Fax No. (65) 6482 4452

Co.reg no. 200808259H

1 Pc. Rear Bumper Centre Retainer	1 1 ? X	199.00 X
1 Pc. Rear Bumper Stop Panel	X MIS ✓	398.00 X
2 Pcs. Rear Bumper Reflector	? CRA ✓	317.00 ✓
1 Set Rear Bumper Reverse Sensor	✓ SL	388.00 200 ✓
12 Pcs. Rear Bumper Clips	✓ MC	72.00 30 ✓
2 Pcs. Rear Bumper Side Pad	✓ ? BR ✓	313.60 ✓
2 Pcs. Rear Bumper Side Retainer	✓ OR	197.20 ✓
10 Pcs. Rear Bumper Side Pad Clips	? NG ✓	60.00 20 ✓
2 Pcs. Rear Fender Wheel Garnish	(PH) ✓ OR	372.40 ✓
20 Pcs. Rear Fender Wheel Garnish Clips	✓ MC	120.00 30 ✓
1 Pc. Rear End Panel	✓ DP	499.30 ✓
1 Pc. Rear End Panel Garnish	✓ CR4	228.50 ✓
1 Pc. Rear End Panel Weather Strip	✓ CR4	299.00 ✓
1 Pc. Rear Floor Spare Panel	X ✓ DD ✓	1,098.00 ✓
1 Pc. Rear Floor Board	✓ CR4	495.80 240 ✓
1 Pc. Rear Spare Panel Garnish	? X DIS ✓	310.00 197 ✓
10 Pcs. Rear Spare Panel Garnish Clips	? X	60.00 X
1 Pc. Rear Exhaust Muffler	X	598.00 X
2 Pcs. Rear Exhaust Mounting	X	136.00 X
1 Pc. Rear Exhaust Chrome Pipe	✓ CH	196.20 ✓

Total (Panels / Parts):**15,973.90 (SGD)****LABOR CHARGES**

To check wiring & remove refit camera, parking Sensor & reinstall.

200.00 50

To remove & refit rear windscreen.

180.00 120

To remove & refit interior garnish, side board, Cushion & all accident affected area.

280.00 50 100

To remove & refit exhaust system.

200.00 X

GOH LEE HWA AUTOMOBILE PTE LTD

Block 5033 Ang Mo Kio Industrial Park 2

#01-255 Singapore 569536

Tel No: (65) 6482 5168

Fax No. (65) 6482 4452

Co.reg no. 200808259H

To knocking, welding, straightening repair & renew All accident damage affected area.	1,600.00	800	1200
To respray painting inside, outside & all accident Damage affected area & parts.	1,800.00	700	800
To rust proof all accident affected area.	200.00	50	2320

Total (Labor Charges): 4,460.00 (SGD)**TOTAL COST SUMMARY**PANELS / PARTS
LABOR CHARGES

P- 7695-60
L- 2320
Sum- 421-60
10,437-20

15,973.90
4,460.00**Grand Total:****20,433.90 (SGD)**

L/S- 8349.76
= 8350

We shall be glad if you can forward the payment at your early convenience.

Cheque should be crossed and make payable to 'GOH LEE HWA AUTOMOBILE PTE LTD'

Steve (LKK)
83228813

WL 16/6L
L/S

RJ AL SH

17/2/20, 12.00 pm

9 1/2 days

Alfred Quah

GOH LEE HWA AUTOMOBILE PTE LTD

GOH LEE HWA AUTOMOBILE PTE LTD

Block 5033 Ang Mo Kio Industrial Park 2
#01-255 Singapore 569536
Tel No: (65) 6482 5168
Fax No. (65) 6482 4452
Co.reg no. 200808259H

Reference No: 140220

Date: 14.02.2020

Tan Lye Lye Robert
Blk 419 #03-271 Pasir Ris Drive 6
Singapore 510419
Honda Vezel 1.5X CVT

Supplementary Repair Cost for Vehicle Reg. No: SKW 8348 T

REPLACEMENT OF DAMAGED PANELS / PARTS

1 Pc. Buzzer Assy	✓ BR ✓	145.80	130 - 206 104 ✓
Grand Total:		<u>145.80 (SGD)</u>	

We shall be glad if you can forward the payment at your early convenience.

Cheque should be crossed and make payable to 'GOH LEE HWA AUTOMOBILE PTE LTD'

mfh
GOH LEE HWA AUTOMOBILE PTE LTD

18/2/20
Supplementary

1pc Spare Tyre Tool Box \$197 / cru
1ect Spare Tyre Panel Insulator. \$200 / rrc

*397
- 206
191
191 + 104 = 295*

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Feb 2020		17 Feb 2020 10:22 Edit Adj Rpt	S\$8,350.00 Edit Estimates	S\$8,350.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	Co. Reg. No.: -								
Main Claimant:	TAN LYE LYE ROBERT, ID: S1466506D								
Vehicle Reg. No.:	SKW8348T	Date of Loss:	13/02/2020 13:00 - :59 [50 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM20D200823C02	Policy/Cover Note No.:	DMPCSN30755218000						
Vehicle Reg. No. (Insured):	SJJ1159Z	Policy No. (Claimant):	5104550535-01						
		Excess:	S\$750.00						
Repairer:	Goh Lee Hwa Automobile Pte Ltd (HQ) Block 5033 Ang Mo Kio Industrial Park 2 #01-255, 569536 Ang Mo Kio - Tel: 64825168								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Adeline Chng Pei Wen]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 26/02/2020]								
Adj Asg. Remarks:	survey revert								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKW8348T (SNM20D200823C02)
[SJJ1159Z]
TP
TAN LYE LYE ROBERT
Feb 13 2020 1:00PM
[-]
Goh Lee Hwa Automobile Pte Ltd

Upload Documents



















































Upload Photos











































Compose New Letter

View

View in Browser

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	14/02/20 10:09	Accident Statement	Load HTM	<input checked="" type="checkbox"/>
<div> <div>Photos/Images</div> <div>3 per page</div> <div><input checked="" type="checkbox"/></div> </div>				
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	14/02/20 10:07	Accident Photo <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>
2	14/02/20 10:07	Accident Photo <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>
3	14/02/20 10:07	Accident Photo <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>
4	14/02/20 10:07	Accident Photo <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>
5	14/02/20 10:07	Accident Photo <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>
6	14/02/20 10:07	Accident Photo <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>
7	14/02/20 10:07	Accident Photo <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>
8	14/02/20 10:07	Accident Photo <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>
9	14/02/20 10:07	Accident Photo <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/02/20 19:35	General View	Load JPG	<input checked="" type="checkbox"/>
2	17/02/20 19:35	General View	Load JPG	<input checked="" type="checkbox"/>
3	17/02/20 19:35	General View	Load JPG	<input checked="" type="checkbox"/>
4	17/02/20 19:35	General View	Load JPG	<input checked="" type="checkbox"/>
5	17/02/20 19:35	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
6	17/02/20 19:35	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
7	17/02/20 19:35	General View	Load JPG	<input checked="" type="checkbox"/>
8	17/02/20 19:35	General View	Load JPG	<input checked="" type="checkbox"/>
9	17/02/20 19:35	General View	Load JPG	<input checked="" type="checkbox"/>
10	17/02/20 19:35	General View	Load JPG	<input checked="" type="checkbox"/>
11	17/02/20 19:35	General View	Load JPG	<input checked="" type="checkbox"/>
12	17/02/20 19:35	General View	Load JPG	<input checked="" type="checkbox"/>
13	17/02/20 19:35	General View	Load JPG	<input checked="" type="checkbox"/>
14	17/02/20 19:35	General View	Load JPG	<input checked="" type="checkbox"/>
15	17/02/20 19:35	General View	Load JPG	<input checked="" type="checkbox"/>
16	17/02/20 19:35	General View	Load JPG	<input checked="" type="checkbox"/>
17	17/02/20 19:35	General View	Load JPG	<input checked="" type="checkbox"/>
18	17/02/20 19:35	General View	Load JPG	<input checked="" type="checkbox"/>
19	17/02/20 19:35	General View	Load JPG	<input checked="" type="checkbox"/>
20	17/02/20 19:35	General View	Load JPG	<input checked="" type="checkbox"/>
21	17/02/20 19:35	General View	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
22	17/02/20 19:35	General View		<input checked="" type="checkbox"/>
23	17/02/20 19:35	General View		<input checked="" type="checkbox"/>
24	17/02/20 19:35	General View		<input checked="" type="checkbox"/>
25	17/02/20 19:35	General View		<input checked="" type="checkbox"/>
26	17/02/20 19:35	General View		<input checked="" type="checkbox"/>
27	17/02/20 19:35	General View		<input checked="" type="checkbox"/>
28	17/02/20 19:35	General View		<input checked="" type="checkbox"/>
29	17/02/20 19:36	General View		<input checked="" type="checkbox"/>
30	17/02/20 19:36	General View		<input checked="" type="checkbox"/>
31	17/02/20 19:36	General View		<input checked="" type="checkbox"/>
32	17/02/20 19:36	General View		<input checked="" type="checkbox"/>
33	17/02/20 19:36	General View		<input checked="" type="checkbox"/>
34	17/02/20 19:36	General View		<input checked="" type="checkbox"/>
35	17/02/20 19:36	General View		<input checked="" type="checkbox"/>
36	17/02/20 19:36	General View		<input checked="" type="checkbox"/>
37	17/02/20 19:36	General View		<input checked="" type="checkbox"/>
38	17/02/20 19:36	General View		<input checked="" type="checkbox"/>
39	17/02/20 19:36	General View		<input checked="" type="checkbox"/>
40	17/02/20 19:36	General View		<input checked="" type="checkbox"/>
41	17/02/20 19:36	General View		<input checked="" type="checkbox"/>
42	17/02/20 19:36	General View		<input checked="" type="checkbox"/>
43	17/02/20 19:36	General View		<input checked="" type="checkbox"/>
44	17/02/20 19:36	General View		<input checked="" type="checkbox"/>
45	17/02/20 19:36	General View		<input checked="" type="checkbox"/>
46	17/02/20 19:36	General View		<input checked="" type="checkbox"/>
47	17/02/20 19:36	General View		<input checked="" type="checkbox"/>
48	17/02/20 19:36	General View		<input checked="" type="checkbox"/>
49	17/02/20 19:36	General View		<input checked="" type="checkbox"/>
50	17/02/20 19:36	General View		<input checked="" type="checkbox"/>
51	17/02/20 19:36	General View		<input checked="" type="checkbox"/>
52	17/02/20 19:36	General View		<input checked="" type="checkbox"/>
53	17/02/20 19:36	General View		<input checked="" type="checkbox"/>
54	17/02/20 19:36	General View		<input checked="" type="checkbox"/>
55	17/02/20 19:36	General View		<input checked="" type="checkbox"/>
56	17/02/20 19:36	General View		<input checked="" type="checkbox"/>
57	17/02/20 19:36	General View		<input checked="" type="checkbox"/>
58	17/02/20 19:36	General View		<input checked="" type="checkbox"/>
59	24/02/20 08:39	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
60	24/02/20 08:39	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
61	24/02/20 08:39	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
62	24/02/20 08:39	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
63	24/02/20 08:39	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
64	24/02/20 08:39	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
65	24/02/20 08:39	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
66	24/02/20 08:39	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
67	24/02/20 08:39	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
68	24/02/20 08:39	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
69	24/02/20 08:39	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
70	24/02/20 08:39	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
71	24/02/20 08:39	Photographs of Damaged Parts		<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
72	24/02/20 08:39	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
73	24/02/20 08:39	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
74	24/02/20 08:39	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
75	24/02/20 08:39	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
76	24/02/20 08:39	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
77	24/02/20 08:39	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
78	24/02/20 08:39	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
79	24/02/20 08:39	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
80	24/02/20 08:39	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
81	24/02/20 08:39	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
82	24/02/20 08:39	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
83	24/02/20 08:39	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
84	24/02/20 08:39	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
85	24/02/20 08:39	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
86	24/02/20 08:39	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
87	24/02/20 08:39	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
88	24/02/20 08:39	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
89	24/02/20 08:39	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
90	24/02/20 08:39	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
91	24/02/20 08:39	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
92	24/02/20 08:39	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
93	24/02/20 08:39	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
94	24/02/20 08:39	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
95	24/02/20 08:39	After Repair Photo		<input checked="" type="checkbox"/>
96	24/02/20 08:39	After Repair Photo		<input checked="" type="checkbox"/>
97	24/02/20 08:39	After Repair Photo		<input checked="" type="checkbox"/>
98	24/02/20 08:39	After Repair Photo		<input checked="" type="checkbox"/>
99	24/02/20 08:40	After Repair Photo		<input checked="" type="checkbox"/>
100	24/02/20 08:40	After Repair Photo		<input checked="" type="checkbox"/>
101	24/02/20 08:40	After Repair Photo		<input checked="" type="checkbox"/>
102	24/02/20 08:40	After Repair Photo		<input checked="" type="checkbox"/>
103	24/02/20 08:40	After Repair Photo		<input checked="" type="checkbox"/>
104	24/02/20 08:40	After Repair Photo		<input checked="" type="checkbox"/>
105	24/02/20 08:40	After Repair Photo		<input checked="" type="checkbox"/>
106	24/02/20 08:41	After Repair Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	17/02/20 10:23	Pre-Repair Survey		<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	14/02/20 10:07	Sketch Plan [Linked Accident Report Documents]		<input type="checkbox"/>
2	14/02/20 10:07	Sketch Plan #2 [Linked Accident Report Documents]		<input type="checkbox"/>
3	14/02/20 10:08	Common Statement [Linked Accident Report Documents]		<input type="checkbox"/>
4	14/02/20 10:08	Common Statement [Linked Accident Report Documents]		<input type="checkbox"/>
5	14/02/20 10:08	Common Statement [Linked Accident Report Documents]		<input type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/02/20 11:58	Supplementary		<input type="checkbox"/>

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	1 per page	<input checked="" type="checkbox"/>
1	14/02/20 10:09	Accident Statement		Thumbnail Print
			Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	14/02/20 10:07	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	14/02/20 10:07	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	14/02/20 10:07	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	14/02/20 10:07	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	14/02/20 10:07	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	14/02/20 10:07	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	14/02/20 10:07	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	14/02/20 10:07	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	14/02/20 10:07	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	14/02/20 10:07	Sketch Plan	Load TIF	
2	14/02/20 10:07	Sketch Plan #2	Load TIF	
3	14/02/20 10:08	Common Statement	Load TIF	
4	14/02/20 10:08	Common Statement	Load TIF	
5	14/02/20 10:08	Common Statement	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid #ccc; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20002654/EVF3E2

Date: 27/02/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30755218000
Claimant Vehicle No :	SKW8348T	Insured Vehicle No :	SJJ1159Z
Date of Loss:	13/02/2020	Nature of Claim:	TP
		Claim No:	SNM20D200823C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKW8348T	Engine No:	L15B4025169
Make & Model:	HONDA VEZEL, 1.5 (A)	Chassis No:	RU11105154
Reg. Date:	18/11/2015 (Man. Year: 2015)	Odometer:	78621 km
Colour:	Red		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,516.70	8,117.20	8,399.50	50.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,460.00	2,320.00	2,140.00	47.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,976.70	10,437.20	10,539.50	50.24
Approved Total (Overridden) (S\$)		8,350.00		
Nett Amount (S\$)	20,976.70	8,350.00	12,626.70	60.19

INSPECTION

Date of Assignment:	17/02/2020	
Date Inspected:	17/02/2020 Inspected At:	Goh Lee Hwa Automobile Pte Ltd (HQ) Block 5033 Ang Mo Kio Industrial Park 2 #01-255 Singapore 569536
Estimated Period of Repair:	9.0 days	

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 27 Feb 2020)	
Parts: M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SKW8348T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Dented	1,280.00 F	*1,100.00 FL
2	1		*TAIL GATE TOP SPOILER	Not Necessary	699.80 F	*- FL
3	10		*TAIL GATE TOP SPOILER CLIPS	Not Necessary	80.00 F	*- FL
4	2		*TAIL GATE HINGER	Not Necessary	130.00 F	*- FL
5	2		*TAIL GATE ABSORBER	Jammed	820.00 F	*600.00 FL
6	1		*TAIL GATE AUTO ABSORBER SWITCH	Distorted	288.00 F	*175.00 FL
7	1		*TAIL GATE LOCK ASSY	Bent	299.60 F	*269.00 FL
8	1		*TAIL GATE INNER GARNISH	Crushed	598.80 F	*276.00 FL
9	10		*TAIL GATE INNER GARNISH CLIPS	Necessary	60.00 F	*20.00 FL
10	1		*TAIL GATE WINDSCREEN MOULDING	Necessary	299.80 F	*227.00 FL
11	2		*TAIL GATE WINDSCREEN SEAL TOP / BOTTOM	Not Necessary	160.00 F	*- FL
12	1		*TAIL GATE WINDSCREEN SEALANT	Necessary	180.00 F	*40.00 FL
13	1		*TAIL GATE LOGO	Necessary	32.30 F	*32.30 FL
14	1		*TAIL GATE VEZEL EMBLEM	Necessary	59.90 F	*59.90 FL
15	1		*TAIL GATE HONDA EMBLEM	Necessary	60.50 F	*60.50 FL
16	2		*TAIL GATE LAMP ASSY	Cut	976.00 F	*756.00 FL
17	2		*TAIL GATE LAMP CHROME	Necessary	420.00 F	*300.00 FL
18	2		*TAIL GATE NO. PLATE LAMP	Not Necessary	184.00 F	*- FL
19	1		*TAIL GATE CENTRE HANDLE OPENER	Not Necessary	199.20 F	*- FL
20	1		*TAIL GATE CENTRE HANDLE GARNISH	Not Necessary	290.00 F	*- FL
21	2		*TAIL GATE STOPPER	Not Necessary	56.00 F	*- FL
22	2		*TAIL LAMP ASSY	Cracked	987.20 F	*900.00 FL
23	2		*TAIL LAMP CHROME	Not Necessary	360.00 F	*- FL
24	1		*REAR BUMPER	Dented	565.60 F	*565.60 FL
25	1		*REAR BUMPER BEAM	Not Necessary	282.00 F	*- FL
26	2		*REAR BUMPER BRACKET	Not Necessary	247.20 F	*- FL
27	1		*REAR BUMPER CENTRE RETAINER	Not Necessary	199.00 F	*- FL
28	1		*REAR BUMPER STOP PANEL	Not Necessary	398.00 F	*- FL
29	2		*REAR BUMPER REFLECTOR	Cracked	317.00 F	*317.00 FL
30	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	388.00 F	*200.00 FL
31	12		*REAR BUMPER CLIPS	Necessary	72.00 F	*30.00 FL
32	2		*REAR BUMPER SIDE PAD	Broken	313.60 F	*313.60 FL
33	2		*REAR BUMPER SIDE RETAINER	Broken	197.20 F	*197.20 FL
34	10		*REAR BUMPER SIDE PAD CLIPS	Necessary	60.00 F	*20.00 FL
35	2		*REAR FENDER WHEEL GARNISH	Broken	372.40 F	*372.40 FL
36	20		*REAR FENDER WHEEL GARNISH CLIPS	Necessary	120.00 F	*30.00 FL
37	1		*REAR END PANEL	Dented	499.30 F	*499.30 FL
38	1		*REAR END PANEL GARNISH	Crushed	228.50 F	*228.50 FL
39	1		*REAR END PANEL WEATHER STRIP	Crushed	299.00 F	*299.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*REAR FLOOR SPARE PANEL	Dented	1,098.00 F	*1,098.00 FL
41	1		*REAR FLOOR BOARD	Crushed	495.80 F	*240.00 FL
42	1		*REAR SPARE PANEL GARNISH	Distorted	310.00 F	*197.00 FL
43	10		*REAR SPARE PANEL GARNISH CLIPS	Not Necessary	60.00 F	*- FL
44	1		*REAR EXHAUST MUFFLER	Not Necessary	598.00 F	*- FL
45	2		*REAR EXHAUST MOUNTING	Not Necessary	136.00 F	*- FL
46	1		*REAR EXHAUST CHROME PIPE	Cut	196.20 F	*196.20 FL
47	1		*BUZZER ASSY	Broken	145.80 F	*130.00 FL
48	1		*SPARE TYRE TOOL BOX	Crushed	197.00 F	*197.00 FL
49	1		*SPARE TYRE PANEL INSULATOR	Necessary	200.00 F	*200.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	16,516.70	10,146.50
- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	2,029.30

Total Parts (S\$)	16,516.70	8,117.20
-------------------	-----------	----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING & REMOVE REFIT CAMERA, PARKING SENSOR & REINSTALL	New	200.00	50.00
2	TO REMOVE & REFIT REAR WINDSCREEN	New	180.00	120.00
3	TO REMOVE & REFIT INTERIOR GARNISH, SIDE BOARD, CUSHION & ALL ACCIDENT AFFECTED AREA	New	280.00	100.00
4	TO REMOVE & REFIT EXHAUST SYSTEM	New	200.00	0.00
5	TO KNOCKING, WELDING, STRAIGHTENING REPAIR & RENEW ALL ACCIDENT DAMAGE AFFECTED AREA	New	1,600.00	1,200.00
6	TO RESPRAY PAINTING INSIDE, OUTSIDE & ALL ACCIDENT DAMAGE AFFECTED AREA & PARTS	New	1,800.00	800.00
7	TO RUST PROOF ALL ACCIDENT AFFECTED AREA	New	200.00	50.00
Gross Labour Cost (S\$)			4,460.00	2,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >