



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 8431B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	I40VC COVER ASSY - RR BUMPE	TO REPAIR SEE LABOUR	553.00	-
10	HYUNDAI BUMPER COVER CLIP	NOT NECESSARY	22.00	-
1	I40VC COVER - RR BUMPER LWR	SCRATCHED	228.00	228.00
	LESS 20% DISCOUNT		-160.60	-45.60
			642.40	182.40
<b>SPECIAL NETT ITEMS</b>				
1	HYUNDAI REVERSE SENSOR (SN)	NOT NECESSARY	135.70	-
1	I40VC PROTECTOR MAT (SN)	NOT NECESSARY	50.00	-
			185.70	-
<b>LABOUR</b>				
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF I40VC COVER ASSY - RR BUMPE.		350.00	280.00
	SPRAY PAINT ON AFFECTED AREA.		250.00	200.00
	REMOVE / REFIX REVERSE SENSOR.		80.00	50.00
			680.00	530.00
<b>GRAND TOTAL</b>			<b>1,508.10</b>	<b>712.40</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>550.00</b>

Report Ref No. CS/QW20002662/Ft3s2

PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.