

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### **TAX INVOICE**

MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE

SINGAPORE 068877

INV No. AC2005555

INV Date 13/08/2020

Reference CC4/FCI20002678/Uda3q2

Code FCI2

### **PROFESSIONAL SERVICE FEE**

Vehicle No. GBC 3368E

Insured Veh. SHC 185P

Claim No. D20000991MFSH/1

Policy No. D-20094921MFSH

Accident Date 12/02/2020

Inspection Date 17/02/2020

Description	Total
Third Party Express Settlement	500.00
Subtotal	500.00
GST (7%)	35.00
Grand Total	535.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

**LKK Auto Consultants Pte Ltd** 





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

	Affiliated to Federation Internationale Des Experts En Automobile						
MS F	S FIRST CAPITAL INSURANCE LTD Ref : CC4/FCl20002678/Uda3q2						
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date: 13-08-2020 Code: FCI2					
1.	1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SHC 185P	Veh. Inspected	GBC 3368E			
	Policy No.	D-20094921MFSH	Coverage (\$)	0.00			
	Claim No.	D20000991MFSH/1	Excess (\$)	0.00			
	Assign From	MERINA CHIA	Assign Date	17/02/2020			
2.		Vehicle Partic	culars & Condition				
	Make & Model	NISSAN CABSTAR (M)	c.c	2953			
	Engine No.	HIDDEN	Year of Reg.	2011			
	Chassis No.	JN1SC2F24Z0850334	Colour	WHITE			
	Odometer	470095	Steering	IN ORDER			
	Brakes	IN ORDER	Modification	NIL			
	General	GOOD					
3.		Condition	ons of Tyres				
		Size	Make	Balance			
	R/H Front Tyre	195 R15	GREEN MAX	7 mm			
	L/H Front Tyre	195 R15	GREEN MAX	7 mm			
	R/H Rear Tyre	155 R13 (D)	LEAO	7/7 mm			
	L/H Rear Tyre	155 R13 (D)	LEAO	7/7 mm			
4.	,	Description	on of Damages				
	THE VEHICLE SUS	STAINED DAMAGES AT THE FRO	ONT AND O/S FRONT PORT	ION.			
	DAMAGES SEE DI	ETAILS.					
5.		General	Information				
	Accident Date	12/02/2020	Inspection Date	17/02/2020			
	Survey held at	SME MOTOR PTE LTD					
		1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKI SINGAPORE 417883	T)				
5a.		Re	emarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.						
5b.	Estimate Days of Repair						
	ESTIMATED NORI	MAL PERIOD FOR REPAIR:	6 Working Days				



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBC 3368E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRT WINDSCREEN MOULDING (N)	NOT NECESSARY	420.00	-
1	FRT PANEL (N)(BADLY DENTED)	NOT CONSISTENT WITH THE IMPACT	1,580.90	-
1	FRT PANEL 'CABSTAR' PLATE (N)	NOT NECESSARY	38.00	-
1	FRT GRILLE (N)	CRACKED	461.90	461.90
1	GRILLE CENTRE LOGO (N)	NECESSARY	60.00	60.00
6	GRILLE CLIPS (N)	NECESSARY	33.00	33.00
1	FRT BUMPER (N)	TORN	1,155.10	945.10
1	HEADLAMP (N)	N/S NOT NECESSARY / O/S CRACKED	1,037.00	473.40
1	RH HEADLAMP LOWER TRIM (N)	N/S NOT NECESSARY / O/S CRACKED	81.30	40.65
1	FRT RH CORNER PANEL (N)	DENTED	436.30	389.90
1	FRT RH DOOR PILLAR (N)	TO REPAIR SEE LABOUR	1,842.40	-
1	FRT CABIN BRACKET (N)	TO REPAIR SEE LABOUR	502.40	-
	LESS 10% DISCOUNT		-764.83	-240.40
			6,883.47	2,163.55
	SPECIAL NETT ITEMS			
2	ENGINE MOUNTING (SN)	TORN	183.20	183.20
1	RADIATOR (SN)	BENT / CRACKED	792.90	792.90
1	RADIATOR FAN CLUTCH (SN)	JAMMED	533.00	533.00
2	RADIATOR MOTOR COWLING (SN)	CRACKED	173.80	173.80
1	RADIATOR FAN BLADE (SN)	CRACKED	260.90	260.90
1	GEARBOX MOUNTING (SN)	TORN	97.90	97.90
1	AIRCON LIQUID PIPE (DENTED) (SN)	NOT CONSISTENT WITH THE IMPACT	229.50	-
1	AIRCON DISCHARGE PIPE (SN)	NOT NECESSARY	249.50	_
1	FRT WINDSCREEN GUM (SN)	NOT NECESSARY	60.00	_
1	NUMBER PLATE (BROKEN) (SN)	NOT CONSISTENT WITH THE IMPACT	25.00	-

Report Ref No. CC4/FCI20002678/Uda3q2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	RADIATOR COOLANTS (SN)	NECESSARY	20.00	20.00
1	FRT RH DOOR COMPANY SRICKER (SN)	NECESSARY	20.00	20.00
1	FRT RH DOOR COMPANY ADVERTISEMENT STICKER (SN) (ADDITIONAL)	NECESSARY	180.00	180.00
			2,825.70	2,261.70
	LABOUR			
	WIRE CHECKING.		30.00	20.00
	REMOVE & REFIX FRT WINDSCREEN .	NOT NECESSARY	120.00	-
	REMOVE & REFIX DASHBOARD .	NOT NECESSARY	250.00	-
	REMOVE & REFIX 1 SET ENGINE MOUNTING.		180.00	50.00
	LABOUR CHARGE.INCLUSIVE OF THE REPAIR OF FRT RH DOOR PILLAR AND FRT CABIN BRACKET .		1,000.00	600.00
	SPRAY PAINTING.		900.00	600.00
	REPAIR WIRE HARNESS AND REPLACE SOCKETS. (ADDITIONAL)	NOT NECESSARY	150.00	-
			2,630.00	1,270.00
	GRAND TOTAL		12,339.17	5,695.25

RECOMMENDED COST OF LUMP SUM REPAIRS
(TO ITS PRE-ACCIDENT CONDITION)

4,550.00

Report Ref No. CC4/FCI20002678/Uda3q2

CHUA KANG SENG

Licensed Appraiser




51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R

# PHOTOGRAPHS FOR VEHICLE NO. GBC 3368E

















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Sngapore 408933
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Sngapore 408933


















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R


# PHOTOGRAPHS FOR VEHICLE NO. GBC 3368E


















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933


















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R

# PHOTOGRAPHS FOR VEHICLE NO. GBC 3368E



RE-INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315





