

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20002681/R1ES3Q2

Date: 25/06/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100323702

Claimant
Vehicle No : SMF7053R **Insured Vehicle No :** SKD4849R

Date of Loss: 07/02/2020 Nature of Claim: TP Claim No: 7163010790SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMF7053R	Engine No:	G4FGJH709791
Make & Model:	KIA CERATO, 1.6 EX (A)	Chassis No:	KNAF3416MK5020704
Reg. Date:	22/11/2018 (Man. Year: 2018)	Odometer:	19143 km
Colour:	Red		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,237.20	3,199.20	2,038.00	38.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,640.00	1,260.00	380.00	23.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,877.20	4,459.20	2,418.00	35.16
Approved Total (Overridden) (S\$)		3,500.00		
Nett Amount (S\$)	6,877.20	3,500.00	3,377.20	49.11
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
Nett Liability (S\$)		3,860.00		

INSPECTION

Date of Assignment: 14/02/2020

Date Inspected: 14/02/2020 Inspected At:

Sin Hup Lee Service Company (HQ)
Blk 1005 Bukit Merah Lane 2, #01-20
Singapore 159761

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Bent	1,297.00 FL	*1,297.00 FL
2	1		*BOOT LOGO	Necessary	45.00 FL	*45.00 FL
3	1		*BOOT EMBLEM CERATO	Necessary	55.00 FL	*55.00 FL
4	1		*BOOT LOCK	Serviceable	135.00 FL	*- FL
5	1		*BOOT REFLECTOR	Serviceable	1,216.00 FL	*- FL
6	1		*TAIL LAMP RH	Cracked	675.00 FL	*675.00 FL
7	1		*REAR END PANEL	Bent	378.00 FL	*378.00 FL
8	1		*REAR BUMPER	Cut	688.00 FL	*688.00 FL
9	1		*REAR BUMPER LOWER	Deformed	287.00 FL	*287.00 FL
10	1		*REAR REINFORCEMENT	Cracked	324.00 FL	*324.00 FL
11	1		*REAR BUMPER LAMP	Serviceable	362.00 FL	*- FL
12	1		*REAR BUMPER LAMP GARNISH	Serviceable	84.00 FL	*- FL
13	1		*REAR BUMPER RETAINER	Serviceable	88.00 FL	*- FL
14	1		*SET REVERSE SENSOR	Not Working	250.00 FS	*200.00 FS
15	1		*SET REVERSE CAMERA	Serviceable	480.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,364.00	3,949.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,126.80	749.80
Total Parts (\$\$)	5,237.20	3,199.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CUT ,WELD REAR PANEL,REMOVE AND REFIX DAMAGED PARTS ,STRAIGHTEN AND REALIGN AFFECTED AREAS	New	480.00	480.00
2	TO SPRAY PAINT AFFECTED AREAS	New	850.00	600.00
3	TO REMOVE AND REFIX LUGGAGE COMPARTMENT AND SIDE GARNISH	New	80.00	60.00
4	TO INSTALL REVERSE SENSOR AND CAMERA & CHECK WATER SEEPAGE	New	150.00	60.00
5	TO RUST PROOF AFFECTED AREA	New	80.00	60.00
Gross Labour Cost (S\$)			1,640.00	1,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >