

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
 Singapore 408933  
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG20002686/KSF3E2  
**Date:** 04/08/2020

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No: 71691682
Claimant Vehicle No : SHC7095U	Insured Vehicle No : SMF4094S
Date of Loss: 10/02/2020	Nature of Claim: TP Claim No: 619460

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC7095U		
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Engine No:	D4FDFU595965
Reg. Date:	04/03/2016 (Man. Year: 2015)	Chassis No:	KMHLB41UMGU085495
Colour:	Yellow	Odometer:	417608 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 9 mm	Rear Left Side:	West Lake 8 mm
Front Right Side:	West Lake 9 mm	Rear Right Side:	West Lake 8 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,185.76	6,876.72	9,309.04	57.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,260.00	1,510.00	1,750.00	53.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>19,445.76</b>	<b>8,386.72</b>	<b>11,059.04</b>	<b>56.87</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>6,500.00</b>		
<b>(\$\$)</b>	19,445.76	6,500.00	12,945.76	66.57
<b>+ GST 7.00/7.00% (\$\$)</b>	1,361.20	455.00	906.20	66.57
<b>Nett Amount (\$\$)</b>	<b>20,806.96</b>	<b>6,955.00</b>	<b>13,851.96</b>	<b>66.57</b>

### INSPECTION

Date of Assignment:	17/02/2020	
Date Inspected:	18/02/2020 Inspected At:	Bifrost Auto Pte Ltd (sin Ming) (HQ) Blk 9 Sector C, #01-42 Sin Ming Industrial Estate Singapore 575644
Estimated Period of Repair:	4.0 days	

---

**Adjuster:** KENNETH KONG**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 04 Aug 2020)
<b>Parts:</b>	143	HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHC7095U)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	2,265.90 FL	*- FL
2	1		*BONNET HINGE (LH)	Repair	82.00 FL	*- FL
3	1		*BONNET INSULATOR CLIPS	Not Necessary	15.00 FL	*- FL
4	1		*FRONT BUMPER COVER	Buckled	1,052.20 FL	*1,052.20 FL
5	1		*FRONT BUMPER GRILLE (LH)	Serviceable	49.20 FL	*- FL
6	1		*FRONT BUMPER BRACKET TOP (LH)	Serviceable	44.80 FL	*- FL
7	1		*FRONT BUMPER BRACKET (LH)	Repair	49.20 FL	*- FL
8	1		*FRONT BUMPER SIDE BRACKET	Distorted	4.60 FL	*4.60 FL
9	1		*FRONT BUMPER RETAINER MOUNTING	Serviceable	8.00 FL	*- FL
10	1		*FRONT BUMPER GRILLE AIR DUCT	Serviceable	26.20 FL	*- FL
11	1		*HEADLAMP SUPPORT PANEL ASSY	Cracked	907.40 FL	*907.40 FL
12	1		*HEADLAMP (LH)	Cut	2,776.00 FL	*2,776.00 FL
13	1		*HEADLAMP SUPPORT TOP COVER	Serviceable	222.60 FL	*- FL
14	1		*FRONT FENDER (LH)	Bent	566.30 FL	*566.30 FL
15	1		*FRONT FENDER SHIELD (LH)	Distorted	174.90 FL	*174.90 FL
16	1		*FRONT FENDER MUDFLAP (LH)	No such part	13.50 FL	*- FL
17	1		*FRONT FENDER RETAINER	Not Necessary	3.00 FL	*- FL
18	1		*FRONT DOOR MIRROR SIDE GARNISH	Serviceable	225.00 FL	*- FL
19	1		*FRONT DOOR (LH)	Repair	2,256.40 FL	*- FL
20	1		*FRONT DOOR HINGE UPPER (LH)	Repair	44.50 FL	*- FL
21	1		*FRONT DOOR HINGE LOWER (LH)	Repair	44.50 FL	*- FL
22	1		*FRONT DOOR CHECK (LH)	Serviceable	91.80 FL	*- FL
23	1		*FRONT DOOR MIRROR (LH)	Cracked	670.00 FL	*670.00 FL
24	1		*FRONT WHEEL RIM (LH)	Repair	650.60 FL	*- FL
25	1		*FRONT WHEEL HUB CAP (LH)	Dented	214.20 FL	*214.20 FL
26	1		*FRONT WHEEL NUT	Serviceable	5.70 FL	*- FL
27	1		*FRONT WHEEL BEARING	Necessary	301.80 FL	*301.80 FL
28	1		*FRONT WHEEL HUB ASSY	Bent	153.60 FL	*153.60 FL
29	1		*FRONT SHOCK ABSORBER ASSY (LH)	Serviceable	217.60 FL	*- FL
30	1		*FRONT SHOCK ABSORBER MOUNTING (LH)	Serviceable	217.60 FL	*- FL
31	1		*FRONT DRIVE SHAFT	Repair	2,061.60 FL	*- FL
32	1		*RACK & PINION ASSY	Repair	1,820.00 FL	*- FL
33	1		*STG TIE ROD	Serviceable	135.00 FL	*- FL
34	1		*STG TIE END	Serviceable	125.20 FL	*- FL
35	1		*STG BALL JOINT	Serviceable	73.10 FL	*- FL
36	1		*STABILIZER BAR	Serviceable	252.30 FL	*- FL
37	1		*STABILIZER BAR BUSH	Serviceable	16.40 FL	*- FL
38	1		*STABILIZER BAR LINK	Serviceable	68.10 FL	*- FL
39	1		*STABILIZER BRACKET	Repair	24.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*FRONT SUSPENSION LOWER ARM (LH)	Distorted	595.90 FL	*595.90 FL
41	1		*KNUCKLE ARM (LH)	Bent	1,104.00 FL	*1,104.00 FL
42	1		*FRONT DOOR COLOURED COMFORT LOGO	Not Necessary	66.00 FS	*- FS
43	1		*FRONT DOOR ADVERTISEMENT LOGO	Not Necessary	100.00 FS	*- FS
44	2		*FRONT TYRE (LH/RH)	Serviceable	216.00 FS	*- FS
45	1		*FRONT FENDER ADVERTISEMENT LOGO	Necessary	100.00 FS	*60.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					<b>Sub Total (\$\$)</b>	<b>20,111.70</b>
					<b>8,580.90</b>	
					<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>3,925.94</b>
						<b>1,704.18</b>
					<b>Total Parts (\$\$)</b>	<b>16,185.76</b>
						<b>6,876.72</b>

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	PANEL BEATING	New	1,200.00	500.00
2	SPRAY PAINTING CHARGE	New	1,000.00	650.00
3	WIRING CHARGE	New	120.00	20.00
4	TUFF KOTE	New	150.00	30.00
5	TOWING CHARGE	New	50.00	50.00
6	REMOVE / REFIX UNDERCARRIAGE (FRT)	New	400.00	200.00
7	FRONT / FOUR WHEEL ALIGNMENT	New	120.00	60.00
8	REMOVE / REFIX RADIATOR	New	90.00	0.00
9	REMOVE / REFIX AIRCON & REFILL GAS	New	130.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,260.00</b>	<b>1,510.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >