

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
AXA	INSURANCE PTE	LTD	Ref : CC4/ASM20002698/R1pa3q2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:RICHARD ANG			Date: 24-04-2020 Code: ASM		
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLC 4124S	Veh. Inspected	SGY 4056Z	
	Policy No.	VPA/P2134142	Coverage (\$)	0.00	
	Claim No.	S0M02DA5	Excess (\$)	0.00	
	Assign From		Assign Date	17/02/2020	
2. Vehicle Particulars & Condition					
	Make & Model	B.M.W. 318I SEDAN	c.c	1499	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	WBA8E36070NT39187	Colour	WHITE	
	Odometer	49135	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	225/50 R17	BRIDGESTONE	6 mm	
	L/H Front Tyre	225/50 R17	BRIDGESTONE	6 mm	
	R/H Rear Tyre	225/50 R17	BRIDGESTONE	6 mm	
	L/H Rear Tyre	225/50 R17	BRIDGESTONE	6 mm	
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	08/01/2020	Inspection Date	17/02/2020	
	Survey held at	MOVA AUTOMOTIVE PTE LTD			
		BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 . SINGAPORE 159722			
5a.					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days				