

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBU 2626Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAILGATE (CONSISTENT)	DENTED	2,048.00	1,802.00
1	TAILGATE WEATHER STRIP (CONSISTENT)	NOT DAMAGED	365.00	-
1	TAILGATE LOGO (CONSISTENT)	NECESSARY	254.00	120.00
1	TAILGATE EMBLEM 'ASTRA' (CONSISTENT)	NECESSARY	89.00	89.00
1	TAILGATE EMBLEM 'ECO' (CONSISTENT)	NECESSARY	72.00	72.00
1	TAILGATE WINDSCREEN MOULDING (CONSISTENT)	NECESSARY	298.60	298.60
2	TAILGATE REFLECTOR @\$851.00 (CONSISTENT)	NOT DAMAGED	1,702.00	-
1	REAR END PANEL TOP GARNISH (CONSISTENT)	NOT DAMAGED	291.90	-
1	REAR BUMPER (CONSISTENT)	CUT	1,523.00	1,523.00
2	REAR BUMPER SIDE RETAINER @\$214.50 (CONSISTENT)	NECESSARY	429.00	278.32
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	BENT	795.00	547.00
2	REAR BUMPER REINFORCEMENT BRACKET @\$268.40 (CONSISTENT)	NO SUCH PARTS	536.80	-
1	REAR BUMPER TOWING COVER (CONSISTENT)	NOT DAMAGED	92.50	-
1	REAR BUMPER LOWER (CONSISTENT)	NOT DAMAGED	758.00	-
2	REAR BUMPER BRACKET @\$106.50 (CONSISTENT)	NOT DAMAGED	213.00	-
2	REAR BUMPER REFLECTOR @\$185.00 (CONSISTENT)	BROKEN	370.00	134.00
	LESS 10% DISCOUNT		-983.78	-486.39
			8,854.02	4,377.53
	SPECIAL NETT ITEMS			
1	SUNDRIES (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
1	TAILGATE SEALANT (SN) (CONSISTENT)	NECESSARY	80.00	40.00
2	TAILGATE REFLECTOR SEAL @\$50.00 (SN) (CONSISTENT)	NOT NECESSARY	100.00	-
1	TAILGATE WINDSCREEN SEALANT (SN) (CONSISTENT)	NECESSARY	100.00	60.00
1	REAR BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	60.00	30.00
1	REAR BUMPER LOWER CLIPS (SN) (CONSISTENT)	NOT NECESSARY	60.00	-
4	REAR BUMPER REVERSE SENSOR @\$250.00 (SN) (CONSISTENT)	CUT (2 PCS ONLY)	1,000.00	300.00
1	REAR END PANEL TOP GARNISH CLIPS (SN) (CONSISTENT)	NOT NECESSARY	60.00	-

Report Ref No. CC4/ASM20002700/Bpa3q2



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

5,150.00

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	REAR REVERSE CAMERA (SN) (CONSISTENT)	NOT DAMAGED	480.00	-
1	REAR END PLATE W/COWLING (SN) (CONSISTENT)	NOT DAMAGED	80.00	-
			2,100.00	430.00
	LABOUR			
	R&R REAR WINDSCREEN.		150.00	120.00
	PANEL BEAT.		1,200.00	800.00
	RUST PROOFING .		200.00	60.00
	SPRAY PAINTING .		1,200.00	600.00
	RESET FAULT CODE.		150.00	60.00
	R&R REVERSE SENSOR AND CHECK WIRING .		60.00	30.00
			2,960.00	1,670.00
	GRAND TOTAL		13,914.02	6,477.53

Report Ref No. CC4/ASM20002700/Bpa3q2

RECOMMENDED COST OF LUMP SUM REPAIRS

(TO ITS PRE-ACCIDENT CONDITION)

**LIM TEOW GUAN** 

**Automotive Assessor** 

**HO LEONG CHUAN** 

**Automotive Assessor**