



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBA 1955J

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
2	R/L FRONT FORK ASSY (CONSISTENT)	BENT	590.00	590.00
1	UNDER BRACKET (CONSISTENT)	BENT	385.00	385.00
1	FORK CENTRAL BRACKET (CONSISTENT)	BENT	280.00	280.00
1	FRONT MUDGUARD (CONSISTENT)	BROKEN	245.00	245.00
1	FRONT SPOILING ASSY RIM (CONSISTENT)	BENT / CUT	695.00	695.00
2	FRONT BRAKE DICS ASSY (LH / RH) (CONSISTENT)	BENT	795.00	795.00
1	FRONT SPOILING SHAFT (RIM SHAFT) (CONSISTENT)	BENT	85.00	85.00
1	AIR HORT ASSY (CONSISTENT)	NOT NECESSARY	75.00	-
1	HEAD LIGHT ASSY (CONSISTENT)	BENT	385.00	385.00
1	HEAD LIGHT WISKIM (FAIRY) (CONSISTENT)	BROKEN	220.00	220.00
1	HEAD LIGHT BRACKET (METAL) (CONSISTENT)	BENT	185.00	185.00
1	R/L METER BRACKET (CONSISTENT)	BENT	170.00	170.00
1	METER ASSY (CONSISTENT)	BROKEN	950.00	950.00
1	VOLT METER (CONSISTENT)	NOT NECESSARY	75.00	-
1	HANDLE BAR ASSY (CONSISTENT)	BENT	180.00	180.00
1	COMPELING ASSY (BEARING) (CONSISTENT)	NECESSARY	145.00	145.00
1	BRAKE PUMP (CONSISTENT)	NOT NECESSARY	210.00	-
1	MIRROR ASSY (CONSISTENT)	CUT	85.00	60.00
1	H.BTE HODIE ASSY (HANDLE BAR BRACKET UPPER) (CONSISTENT)	BENT	58.00	58.00
1	TANK	TO REPAIR SEE LABOUR	350.00	-
1	AIR PIPR CUSTOM (HANDLE) (EXHAUST CENTRE PIPE) (CONSISTENT)	BENT	780.00	650.00
1	REAR PIPE (BLUE FRAME) (CONSISTENT)	BENT	1,450.00	1,200.00
1	REAR BOX & BRACKET BEARING (CONSISTENT)	NOT NECESSARY	80.00	-
1	ENGINE REAR ASSY (SIDE BAR LH) (CONSISTENT)	BENT	180.00	180.00
1	LH SIDE STEM (CONSISTENT)	BROKEN	98.00	98.00
1	SIDE STEM SWITCH (CONSISTENT)	NOT NECESSARY	78.00	-
	LESS 50% DISCOUNT		-	-3,778.00
			8,829.00	3,778.00

Report Ref No. CC4/ASM20002701/Epa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>LABOUR</u>			
	TOWING.	NOT NECESSARY	45.00	40.00
	TOWING TO IDAC.		45.00	-
	LABOUR. INCLUSIVE OF THE REPAIR OF TANK. }		280.00	250.00
1	PAINTING: TANK. }		-	200.00
			370.00	490.00
GRAND TOTAL			9,199.00	4,268.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,850.00

Report Ref No. CC4/ASM20002701/Epa3s2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.