

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20002706/R1PA3Q2

Date: 16/04/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SMG4586J	Insured Vehicle No :	SH8592M
Date of Loss: 12/02/2020	Nature of Claim: TP	Claim No: MCT20020261

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG4586J		
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Engine No:	2ZR0B45670
Reg. Date:	20/12/2018 (Man. Year: 2018)	Chassis No:	ZVW400029138
Colour:	Brown	Odometer:	103221 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	845.50	348.00	497.50	58.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	594.04	546.75	47.29	7.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,439.54	894.75	544.79	37.84
+ GST 7.00/7.00% (S\$)	100.77	62.63	38.14	37.85
Nett Amount (S\$)	1,540.31	957.38	582.93	37.84
+ Loss of Use (3.0 x S\$80.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		7.45		
+ Other Doc Fees (S\$)		42.00		
Nett Liability (S\$)		1,246.83		

INSPECTION

Date of Assignment: 14/02/2020

Date Inspected: 18/02/2020 Inspected At:

AutoSprint Pte Ltd (HQ)
24, Leng Kee Road, #07-01/02 Leng
Kee AutoPoint
Singapore 159096

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Mar 2020)
Parts:	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMG4586J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*END PANEL (WCP)	Repair	230.00 F	*- F
2	1		*L/R UPP BUMPER BRKT (WCP)	Serviceable	50.00 F	*- F
3	1		*R/R UPP BUMPER BRKT (WCP)	Serviceable	50.00 F	*- F
4	1		*REAR BUMPER (WCP)	Deformed	280.00 F	*280.00 F
5	1		*RR PLUG COMPART TRIM64716 52170C0 (WCP)	Not Necessary	95.00 F	*- F
6	1		*REAR BUMPER CLIP	Necessary	70.00 FS	*40.00 FS

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	775.00	320.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	70.50	28.00
Total Parts (\$\$)	845.50	348.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	49.0 WU X 50.00 SGD/H	New	280.00	280.00
2	LABOUR COST 47.0 WU X 50.00 SGD/H	New	235.00	195.00
3	MATERIAL COST	New	79.04	71.75
Gross Labour Cost (\$\$)			594.04	546.75

Report was unsubmitted during this print-out.

< END OF ESTIMATES >