

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD20002707/APA3Q2

Date: 25/06/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd.	Policy No:	PNPV2019-00004646
Claimant		
Vehicle No : SGV7148M	Insured Vehicle No :	SLX3416X
Date of Loss: 14/02/2020	Nature of Claim: TP	Claim No: 1202000008670

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGV7148M	Engine No:	4G18JD0092
Make & Model:	MITSUBISHI LANCER, 1.6 (A)	Chassis No:	JMYSTCS3A7U014362
Reg. Date:	25/06/2007 (Man. Year: 2007)	Odometer:	218099 km
Colour:	Silver		
Engine Capacity:	1584 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,877.80	9,605.70	6,272.10	39.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,240.00	2,910.00	2,330.00	44.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	21,117.80	12,515.70	8,602.10	40.73
Approved Total (Overridden) (\$\$)		4,300.00		
Nett Amount (\$\$)	21,117.80	4,300.00	16,817.80	79.64
+ Car Rental (8.0 x S\$100.00/day) (\$\$)		800.00		
+ Doc/Search Fee (\$\$)		7.45		
+ Other Costs (\$\$)		60.00		
Nett Liability (\$\$)		5,167.45		
Global Sum Settlement (\$\$)		5,150.00		

INSPECTION

Date of Assignment:	17/02/2020	
Date Inspected:	17/02/2020 Inspected At:	Premium Carz Services Pte Ltd (HQ)
		1 Kaki Bukit Ave 6 #01-90
		Autobay@Kaki
		Singapore 417883
Estimated Period of Repair:	9.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 May 2020)
Parts:	143	MITSUBISHI LANCER 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGV7148M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	810.00 FL	*810.00 FL
2	1		*BONNET LOCK	Damaged	158.00 FL	*158.00 FL
3	1		*BONNET WEATHERSTRIP -INNER	Not Necessary	68.00 FL	*- FL
4	1		*BONNET WEATHERSTRIP -OUTER	Not Necessary	68.00 FL	*- FL
5	2		*BONNET HINGES	Bent	250.00 FL	*250.00 FL
6	1		*BONNET STAND	Not Necessary	55.00 FL	*- FL
7	1		*BONNET STAND CLIP	Not Necessary	10.00 FL	*- FL
8	1		*BONNET INSULATOR	Crumpled	175.00 FL	*175.00 FL
9	1		*HEADLAMP RH	Cracked	658.00 FL	*658.00 FL
10	1		*HEADLAMP LH	Cracked	658.00 FL	*658.00 FL
11	1		*HEADLAMP TOP RUBBER RH	Not Necessary	45.00 FL	*- FL
12	1		*HEADLAMP TOP RUBBER LH	Not Necessary	45.00 FL	*- FL
13	1		*FRONT BUMPER	Deformed	729.00 FL	*729.00 FL
14	1		*FRONT BUMPER SIDE RETAINER RH	Necessary	45.00 FL	*45.00 FL
15	1		*FRONT BUMPER SIDE RETAINER LH	Necessary	45.00 FL	*45.00 FL
16	1		*FRONT BUMPER REINFORCEMENT	Bent	313.00 FL	*313.00 FL
17	1		*FRONT BUMPER CENTRE BEAM	Not Necessary	189.00 FL	*- FL
18	1		*FRONT NUMBER PLATE GARNISH	Deformed	128.00 FL	*128.00 FL
19	1		*FRONT BUMPER LOWER GRILLE	Deformed	180.00 FL	*180.00 FL
20	1		*FRONT BUMPER GARNISH RH	Not Necessary	75.00 FL	*- FL
21	1		*FRONT BUMPER GARNISH LH	Not Necessary	75.00 FL	*- FL
22	1		*FRONT GRILLE RH	Deformed	210.00 FL	*91.00 FL
23	1		*FRONT GRILLE LH	Deformed	210.00 FL	*91.00 FL
24	1		*FRONT GRILLE BASE	Deformed	286.00 FL	*286.00 FL
25	1		*FRONT GRILLE MITSUBISHI LOGO	Necessary	58.00 FL	*58.00 FL
26	1		*SUPPORT PANEL ASSY	Buckled	1,150.00 FL	*1,150.00 FL
27	1		*SUPPORT STAY PANEL	Bent	137.00 FL	*137.00 FL
28	1		*RADIATOR	Dented	1,294.00 FL	*1,294.00 FL
29	1		*RADIATOR FAN MOTOR	Not Necessary	475.00 FL	*- FL
30	1		*RADIATOR FAN BLADE	Not Necessary	157.00 FL	*- FL
31	1		*RADIATOR SPARE TANK	Not Necessary	98.00 FL	*- FL
32	1		*RADIATOR COWLING	Not Necessary	266.00 FL	*- FL
33	1		*AIR-CON CONDENSER	Bent	914.00 FL	*914.00 FL
34	1		*AIR-CONDENSER FAN MOTOR	Not Necessary	475.00 FL	*- FL
35	1		*AIR-CON CONDENSER FAN BLADE	Not Necessary	157.00 FL	*- FL
36	1		*AIR FILTER HOUSING	Cracked	473.00 FL	*473.00 FL
37	1		*AIR DUCT	Cracked	247.00 FL	*247.00 FL
38	1		*WIPER WASHER TANK	Not Necessary	257.00 FL	*- FL
39	1		*WIPER WASHER TANK MOTOR	Not Necessary	98.00 FL	*- FL
40	1		*BATTERY TRAY (NPA)	Not Necessary	0.00 FL	*- FL
41	1		*BATTERY COVER (NPA)	Not Necessary	0.00 FL	*- FL
42	1		*FRONT CHASSIS RH (NPA)	Repair	0.00 FL	*- FL
43	1		*FRONT FENDER RH	Buckled	596.00 FL	*596.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*FRONT FENDER LH (NPA)	Repair	0.00 FL	*- FL
45	1		*FRONT FENDER INDICATOR LIGHT RH	Not Necessary	67.00 FL	*- FL
46	1		*FRONT FENDER CHROME RH	Necessary	55.00 FL	*55.00 FL
47	1		*FRONT DOOR RH (NPA)	Repair	0.00 FL	*- FL
48	1		*REAR BUMPER	Deformed	710.00 FL	*710.00 FL
49	1		*REAR BUMPER CENTRE BRACKET	Not Necessary	171.00 FL	*- FL
50	1		*REAR BUMPER BRACKET RH	Not Necessary	45.00 FL	*- FL
51	1		*REAR BUMPER BRACKET LH	Not Necessary	45.00 FL	*- FL
52	1		*BOOT LID	Repair	593.00 FL	*- FL
53	2		*BOOT LID STOPPER	Not Necessary	110.00 FL	*- FL
54	1		*BOOT LID LOCK	Not Necessary	61.00 FL	*- FL
55	1		*BOOT LID LOWER CATCH	Not Necessary	28.00 FL	*- FL
56	1		*BOOT LID MITSUBISHI LOGO	Necessary	46.00 FL	*46.00 FL
57	1		*BOOT LID LANCER EMBLEM	Necessary	43.00 FL	*43.00 FL
58	1		*BOOT LID GLX EMBLEM	Necessary	33.00 FL	*33.00 FL
59	1		*BOOT LID WEATHERSTRIP	Not Necessary	169.00 FL	*- FL
60	2		*BOOT LID HINGE	Not Necessary	168.00 FL	*- FL
61	1		*REAR LICENSE PLATE GARNISH	Not Necessary	198.00 FL	*- FL
62	1		*REAR END PANEL	Not Necessary	423.00 FL	*- FL
63	1		*REAR END PANEL GARNISH	Not Necessary	150.00 FL	*- FL
64	1		*TAIL LAMP LH	Not Necessary	404.00 FL	*- FL
65	1		*SPARE TYRE PANEL (NPA)	Repair	0.00 FL	*- FL
66	1		*SPARE TYRE BOARD	Not Necessary	156.00 FL	*- FL
67	10		*FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
68	3		*AIR DUCT CLIP	Necessary	15.00 FS	*15.00 FS
69	10		*BONNET INSULATOR CLIP	Necessary	50.00 FS	*30.00 FS
70	1		*FRONT GRILLE CLIP (6 PCS)	Necessary	30.00 FS	*10.00 FS
71	10		*FRONT FENDER INNER SHIELD CLIP	Not Necessary	50.00 FS	*- FS
72	1		*FRONT NUMBER PLATE W/CASING	Bent	70.00 FS	*70.00 FS
73	1		*COOLANT	Necessary	60.00 FS	*40.00 FS
74	1		*SET HORN	Not Necessary	188.00 FS	*- FS
75	1		*RADIATOR TOP HOSE	Twisted	45.00 FS	*45.00 FS
76	1		*RADIATOR BOTTOM HOSE	Not Necessary	55.00 FS	*- FS
77	1		*AIR-CON LIQUID PIPE	Not Necessary	150.00 FS	*- FS
78	1		*AIR-CON DISCHARGE PIPE	Not Necessary	112.00 FS	*- FS
79	1		*AIR-CON SUCTION PIPE	Not Necessary	152.00 FS	*- FS
80	4		*TAIL LAMP CLIP	Not Necessary	20.00 FS	*- FS
81	1		*SET REVERSE SENSOR	Not Necessary	250.00 FS	*- FS
82	1		*REAR NUMBER PLATE W/CASING	Not Necessary	70.00 FS	*- FS
83	10		*REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
84	10		*REAR END PANEL GARNISH CLIP	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	17,479.00	10,643.00
- List Item Discount on L Items 10.00/10.00% (\$)	1,601.20	1,037.30
Total Parts (\$)	15,877.80	9,605.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING AND REFOCUS HEADLAMP	New	120.00	30.00
2	FRONT-PANEL BEATING CHARGES TO REMOVE AND REPLACE ,TO CUT AND WELD ,TO KNOCK AND RESHAPE DAMAGED PARTS & AREAS	New	1,200.00	1,000.00
3	FRONT-SPRAY PAINTING ALL AFFECTED PARTS & AREAS	New	1,400.00	1,000.00
4	REAR-PANEL BEATING CHARGES TO REMOVE AND REPLACE ,TO CUT AND WELD ,TO KNOCK AND RESHAPE DAMAGED PARTS & AREAS	New	800.00	300.00
5	REAR -SPRAY PAINTING ALL AFFECTED PARTS & AREAS	New	1,000.00	400.00
6	TO SPRAY ANTI-RUST UNDERCOAT	New	120.00	60.00
7	TO REMOVE AND REFIT REAR SEATS ,REAR WHEELHOUSE INNER GARNISH,FLOOR CARPET & UPHOLSTERY TO FACILITATE REPAIRS	New	250.00	0.00
8	TO REMOVE AND REFIT RADIATOR AND AIR-CON CONDENSER AND TO VACUUM AIRC-CON SYSTEM AND CHARGE UP AIR-CON GAS	New	350.00	120.00
Gross Labour Cost (\$\$)			5,240.00	2,910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >