

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Feb 2020 Edit Reg		17 Feb 2020 00:00 Edit Adj Rpt	S\$11,250.00 Edit Estimates	S\$11,250.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: JAREEN HIRE , Co. Reg. No.: 53367982J									
Main Claimant: SJ MOTOR ENTERPRISE , Co. Reg. No.: 52838801X									
Vehicle Reg. No.: SLF2950X		Date of Loss: 14/02/2020 00:00 - :59 [361 Months and 13 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 1202000008662		Policy/Cover Note No.: PNCV2019-00001510 (Comprehensive) Coverage: 20/11/2019 - 19/11/2020							
Vehicle Reg. No. (Insured): SLT1023E		Policy No. (Claimant): M400000147MCX							
		Excess:							
Repairer: Auto Insure Pte Ltd (HQ) (Woodlands) 6 Marsiling Lane, 739145 Woodlands - Tel: 3157 2626									
Handling Insurer: FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Josey Loh]									
Claimant's Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by OI SUN PIN] ... [Final Rpt due 26/02/2020]									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
FWD_SG (25/06/2020): Alert - Adj Mandate Approved (S\$12754.50) - SLF2950X - Claim Handler: Josey Loh									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLF2950X (1202000008662)**

[SLT1023E]

TP

SJ MOTOR ENTERPRISE

Feb 14 2020 12:00AM

[JAREEN HIRE]

Auto Insure Pte Ltd (HQ)

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Letters/Correspondences

1 per page
 ☒

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown		Edit

Assessment Reports

1 per page
 ☒

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/05/20 14:34	Adjuster Immediate Advice		Load HTM

Photos/Images

3 per page
 ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/02/20 10:24	Chassis Number		Load JPG
2	20/02/20 10:24	Odometer Reading		Load JPG
3	20/02/20 10:24	General View		Load JPG
4	20/02/20 10:24	General View		Load JPG
5	20/02/20 10:24	General View		Load JPG
6	20/02/20 10:24	General View		Load JPG
7	20/02/20 10:24	General View		Load JPG
8	20/02/20 10:24	General View		Load JPG
9	20/02/20 10:24	General View		Load JPG
10	20/02/20 10:24	General View		Load JPG
11	20/02/20 10:24	General View		Load JPG
12	20/02/20 10:24	General View		Load JPG
13	20/02/20 10:24	General View		Load JPG
14	20/02/20 10:24	General View		Load JPG
15	20/02/20 10:24	General View		Load JPG
16	20/02/20 10:24	General View		Load JPG
17	20/02/20 10:24	General View		Load JPG
18	20/02/20 10:24	General View		Load JPG
19	20/02/20 10:24	General View		Load JPG
20	20/02/20 10:24	General View		Load JPG
21	20/02/20 10:24	General View		Load JPG
22	20/02/20 10:24	General View		Load JPG
23	20/02/20 10:24	General View		Load JPG
24	20/02/20 10:24	General View		Load JPG
25	20/02/20 10:24	General View		Load JPG
26	20/02/20 10:24	General View		Load JPG
27	20/02/20 10:24	General View		Load JPG
28	20/02/20 10:24	General View		Load JPG
29	20/02/20 10:24	General View		Load JPG
30	20/02/20 10:24	General View		Load JPG
31	20/02/20 10:24	General View		Load JPG
32	20/02/20 10:24	General View		Load JPG
33	20/02/20 10:24	General View		Load JPG
34	20/02/20 10:24	General View		Load JPG

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
35	20/02/20 10:24	General View		Load JPG	☒
36	20/02/20 10:24	General View		Load JPG	☒
37	20/02/20 10:24	General View		Load JPG	☒
38	20/02/20 10:24	General View		Load JPG	☒
39	20/02/20 10:24	General View		Load JPG	☒
40	20/02/20 10:24	General View		Load JPG	☒
41	20/02/20 10:24	General View		Load JPG	☒
42	20/02/20 10:24	General View		Load JPG	☒
43	20/02/20 10:24	General View		Load JPG	☒
44	20/02/20 10:24	General View		Load JPG	☒
45	20/02/20 10:24	General View		Load JPG	☒
46	20/02/20 10:24	General View		Load JPG	☒
47	20/02/20 10:24	General View		Load JPG	☒
48	20/02/20 10:24	General View		Load JPG	☒
49	20/02/20 10:24	General View		Load JPG	☒
50	20/02/20 10:24	General View		Load JPG	☒
51	20/02/20 10:24	General View		Load JPG	☒
52	20/02/20 10:24	General View		Load JPG	☒
53	20/02/20 10:24	General View		Load JPG	☒
54	20/02/20 10:24	General View		Load JPG	☒
55	20/02/20 10:24	General View		Load JPG	☒
56	20/02/20 10:24	General View		Load JPG	☒
57	20/02/20 10:24	General View		Load JPG	☒
58	20/02/20 10:24	General View		Load JPG	☒
59	20/02/20 10:24	General View		Load JPG	☒
60	20/02/20 10:24	General View		Load JPG	☒
61	20/02/20 10:24	General View		Load JPG	☒
62	20/02/20 10:24	General View		Load JPG	☒
63	20/02/20 10:24	General View		Load JPG	☒
64	20/02/20 10:24	General View		Load JPG	☒
65	20/02/20 10:24	General View		Load JPG	☒
66	06/05/20 17:31	Dismantled Parts		Load JPG	☒
67	06/05/20 17:31	Dismantled Parts		Load JPG	☒
68	06/05/20 17:31	Dismantled Parts		Load JPG	☒
69	06/05/20 17:31	Dismantled Parts		Load JPG	☒
70	06/05/20 17:31	Dismantled Parts		Load JPG	☒
71	06/05/20 17:31	Dismantled Parts		Load JPG	☒
72	06/05/20 17:31	Dismantled Parts		Load JPG	☒
73	06/05/20 17:31	Dismantled Parts		Load JPG	☒
74	06/05/20 17:31	Dismantled Parts		Load JPG	☒
75	06/05/20 17:31	Dismantled Parts		Load JPG	☒
76	06/05/20 17:31	Dismantled Parts		Load JPG	☒
77	06/05/20 17:31	Dismantled Parts		Load JPG	☒
78	06/05/20 17:31	Dismantled Parts		Load JPG	☒
79	06/05/20 17:31	Dismantled Parts		Load JPG	☒
80	06/05/20 17:31	Dismantled Parts		Load JPG	☒
81	06/05/20 17:31	Dismantled Parts		Load JPG	☒
82	06/05/20 17:31	Dismantled Parts		Load JPG	☒
83	06/05/20 17:31	Dismantled Parts		Load JPG	☒
84	06/05/20 17:31	Dismantled Parts		Load JPG	☒
85	06/05/20 17:31	Dismantled Parts		Load JPG	☒
86	06/05/20 17:31	Dismantled Parts		Load JPG	☒
87	06/05/20 17:31	Dismantled Parts		Load JPG	☒

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
88	06/05/20 17:31	Dismantled Parts		Load JPG	☒
89	06/05/20 17:31	Dismantled Parts		Load JPG	☒
90	06/05/20 17:31	Dismantled Parts		Load JPG	☒
91	06/05/20 17:31	Dismantled Parts		Load JPG	☒
92	06/05/20 17:31	Dismantled Parts		Load JPG	☒
93	06/05/20 17:31	Dismantled Parts		Load JPG	☒
94	06/05/20 17:31	Dismantled Parts		Load JPG	☒
95	06/05/20 17:31	Dismantled Parts		Load JPG	☒
96	06/05/20 17:31	Dismantled Parts		Load JPG	☒
97	06/05/20 17:31	Dismantled Parts		Load JPG	☒
98	06/05/20 17:31	Dismantled Parts		Load JPG	☒
99	06/05/20 17:31	Dismantled Parts		Load JPG	☒
100	06/05/20 17:31	Dismantled Parts		Load JPG	☒
101	06/05/20 17:31	Dismantled Parts		Load JPG	☒
102	06/05/20 17:31	Dismantled Parts		Load JPG	☒
103	06/05/20 17:31	Dismantled Parts		Load JPG	☒
104	06/05/20 17:31	Dismantled Parts		Load JPG	☒
105	06/05/20 17:31	Dismantled Parts		Load JPG	☒
106	06/05/20 17:31	Dismantled Parts		Load JPG	☒
107	06/05/20 17:31	Dismantled Parts		Load JPG	☒
108	06/05/20 17:31	Dismantled Parts		Load JPG	☒
109	06/05/20 17:31	Dismantled Parts		Load JPG	☒
110	06/05/20 17:31	Dismantled Parts		Load JPG	☒
111	06/05/20 17:31	Dismantled Parts		Load JPG	☒
112	06/05/20 17:31	Dismantled Parts		Load JPG	☒
113	06/05/20 17:31	Dismantled Parts		Load JPG	☒
114	06/05/20 17:31	Dismantled Parts		Load JPG	☒
115	06/05/20 17:31	Dismantled Parts		Load JPG	☒
116	06/05/20 17:31	After Repair Photo		Load JPG	☒
117	06/05/20 17:31	After Repair Photo		Load JPG	☒
118	06/05/20 17:31	After Repair Photo		Load JPG	☒
119	06/05/20 17:31	After Repair Photo		Load JPG	☒
120	06/05/20 17:31	After Repair Photo		Load JPG	☒
121	06/05/20 17:31	After Repair Photo		Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	17/02/20 19:06	EMAIL - FWD TO OI DD 17.02.2020		Load PDF	
2	17/02/20 19:06	EMAIL FROM FWD DD 17.02.2020		Load PDF	
3	17/02/20 19:06	NOTIFICATION FROM WORKSHOP		Load PDF	
4	27/05/20 13:45	TP ESTIMATE - MARKED		Load PDF	
5	27/05/20 13:57	TP LOD		Load PDF	
6	27/05/20 13:57	TP GIA REPORT		Load PDF	
7	24/06/20 14:23	LOD AND OTHER DOCUMENTS		Load PDF	
8	24/06/20 14:23	TP FINAL EST LIST		Load PDF	
9	28/07/20 08:59	Authorisation to Act		Load PDF	
10	28/07/20 08:59	GIA SEARCH		Load PDF	
11	28/07/20 08:59	Release Voucher		Load PDF	
12	28/07/20 08:59	SUB-CONTRACT AGREEMENT		Load PDF	
13	28/07/20 08:59	WORKSHOP INVOICE		Load PDF	
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)		Thumbnail	Print
1	18/02/20 10:02	SLT1023E OI GIA		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLT1023E (Insd veh)	Model:	TOYOTA SIENTA 1.5 (A)
	SLF2950X (TP veh)		
Date of Accident:	14/02/2020		

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	:\$	30,467.39	
Final Repair Cost	:\$	12,700.00	
Loss of Use	:\$	days at \$0.00 per day	
Rental (if any)	:\$	11 days	
LTA / GIA Search Fee	:\$		
Others:	:\$		
	:\$		
Final Settlement Sum (GLOBAL SUM)	:\$	12,700.00	
Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Auto Insure Pte Ltd	:\$	12,700.00
2)		:\$	
3)		:\$	

NUR SHAQILAH BTE ABDOL WAHAB

28 Jul
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/FWD20002708/QGA3S2**Date:** 28/07/2020REFERENCE

Handling Insurer:	FWD Singapore Pte. Ltd.	Policy No:	PNCV2019-00001510
Claimant Vehicle No :	SLF2950X	Insured Vehicle No :	SLT1023E
Date of Loss:	14/02/2020	Nature of Claim:	TP
		Claim No:	1202000008662

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF2950X	Engine No:	2NR8561524
Make & Model:	TOYOTA SIENTA, 1.5 (A)	Chassis No:	NSP1707014961
Reg. Date:	01/01/1990 (Man. Year: 1990)	Odometer:	103320 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,764.20	10,656.65	13,107.55	55.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,710.00	3,440.00	1,270.00	26.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	28,474.20	14,096.65	14,377.55	50.49
Approved Total (Overridden) (\$\$)		11,250.00		
(\$\$)	28,474.20	11,250.00	17,224.20	60.49
+ GST 7.00/7.00% (\$\$)	1,993.19	787.50	1,205.69	60.49
Nett Amount (\$\$)	30,467.39	12,037.50	18,429.89	60.49
+ Car Rental (11.0 x S\$65.00/day) (\$\$)		715.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		12,754.50		
Global Sum Settlement (\$\$)		12,700.00		

INSPECTION

Date of Assignment:	17/02/2020		
Date Inspected:	17/02/2020	Inspected At:	Auto Insure Pte Ltd (HQ) (Woodlands) 6 Marsiling Lane Singapore 739145
Estimated Period of Repair:	9.0 days		

Adjuster: OI SUN PIN**Manager:** Chong Pui Lin

7/28/2020

Adjuster Report

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Jul 2020)
Parts:	M1-MPV	TOYOTA SIENTA 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLF2950X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER ASSY	Crushed	956.00 FL	*679.00 FL
2	1		*FRONT BUMPER RETAINER LH	Broken	90.00 FL	*90.00 FL
3	1		*FRONT BUMPER RETAINER RH	Broken	90.00 FL	*90.00 FL
4	1		*RADIATOR GRILLE ASSY	Crushed	1,110.00 FL	*750.00 FL
5	1		*RADIATOR TOYOTA LOGO	Broken	180.00 FL	*105.00 FL
6	1		*FRONT REINFORCEMENT BAR		520.00 FL	*- FL
7	1		*FRONT SUPPORT PANEL	Bent	1,005.00 FL	*1,005.00 FL
8	1		*RADIATOR ASSY	Cracked	1,590.00 FL	*1,190.00 FL
9	1		*RADIATOR FAN SHROUD COWLING	Serviceable	450.00 FL	*- FL
10	1		*RADIATOR FAN BLADE	Serviceable	175.00 FL	*- FL
11	1		*RADIATOR FAN MOTOR ASSY	Serviceable	260.00 FL	*- FL
12	1		*AIR CON CONDENSER ASSY	Serviceable	1,335.00 FL	*- FL
13	1		*HEAD LAMP ASSY LH	Scratched	1,080.00 FL	*1,080.00 FL
14	1		*HEAD LAMP ASSY RH	Cracked	1,080.00 FL	*1,080.00 FL
15	1		*HEAD LAMP PANEL LH	Bent	150.00 FL	*150.00 FL
16	1		*HEAD LAMP PANEL RH	Serviceable	150.00 FL	*- FL
17	1		*AIR INTAKE DUCT	Serviceable	240.00 FL	*- FL
18	1		*FRONT FENDER ASSY LH	Serviceable	710.00 FL	*- FL
19	1		*FRONT FENDER ASSY RH	Crushed	710.00 FL	*710.00 FL
20	1		*FRONT FENDER INNER SHIELD LH	Serviceable	225.00 FL	*- FL
21	1		*FRONT FENDER INNER SHIELD RH	Cut	225.00 FL	*225.00 FL
22	1		*BONNET ASSY	Crushed	820.00 FL	*656.00 FL
23	1		*BONNET HINGE LH	Bent	150.00 FL	*105.00 FL
24	1		*BONNET HINGE RH	Bent	150.00 FL	*105.00 FL
25	1		*BONNET INNER TRIM COVER	Serviceable	140.00 FL	*- FL
26	1		*REAR BUMPER	Dented	1,280.50 FL	*650.00 FL
27	1		*REAR BUMPER UPPER LH	Serviceable	460.00 FL	*- FL
28	1		*REAR BUMPER UPPER RH	Serviceable	460.00 FL	*- FL
29	1		*BUMPER TOW HOOK COVER	Scratched	60.00 FL	*60.00 FL
30	1		*REAR BUMPER LOWER BRACKET	Serviceable	115.80 FL	*- FL
31	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	82.00 FL	*- FL
32	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	82.00 FL	*- FL
33	1		*REAR END PANEL	Dented	822.80 FL	*550.00 FL
34	1		*REAR END PANEL INNER MEMBER	Dented	425.00 FL	*425.00 FL
35	1		*REAR END PANEL INNER GARNISH	Crushed	212.60 FL	*212.60 FL
36	1		*REAR PANEL LOCK CATCH LOWER	Serviceable	42.20 FL	*- FL
37	1		*REAR PANEL RUBBER MOULDING	Crushed	150.00 FL	*150.00 FL
38	1		*REAR FLOOR PANEL	Serviceable	1,230.00 FL	*- FL
39	1		*TAIL GATE ASSY	Dented	1,800.00 FL	*1,280.00 FL
40	1		*TAIL GATE TOYOTA LOGO	Necessary	180.00 FL	*90.00 FL
41	1		*TAIL GATE RUBBER MOULDING	Serviceable	150.00 FL	*- FL
42	1		*TAILGATE LOCK UPPER	Jammed	203.60 FL	*203.60 FL
43	1		*TAILGATE OUTER GARNISH	Serviceable	280.00 FL	*- FL
44	1		*TAILGATE OUTER HANDLE	Serviceable	48.90 FL	*- FL
45	1		*TAILGATE INNER PULL POCKET	Serviceable	86.20 FL	*- FL
46	1		*TAILGATE INNER TRIM BOARD	Serviceable	490.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*TAIL GATE HINGE LH	Serviceable	150.00 FL	*- FL
48	1		*TAIL GATE HINGE RH	Serviceable	150.00 FL	*- FL
49	1		*TAIL GATE DAMPER LH	Serviceable	260.00 FL	*- FL
50	1		*TAIL GATE DAMPER RH	Serviceable	260.00 FL	*- FL
51	1		*TAIL GATE TAIL LAMP	Cracked	750.00 FL	*750.00 FL
52	1		*TAIL GATE TAIL LAMP	Cracked	750.00 FL	*750.00 FL
53	1		*TAIL LAMP ASSY LH	Serviceable	1,171.80 FL	*- FL
54	1		*TAIL LAMP ASSY RH	Serviceable	1,171.80 FL	*- FL
55	1		*TAIL LAMP PANEL LH	Serviceable	633.00 FL	*- FL
56	1		*TAIL LAMP PANEL RH	Serviceable	633.00 FL	*- FL
57	1		*TAIL LAMP BOLT COVER LH	Serviceable	109.20 FL	*- FL
58	1		*TAIL LAMP BOLT COVER RH	Serviceable	109.20 FL	*- FL
59	1		*REAR TAIL LAMP SIDE CLIP LH	Serviceable	72.60 FL	*- FL
60	1		*REAR TAIL LAMP SIDE CLIP RH	Serviceable	72.60 FL	*- FL
61	1		*REAR EXHAUST SILENCER	Serviceable	614.70 FL	*- FL
62	1		*REAR EXHAUST CHROME PIPE	Serviceable	120.30 FL	*- FL
63	1		*REAR EXHAUST MOUNTING	Serviceable	85.20 FL	*- FL
64	1		*REAR EXHAUST INSULATOR	Serviceable	89.60 FL	*- FL
65	2		*REVERSE SENSOR	Shorted	150.00 FS	*150.00 FS
66	1		*REAR FLOOR PANEL SEALANT	Serviceable	90.00 FS	*- FS
67	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*30.00 FS
68	1		*REAR WINDSCREEN SEALANT	Necessary	90.00 FS	*30.00 FS
69	1		*REAR WINDSCREEN MOULDING	Necessary	160.00 FS	*40.00 FS
70	15		*FRONT BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
71	15		*REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
72	1		*FRONT NUMBER PLATE WITH CASING	Crushed	85.00 FS	*35.00 FS
73	1		*REAR NUMBER PLATE WITH CASING	Crushed	85.00 FS	*35.00 FS
74	1		*REAR FLOOR COMPARTMENT TRAY	Crushed	680.00 FL	*371.00 FL
75	1		*BONNET LOCK ASSY	Jammed	390.00 FL	*150.00 FL
76	1		*COOLANT	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	31,395.60	14,072.20
- List Item Discount on L Items 25.00/25.00% (\$\$)	7,631.40	3,415.55
Total Parts (\$\$)	23,764.20	10,656.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS.	New	2,100.00	1,600.00
2	TO REMOVE / REFIX WIRING SYSTEM AT ACCIDENT DND CHECK FOR PROPER FUNCTIONS.	New	80.00	30.00
3	TO REMOVE AND REPLACE FRONT SENSORS AND CHECK PROPER FUNCTIONS.	New	100.00	0.00
4	TO REMOVE AND REFIX TAIL GATE MECHANICAL PART TO NEW TAIL GATE ASSY.	New	120.00	60.00
5	TO RESPRAY UNDERCOATING ON PARTS REPLACED.	New	150.00	40.00
6	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED	New	1,800.00	1,500.00
7	TO REPLACE AND CHECK REAR REVERSE SENSOR DISTANCE TEST.	New	120.00	30.00
8	TO REMOVE AND REFIX REAR WINDSCREEN.	New	180.00	120.00
9	AIRCOND GAS	New	60.00	60.00
Gross Labour Cost (\$\$)			4,710.00	3,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >