

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD20002762/UPA3Q2

Date: 14/08/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd.	Policy No: PNMC2020-00000685	
Claimant		
Vehicle No : SJG4044S	Insured Vehicle No : FBL3795H	
Date of Loss: 15/02/2020	Nature of Claim: TP	Claim No: 1202000009103

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJG4044S	
Make & Model:	HONDA CIVIC, 1.3 IMA (A)	Engine No: LDA23037911
Reg. Date:	28/06/2008 (Man. Year: 2008)	Chassis No: JHMF36208S212183
Colour:	Blue	Odometer: 401141 km
Engine Capacity:	1339 cc	
Market Value/New Car Price:	N/A	
Sum Insured (S\$):	Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No
	Footbrake (Serviceable):	Yes
	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,127.28	1,994.48	5,132.80	72.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,600.00	1,590.00	2,010.00	55.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,727.28	3,584.48	7,142.80	66.59
Approved Total (Overridden) (S\$)		2,850.00		
Nett Amount (S\$)	10,727.28	2,850.00	7,877.28	73.43
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
		(S\$)	3,150.00	
Liabe Amount (50.00%) (S\$)		1,575.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		1,611.45		
Global Sum Settlement (S\$)		1,600.00		

INSPECTION

Date of Assignment:	18/02/2020	
Date Inspected:	18/02/2020 Inspected At:	Zoom Autowerks Pte Ltd (HQ)
		130 Bedok Reservoir Road, Eunos
		Spring, #08-1339
		Singapore 470130

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 May 2020)
Parts:	143	HONDA CIVIC 1.3 IMA (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJG4044S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed / Torn	860.00 FL	*638.00 FL
2	2		*REAR BUMPER RETAINER	Not Necessary	120.00 FL	*- FL
3	2		*REAR BUMPER BRACKET	Not Necessary	80.00 FL	*- FL
4	2		*REAR BUMPER REINFORCEMENT	No such part	156.00 FL	*- FL
5	1		*REAR BUMPER CLIPS	Necessary	60.00 FL	*35.00 FL
6	1		*BOOTLID	Dented	852.00 FL	*610.90 FL
7	1		*BOOTLID BADGE	Necessary	75.00 FL	*28.80 FL
8	1		*BOOTLID BADGE (CIVIC)	Necessary	55.00 FL	*35.00 FL
9	1		*BOOTLID BADGE (HYBRID)	Necessary	68.00 FL	*45.00 FL
10	1		*BOOTLID LAMP RH	Not Necessary	425.00 FL	*- FL
11	1		*BOOTLID LAMP CLIPS	Not Necessary	20.00 FL	*- FL
12	1		*BOOTLID INNER LOCK	Not Necessary	196.00 FL	*- FL
13	1		*BOOTLID CATCH	Not Necessary	65.00 FL	*- FL
14	1		*BOOTLID WEATHERSTRIP	Not Necessary	275.00 FL	*- FL
15	1		*REAR TAILLAMP RH	Cracked	720.00 FL	*285.40 FL
16	1		*REAR END PANEL	Dented	725.00 FL	*316.00 FL
17	1		*REAR END PANEL TOP GARNISH	Not Necessary	245.00 FL	*- FL
18	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	60.00 FL	*- FL
19	1		*REAR FENDER INNER SHIELD RH	Torn	195.00 FL	*66.50 FL
20	1		*REAR FENDER INNER SHIELD CLIPS	Not Necessary	60.00 FL	*- FL
21	1		*REAR EXHAUST END PIPE	Repair	1,150.00 FL	*- FL
22	1		*REAR EXHAUST CHROME MUFFLER	Dented	175.00 FL	*120.00 FL
23	2		*REAR EXHAUST PIPE MOUNTING	Not Necessary	116.00 FL	*- FL
24	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	145.00 FL	*- FL
25	1		*SPARE TYRE PANEL	Not Necessary	896.50 FL	*- FL
26	1		*SPARE TYRE TOP TRIM	Not Necessary	195.80 FL	*- FL
27	1		*SPARE TYRE TOP BOARD	Not Necessary	256.30 FL	*- FL
28	1		*SET REVERSE SENSOR	Torn	250.00 FS	*200.00 FS
29	1		*REAR NUMBER PLATE WITH GARNISH	Not Necessary	80.00 FS	*- FS
30	1		*REAR EXHAUST GUM	Not Necessary	120.00 FS	*- FS
31	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,776.60	2,430.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,649.32	436.12
Total Parts (\$\$)	7,127.28	1,994.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PUTTY, SPRAY PAINT ON REAR AFFECTED ACCIDENT AREAS	New	1,200.00	800.00
2	TO REMOVE & RENEW REAR AFFECTED ACCIDENT AREAS	New	1,400.00	600.00
3	TO TRANSFER ALL BOOTLID COMPONENTS TO FACILITATE REPAIRS	New	150.00	60.00
4	TO TRANSFER ALL BOOTLID INTERIOR COMPONENTS TO FACILITATE REPAIRS	New	150.00	0.00
5	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	20.00
6	TO RE-POSITION & INSTALL REVERSE SENSOR	New	150.00	50.00
7	TO CONDUCT WATER LEAKAGE TEST	New	150.00	0.00
8	TO RE-PROGRAMME & RESET DIAGNOSTIC	New	250.00	0.00
9	TO RUST PROOF AFFECTED AREAS	New	100.00	60.00
Gross Labour Cost (\$)			3,600.00	1,590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >