

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20002774/AKA3Q2

Date: 16/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900019112

Claimant
Vehicle No : SDQ3826C **Insured Vehicle No :** SMJ2231E

Date of Loss: 14/02/2020 Nature of Claim: TP Claim No: 6659587556SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDQ3826C		
Make & Model:	NISSAN SUNNY, 1.6 EX (M)	Engine No:	QG16424963
Reg. Date:	18/01/2008 (Man. Year: 2007)	Chassis No:	JN1CFAN16Z0108822
Colour:	Silver	Odometer:	414689 km
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,784.00	4,902.67	2,881.33	37.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,910.00	3,080.00	1,830.00	37.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,694.00	7,982.67	4,711.33	37.11
Approved Total (Overridden) (\$\$)		5,700.00		
(\$\$)	12,694.00	5,700.00	6,994.00	55.10
+ GST 7.00/7.00% (\$\$)	888.58	399.00	489.58	55.10
Nett Amount (\$\$)	13,582.58	6,099.00	7,483.58	55.10
+ Car Rental (11.0 x S\$100.00/day) (\$\$)		1,100.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		7,201.00		
Global Sum Settlement (\$\$)		7,200.00		

INSPECTION

Date of Assignment: 18/02/2020

Date Inspected: 18/02/2020 Inspected At:

Modern Automotive Pte Ltd (HQ)
Blk 3023A Ubi Road 1, #01-61 & #01-58
Singapore 408717

Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	433.50 FL	*433.50 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
3	2		*REAR BUMPER SIDE HOLDER -LH & RH	Necessary	70.40 FL	*70.40 FL
4	1		*REAR BUMPER SPONGE	Cracked	133.80 FL	*133.80 FL
5	1		*REAR BUMPER SIDE BRACKET -LH & RH	N/S Dented	183.40 FL	*91.70 FL
6	1		*REAR BUMPER CHROME MOULDING	Necessary	168.60 FL	*168.60 FL
7	1		*REAR END PANEL	Distorted	376.20 FL	*376.20 FL
8	1		*REAR END PANEL TOP GARNISH	Deformed	69.60 FL	*69.60 FL
9	1		*REAR END PANEL INNER TRIM	Torn	131.10 FL	*131.10 FL
10	2		*TAIL LAMP -LH & RH	N/S Smashed / O/S Cut	526.40 FL	*526.40 FL
11	1		*TAIL LAMP PANEL -LH	Distorted	171.40 FL	*171.40 FL
12	1		*TAIL LAMP LOWER BRACKET -LH	Smashed	38.20 FL	*38.20 FL
13	1		*BOOTLID	Buckled	655.00 FL	*655.00 FL
14	1		*BOOTLID LOCK	Damaged	43.30 FL	*43.30 FL
15	1		*BOOTLID WEATHERSTRIPE	Cut	29.90 FL	*29.90 FL
16	2		*BOOTLID HINGE	Not Necessary	153.20 FL	*- FL
17	1		*BOOTLID LOWER CHROME MOULDING	Not Necessary	173.80 FL	*- FL
18	1		*REAR FENDER -LH	Distorted	894.80 FL	*894.80 FL
19	1		*REAR FENDER INNER TRIM BOARD -LH	Crumpled	212.40 FL	*212.40 FL
20	1		*SET REAR FENDER INNER TRIM BOARD CLIPS-LH	Necessary	30.00 FL	*30.00 FL
21	1		*REAR FENDER INNER SHIELD -LH	Not Necessary	51.20 FL	*- FL
22	1		*SET REAR FENDER INNER SHIELD CLIPS -LH	Not Necessary	10.00 FL	*- FL
23	1		*REAR FENDER WHEEL HOUSE PANEL -LH	Repair	599.10 FL	*- FL
24	1		*REAR FENDER AIR VENT LH	Not Necessary	54.40 FL	*- FL
25	1		*SPARE TYRE PANEL	Repair	771.40 FL	*- FL
26	1		*SPARE TYRE PANEL TOP COVER	Torn	197.80 FL	*197.80 FL
27	1		*REAR CHASSIS MEMBER -LH	Damaged	258.90 FL	*258.90 FL
28	1		*REAR WINDSCREEN MOULDING	Necessary	130.90 FL	*130.90 FL
29	1		*REAR DOOR -LH	Repair	960.10 FL	*- FL
30	1		*REAR DOOR LOCK -LH	Not Necessary	158.80 FL	*- FL
31	1		*NISSAN LOGO	Necessary	33.20 FL	*33.20 FL
32	1		*SUNNY EMBLEM	Necessary	56.20 FL	*56.20 FL
33	1		*EX SALOON EMBLEM	Necessary	57.10 FL	*57.10 FL
34	1		*CVTC EMBLEM	Necessary	49.40 FL	*49.40 FL
35	1		*E-THROTTLE EMBLEM	Necessary	46.50 FL	*46.50 FL
36	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
37	1		*SPARE TYRE PANEL INSULATOR PAD	Necessary	280.00 FS	*200.00 FS
38	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 8,580.00 5,396.30
- List Item Discount on L Items 10.00/10.00% (\$\$) 796.00 493.63

Total Parts (\$\$) 7,784.00 4,902.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO KNOCKING & PULL OUT REAR PORTION & RENEW ABOVE PARTS	New	2,200.00	1,500.00
2	TO PUTTY & SPRAY UP PAINT WORKS	New	1,800.00	1,200.00
3	TO CHECK WIRING	New	100.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE UPHOLSTERY AND REAR SEAT	New	380.00	100.00
6	TO REMOVE FUEL TANK	New	150.00	80.00
7	TO REMOVE REAR WINDSCREEN	New	180.00	120.00
Gross Labour Cost (S\$)			4,910.00	3,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >