

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20002780/ADA3Q2

Date: 23/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100086001

Claimant
Vehicle No : SKX7438T **Insured Vehicle No :** SJG6995J

Date of Loss: 15/02/2020 Nature of Claim: TP Claim No: 8440226210SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKX7438T		
Make & Model:	TOYOTA VELLFIRE, 2.4 Z (A)	Engine No:	2AZC476470
Reg. Date:	29/09/2008 (Man. Year: 2008)	Chassis No:	ANH208016581
Colour:	Black	Odometer:	450323 km
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,887.52	5,843.97	5,043.55	46.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,130.00	2,420.00	710.00	22.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,017.52	8,263.97	5,753.55	41.05
Approved Total (Overridden) (S\$)		6,600.00		
(S\$)	14,017.52	6,600.00	7,417.52	52.92
+ GST 7.00/7.00% (S\$)	981.23	462.00	519.23	52.92
Nett Amount (S\$)	14,998.75	7,062.00	7,936.75	52.92
+ Loss of Use (6.0 x S\$120.00/day) (S\$)		720.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		7,784.00		
Global Sum Settlement (S\$)		7,730.00		

INSPECTION

Date of Assignment: 17/02/2020

Date Inspected: 17/02/2020 Inspected At:

Modern Automotive Pte Ltd (HQ)
Blk 3023A Ubi Road 1, #01-61 & #01-58
Singapore 408717

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	989.70 FL	*989.70 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
3	2		*REAR BUMPER SIDE HOLDER -LH & RH	Necessary	179.00 FL	*179.00 FL
4	2		*REAR BUMPER REFLECTOR -LH & RH	Not Necessary	232.00 FL	*- FL
5	1		*REAR BUMPER TOWING COVER	Not Necessary	35.00 FL	*- FL
6	2		*REAR BUMPER IMPACT BRACKET -LH & RH	Not Necessary	210.40 FL	*- FL
7	1		*REAR END PANEL	Dented	891.10 FL	*891.10 FL
8	1		*REAR END PANEL TOP GARNISH	Deformed	267.00 FL	*267.00 FL
9	1		*REAR END PANEL ANTENNA SENSOR	Damaged	281.50 FL	*281.50 FL
10	2		*TAIL LAMP -LH & RH	Not Necessary	1,302.80 FL	*- FL
11	2		*TAIL LAMP LOWER APRON-LH & RH	Repair	890.80 FL	*- FL
12	1		*TAILGATE	Dented	1,845.50 FL	*1,845.50 FL
13	1		*TAILGATE LOCK	Damaged	481.00 FL	*481.00 FL
14	1		*TAILGATE WEATHERSTRIP	Cut	315.50 FL	*315.50 FL
15	1		*TAILGATE OUTER GARNISH	Cracked	578.20 FL	*578.20 FL
16	1		*SET TAILGATE OUTER GARNISH CLIPS	Necessary	30.00 FL	*30.00 FL
17	1		*TAILGATE REFLECTOR -LH & RH	N/S Cracked	783.00 FL	*391.50 FL
18	1		*TAILGATE INNER TRIM BOARD	Cracked	549.80 FL	*549.80 FL
19	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	30.00 FL	*30.00 FL
20	1		*TAILGATE GLASS MOULDING	Necessary	145.50 FL	*145.50 FL
21	1		*TOYOTA LOGO	Necessary	85.00 FL	*85.00 FL
22	1		*VELIFIRE WORDING	Necessary	75.00 FL	*75.00 FL
23	2		*REAR FENDER INNER TRIM BOARD	Not Necessary	1,496.60 FL	*- FL
24	1		*SET REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	60.00 FL	*- FL
25	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
26	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
27	1		*REAR CAMERA	Not Necessary	480.00 FS	*- FS
28	4		*REVERSE SENSOR	Damaged	860.00 FS	*350.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,244.40	7,635.30
- List Item Discount on L Items 20.00/25.00% (\$\$)	2,356.88	1,791.33
Total Parts (\$\$)	10,887.52	5,843.97

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO KNOCKING & PULL OUT REAR PORTION & RENEW ABOVE PARTS	New	1,200.00	1,000.00
2	TO PUTTY & SPRAT UP PAINT WORKS	New	1,200.00	1,000.00
3	TO CHECK WIRING	New	50.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	60.00
5	TO REMOVE REAR CAMERA	New	100.00	50.00
6	TO REMOVE UPHOLSTERY	New	150.00	80.00
7	TO REMOVE TAILGATE GLASS	New	180.00	120.00
8	TO TRANSFER TAILGATE FITTINGS	New	150.00	80.00
Gross Labour Cost (\$\$)			3,130.00	2,420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >