



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKQ 9799A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BOOT SMART LOCK MODULE (CONSISTENT)	SERVICEABLE	1,110.00	-
2	REAR BOOT SMART LOCK MODULE ANTENNA @\$123.00 (CONSISTENT)	SERVICEABLE	246.00	-
7	REAR LH FENDER WHEEL ARCH CLIP @\$6.00 (CONSISTENT)	NOT NECESSARY	42.00	-
1	REAR TAIL LAMP(LH) (CONSISTENT)	SERVICEABLE	900.00	-
1	REAR BUMPER (AERODYNAMIC) (CONSISTENT)	BUCKLED	2,848.00	1,400.00
2	REAR BUMPER PARKTRONIC SENSOR (LH) @\$333.00 (CONSISTENT)	MISSING	666.00	301.00
4	REAR BUMPER PARKTRONIC SENSOR SEAL (LH) @\$12.00 (CONSISTENT)	NECESSARY	48.00	48.00
2	REAR BUMPER FRAME @\$307.00 (CONSISTENT)	CRACKED (1 PCS ONLY)	614.00	307.00
1	REAR BUMPER TOWING COVERING (AERODYNAMIC) (CONSISTENT)	DENTED	270.00	32.00
1	REAR BUMPER LOWER LIP (CONSISTENT)	CRACKED	480.00	399.00
1	REAR BUMPER REFLECTOR (LH) (CONSISTENT)	CRACKED	111.00	111.00
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	DAMAGED	660.00	660.00
1	REAR TAIL PIPE CHROME (CONSISTENT)	DENTED	285.00	285.00
	LESS 10% DISCOUNT		-828.00	-354.30
			7,452.00	3,188.70
<u>SPECIAL NETT ITEMS</u>				
1	REAR BOOT 'BMW' EMBLEM (SN)(CONSISTENT)	NECESSARY	169.00	105.00
1	REAR BOOT 'X 3' DESIGNATION (SN)(CONSISTENT)	NECESSARY	102.00	68.00
			271.00	173.00
<u>LABOUR</u>				
	REMOVE AND TRANSFER REAR BUMPER NECESSARY ATTACHMENT SPART PART ITEMS. }		1,200.00	250.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE AND REFIT REAR BOOT SMART LOCK MODULE ,REAR BOOT SMART LOCK MODULE ANTENNA,REAR LH FENDER WHEEL ARCH CLIP ,REAR TAIL LAMP (LH) ,REAR BUMPER (AERODYNAMIC),REAR BUMPER PARKTRONIC SENSOR (LH),REAR BUMPER PARKTRONIC SENSOR SEAL (LH) ,REAR BUMPER FRAME ,REAR BUMPER TOWING COVERING (AERODYNAMIC),REAR BUMPER LOWER LIP,REAR BUMPER REFLECTOR(LH),REAR BUMPER REINFORCEMENT,REAR TAIL PIPE CHROME.}		-	-
	HELD/WELD/BEATING/PULL/STRAIGHTEN/ALIGN REAR CHASSIS FRAME BY CHASSIS ALIGNMENT,JACK.}		-	-
	TO CHECK & REFIT REAR TAIL-LAMP WIRING HARNESS.	NOT NECESSARY	120.00	-
	DIAGNOSTIC AND RESET REAR BUMPER PARKTRONIC SENSOR FAULT ERROR BY HHT,		120.00	80.00
	TUFF KOTE REAR DAMAGED PORTION .	NOT NECESSARY	150.00	-
	PUTTY /PRIMER APPLICATION ,SPRAY PAINTING ON REAR BOOT ,REAR BUMPER (AERODYNAMIC),REAR BUMPER PARKTRONIC SENSOR (LH) ,REAR BUMPER TOWING COVERING (AERODYNAMIC).		1,200.00	500.00
			2,790.00	830.00
GRAND TOTAL			10,513.00	4,191.70
RECOMMENDED COST OF REPAIRS				4,191.70

Report Ref No. CC4/ASM20002788/Kga3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.