



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD  
36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877

INV No. AC2005959  
INV Date 01/09/2020  
Reference CC4/FCI20002793/Eda3q2  
Code FCI2



#### PROFESSIONAL SERVICE FEE

Vehicle No. SH 9248B  
Insured Veh. SHA 4409D  
Claim No. D20000936MFSH  
Policy No. D-20094922MFSH  
Accident Date 10/02/2020  
Inspection Date 17/02/2020

Description	Total
Third Party Express Settlement	600.00
<b>Subtotal</b>	<b>600.00</b>
<b>GST (7%)</b>	<b>42.00</b>
<b>Grand Total</b>	<b>642.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI20002793/Eda3q2

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 01-09-2020



Code : FCI2

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SHA 4409D	<b>Veh. Inspected</b>	SH 9248B
<b>Policy No.</b>	D-20094922MFSH	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	D20000936MFSH	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	JASON TEA	<b>Assign Date</b>	17/02/2020

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	TOYOTA PRIUS	<b>c.c</b>	1798
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2018
<b>Chassis No.</b>	JTDKB3FU803077602	<b>Colour</b>	BLUE
<b>Odometer</b>	146952	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	195/65 R15	DAVANTI	5 mm
<b>L/H Front Tyre</b>	195/65 R15	DAVANTI	5 mm
<b>R/H Rear Tyre</b>	195/65 R15	DAVANTI	5 mm
<b>L/H Rear Tyre</b>	195/65 R15	DAVANTI	5 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.
--

### 5. General Information

<b>Accident Date</b>	10/02/2020	<b>Inspection Date</b>	17/02/2020
<b>Survey held at</b>	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>8 Working Days</b>
-------------------------------------	-----------------------



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 9248B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR TRUNK LID COVER	CUT	1,126.60	1,126.60
1	REAR TRUNK LID LOCK	BENT	457.90	457.90
1	REAR TRUNK LID COVER TRIM BOARD	NOT NECESSARY	216.50	-
1	REAR TRUNK LID RUBBER	CRUSHED	365.20	365.20
1	REAR TRUNK LID GLASS (BLACK COLOR)	NOT NECESSARY	1,569.70	-
1	BOARD ASSY ,BACK DOOR TRIM	NOT NECESSARY	254.40	-
1	GARNISH SUB-ASSY ,BACK DOOR ,OUTSIDE	BROKEN	889.70	889.70
1	REAR TRUNK LID LOGO (PRIUS)	NECESSARY	60.80	60.80
1	REAR TRUNK LID LOGO (HYBRID)	NECESSARY	52.40	52.40
1	REAR TRUNK LID LOGO (TOYOTA STAR)	NECESSARY	52.90	52.90
1	REAR BUMPER	BROKEN	458.60	458.60
1	REAR BUMPER REINFORCEMENT	DENTED	318.80	318.80
1	REAR BUMPER UNDER COVER	CUT	552.60	552.60
1	REAR BUMPER SIDE RETAINER	BROKEN	112.70	112.70
1	REAR BUMPER UNDER SIDE COVER (RH)	MISSING	232.00	232.00
1	REAR BUMPER UNDER SIDE CENTRE COVER	DISLODGE	552.60	552.60
1	REAR BUMPER TOWING COVER	MISSING	82.70	82.70
1	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER SIDE CLIP	NECESSARY	25.00	25.00
1	ARM SUB-ASSY ,REAR BUMPER ,RH	NOT NECESSARY	139.60	-
1	ARM SUB-ASSY ,REAR BUMPER ,LH	NOT NECESSARY	139.60	-
1	RETAINER ,REAR BUMPER ,UPPER SIDE	NOT NECESSARY	30.70	-
1	RETAINER ,REAR BUMPER ,SIDE ,RH	BROKEN	94.80	94.80
1	SEAL ,REAR BUMPER SIDE ,RH	DENTED	148.40	148.40
1	SEAL ,REAR BUMPER SIDE ,LH	NOT NECESSARY	148.40	-
2	TAIL LAMP ASSY (UPPER)@\$557.90	BROKEN (1 PCS ONLY)	1,115.80	557.90
2	TAIL LAMP ASSY (LOWER) @\$548.40	CUT (1 PCS ONLY)	1,096.80	548.40
2	TAIL LAMP QUARTER PANEL @\$216.00	TO REPAIR SEE LABOUR	432.00	-
2	TAIL LAMP SIDE COVER @\$256.00	NOT NECESSARY	512.00	-

Report Ref No. CC4/FCI20002793/Eda3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	LAMP ASSY ,SIDE TURN SIGNAL ,RH	NOT NECESSARY	65.30	-
1	LAMP ASSY ,SIDE TURN SIGNAL ,LH	NOT NECESSARY	65.30	-
1	REAR END PANEL	DENTED	602.10	602.10
1	REAR END PANEL GARNISH	CRUSHED	161.80	161.80
1	REAR SPARE TYRE PANEL	NOT NECESSARY	667.70	-
1	REAR SPARE TYRE CUSHION (FLR BOARD CENTRE)	NOT NECESSARY	101.40	-
1	REAR FIBER TOOL BOX TRIM	NOT NECESSARY	398.00	-
1	REAR EXHAUST PIPE	DENTED	1,163.40	1,163.40
1	REAR EXHAUST PIPE HANGER	NOT NECESSARY	40.70	-
1	REAR EXHAUST PIPE INSULATOR	NOT NECESSARY	314.60	-
1	REAR FENDER RH	DENTED	836.70	836.70
2	REAR FENDER SHIELD (LH/RH)	BROKEN	134.20	134.20
2	REAR FENDER ADVERTISEMENT LOGO (LH/RH)	NECESSARY	100.00	100.00
1	REAR FENDER AIR DUCT	BROKEN	165.10	165.10
1	REAR WINDSCREEN GLASS W/MOULDING	NOT NECESSARY	1,778.30	-
1	REAR WINDSCREEN SEALANT	NOT NECESSARY	46.00	-
1	REAR WIRING ASSY	NOT NECESSARY	582.40	-
1	TAPE ,BLACK OUT,NO.1 RH	NOT NECESSARY	45.60	-
1	TAPE ,BLACK OUT,NO.2 RH	NOT NECESSARY	37.30	-
1	SPOILERSUB-ASSY ,REAR	NOT NECESSARY	953.70	-
1	REAR WINDSCREEN MOULDING (ADDITIONAL)	NECESSARY	72.00	72.00
1	REAR WINDSCREEN UPPER MOULDING (ADDITIONAL)	NECESSARY	56.00	56.00
2	REAR WINDSCREEN LOWER SIDE MOULDING @\$60.00 (ADDITIONAL)	NECESSARY	120.00	120.00
1	REAR WINDSCREEN LOWER MOULDING (ADDITIONAL)	NECESSARY	48.00	48.00
	LESS 20% DISCOUNT		-3,963.36	-
	LESS 25% DISCOUNT		-	-2,542.83
			15,853.44	7,628.47
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REVERSE CAMERA (SN)	NOT NECESSARY	320.00	-
1	REAR BUMPER REVERSE SENSOR (SN)	SHORTED	135.70	135.70
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
1	REAR TRUNK LID APPS STICKER (SN)	NECESSARY	40.00	40.00

Report Ref No. CC4/FCI20002793/Eda3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR TRUNK LID COMFORT & TEL NO.STICKER (SN)	NECESSARY	60.00	60.00
			605.70	285.70
	<b>LABOUR</b>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF TAIL LAMP QUARTER PANEL .		1,200.00	1,000.00
	SPRAY PAINTING CHARGE.		1,000.00	800.00
1	WIRING CHARGE.		150.00	30.00
	TUFF KOTE.		150.00	50.00
	TOWING CHARGE.		50.00	50.00
	REMOVE/REFIX REAR WINDSCREEN GLASS .		120.00	120.00
	REMOVE/REFIX REVERSE SENSOR .		120.00	30.00
	REPAIR EXHAUST PIPE.		60.00	50.00
			2,850.00	2,130.00
<b>GRAND TOTAL</b>			<b>19,309.14</b>	<b>10,044.17</b>

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>8,050.00</b>
---	--	--	--	-----------------

Report Ref No. CC4/FCI20002793/Eda3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SH 9248B

### INSPECTION







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SH 9248B

RE-INSPECTION







## **LKK Auto Consultants Pte Ltd**

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SH 9248B

RE-INSPECTION







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

