

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFG 1972E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	NISSAN EMBLEM (CONSISTENT) (N)	NECESSARY	55.00	55.00
1	SUNNY EMBLEM (CONSISTENT) (N)	NECESSARY	114.00	58.00
1	EX SALOON EMBLEM (CONSISTENT) (N)	NECESSARY	119.00	65.00
1	REAR BUMPER (CONSISTENT) (N)	DEFORMED	502.80	502.80
2	REAR BUMPER RETAINER (CONSISTENT) (N)	NECESSARY	72.00	72.00
1	REAR BUMPER CHROME (CONSISTENT) (N)	NECESSARY	196.00	196.00
8	REAR BUMPER CLIPS (CONSISTENT) (N)	NECESSARY	36.80	36.80
1	END PANEL (CONSISTENT) (N)	TO REPAIR SEE LABOUR	369.20	-
	LESS 10% DISCOUNT		-146.48	-98.56
			1,318.32	887.04
	SPECIAL NETT ITEMS			
1	REVERSE SENSOR (CONSISTENT) (SN)	DAMAGED	250.00	200.00
			250.00	200.00
	LABOUR			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF END PANEL .		500.00	200.00
	SPRAY PAINTING.		600.00	400.00
			1,100.00	600.00
	GRAND TOTAL		2,668.32	1,687.04

DECOMMENDED COOT OF LUMP OUR DEDAIDS		4 000 00
RECOMMENDED COST OF LUMP SUM REPAIRS		1,300.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/ASM20002797/Aga3q2



ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.