



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC20002805/Hsf3n2

73 BRAS BASAH ROAD

Date: 14-04-2020

#05-01 NTUC TRADE UNION HOUSESINGAPORE

189556



ATTN: DAVID PHUA

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBB 9320H	Veh. Inspected	PC 6855E
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1084799-001	Excess (\$)	0.00
Assign From	CYNTHIA ANG	Assign Date	18/02/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HIACE	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	KDH2230034496	Colour	WHITE
Odometer	160733 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/ R15C	HABILEAD	6 mm
L/H Front Tyre	195/ R15C	HABILEAD	6 mm
R/H Rear Tyre	195/ R15C	HABILEAD	6 mm
L/H Rear Tyre	195/ R15C	HABILEAD	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	11/02/2020	Inspect Date / Time	18/02/2020 (04:35 PM)
Survey held at	8 KAKI BUKIT AVE 4# 08-45/46 PREMIER		
Repairer	SK AUTOMOBILE PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------