



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM20002809/Hpa3s2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811

Date : 22-04-2020



ATTN: STACEY NG

Code : ASM

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGX 5241D	Veh. Inspected	SKB 7855M
Policy No.	GA383279/1	Coverage (\$)	0.00
Claim No.	S0M02GJ1	Excess (\$)	0.00
Assign From	STACEY NG	Assign Date	18/02/2020

### 2. Vehicle Particulars & Condition

Make & Model	TOYOTA COROLLA	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	MR053REE104119799	Colour	BEIGE
Odometer	141879	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	DUNLOP	5 mm
L/H Front Tyre	195/65 R15	DUNLOP	5 mm
R/H Rear Tyre	195/65 R15	DUNLOP	5 mm
L/H Rear Tyre	195/65 R15	DUNLOP	5 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

### 5. General Information

Accident Date	15/02/2020	Inspection Date	19/02/2020
Survey held at	8 Kaki Bukit Ave 4 #08-46 Premier @ Kaki Bukit		
Repairer	SPEED AUTO WORKS		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------