

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20002812/KEA3Q2

Date: 25/06/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : SMK6064P **Insured Vehicle No :** SMP1626A

Date of Loss: 10/02/2020 **Nature of Claim:** TP **Claim No:** 1457724261SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK6064P		
Make & Model:	MERCEDES-BENZ GLC 250, 2.0 4MATIC (A)	Engine No:	27492031489938
Reg. Date:	16/04/2019 (Man. Year: 2018)	Chassis No:	WDC2539462F457374
Colour:	Metallic White	Odometer:	16020 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R19	Rear Tyre Size:	235/55 R19
Front Left Side:	Pirelli 8 mm	Rear Left Side:	Pirelli 8 mm
Front Right Side:	Pirelli 8 mm	Rear Right Side:	Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	29,029.58	14,303.24	14,726.34	50.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,560.00	1,960.00	1,600.00	44.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	32,589.58	16,263.24	16,326.34	50.10
+ GST 7.00/7.00% (S\$)	2,281.27	1,138.43	1,142.84	50.10
Nett Amount (S\$)	34,870.85	17,401.67	17,469.18	50.10
+ Car Rental (10.0 x S\$150.00/day + 7.00% GST) (S\$)		1,605.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		19,008.67		
Global Sum Settlement (S\$)		19,000.00		

INSPECTION

Date of Assignment: 14/02/2020

Date Inspected: 17/02/2020 Inspected At:

160 SIN MING DRIVE #06-02
Repairer: MBM Wheelpower Pte Ltd
(Sin Ming)

Estimated Period of Repair: 8.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*TAIL GATE	Bent	2,992.00 FL	*2,433.00 FL
2	1	*TAIL GATE WEATHERSTRIP	Serviceable	484.00 FL	*- FL
3	1	*TAIL GATE INNER TRIM	Serviceable	492.00 FL	*- FL
4	10	*TAIL GATE INNER TRIM CLIPS	Not Necessary	90.00 FL	*- FL
5	1	*TAIL GATE INNER HANDLE GARNISH	Serviceable	189.00 FL	*- FL
6	1	*TAIL GATE SWITCH BUTTON	Serviceable	191.00 FL	*- FL
7	1	*TAIL GATE SWITCH COVER	Serviceable	210.00 FL	*- FL
8	1	*TAIL GATE BUZZER	Serviceable	202.00 FL	*- FL
9	1	*FLOOR BOARD COMPARTMENT COVER	Serviceable	1,304.00 FL	*- FL
10	1	*TAIL GATE LAMP RH	Serviceable	680.00 FL	*- FL
11	1	*TAIL GATE LAMP LH	Serviceable	680.00 FL	*- FL
12	1	*TAIL LAMP RH	Serviceable	702.00 FL	*- FL
13	1	*TAIL LAMP LH	Serviceable	702.00 FL	*- FL
14	1	*REAR BUMPER	Buckled	1,350.00 FL	*1,216.00 FL
15	10	*REAR BUMPER RIVETS	Necessary	90.00 FL	*90.00 FL
16	1	*REAR BUMPER LOWER COVER	Dented	540.00 FL	*540.00 FL
17	1	*REAR BUMPER LOWER TRIM	Dented	506.00 FL	*506.00 FL
18	1	*TAIL PIPE COVER RH	Serviceable	199.00 FL	*- FL
19	1	*TAIL PIPE COVER LH	Serviceable	199.00 FL	*- FL
20	1	*REAR BUMPER TOWING COVER RH	Serviceable	90.00 FL	*- FL
21	1	*REAR REINFORCEMENT	Bent	935.00 FL	*730.00 FL
22	1	*REAR BUMPER REFLECTOR RH	Serviceable	70.00 FL	*- FL
23	1	*REAR BUMPER REFLECTOR LH	Serviceable	70.00 FL	*- FL
24	1	*TAIL GATE INNER LOWER TRIM	Serviceable	255.00 FL	*- FL
25	4	*REAR BUMPER SENSORS	Serviceable	1,000.00 FL	*- FL
26	4	*SENSOR SPACER RINGS	Not Necessary	60.00 FL	*- FL
27	1	*EXHAUST PIPE TIP RH	Serviceable	220.00 FL	*- FL
28	1	*EXHAUST PIPE TIP LH	Serviceable	220.00 FL	*- FL
29	1	*RIVET (30 PCS)	Not Necessary	90.00 FL	*- FL
30	1	*END PANEL	Repair	1,702.00 FL	*- FL
31	1	*END PANEL TOP GARNISH	Serviceable	395.00 FL	*- FL
32	10	*END PANEL TOP GARNISH CLIPS	Not Necessary	90.00 FL	*- FL
33	2	*REAR BUMPER SIDE BRACKET LH & RH	Repair	320.00 FL	*- FL
34	1	*TAIL GATE MERCEDES LOGO	Necessary	92.00 FL	*92.00 FL
35	1	*TAIL GATE 4 MATIC EMBLEM	Necessary	145.00 FL	*102.00 FL
36	1	*TAIL GATE GLC 250 EMBLEM	Necessary	145.00 FL	*98.00 FL
37	1	*BONNET	Bent	2,222.00 FL	*1,840.00 FL
38	1	*BONNET MERCEDES BENZ EMBLEM	Necessary	140.00 FL	*140.00 FL
39	1	*FRONT RADIATOR STAR LOGO	Cracked	189.20 FL	*189.20 FL
40	1	*FRONT RADIATOR STAR LOGO BASE PLATE	Cracked	155.00 FL	*155.00 FL
41	1	*FRONT RADIATOR DIAMOND UPPER GRILLE AMG	Cracked	1,200.00 FL	*1,200.00 FL
42	1	*FRONT RADIATOR DIAMOND LOWER GRILLE	Serviceable	299.60 FL	*- FL
43	1	*FRONT BUMPER LICENSE PLATE BASE	Serviceable	198.40 FL	*- FL
44	1	*FRONT BUMPER	Cracked	2,180.00 FL	*1,453.00 FL
45	10	*FRONT BUMPER RIVET	Necessary	90.00 FL	*90.00 FL
46	1	*FRONT BUMPER BASIC CENTRE CARRIER	Serviceable	314.00 FL	*- FL
47	1	*FRONT BUMPER SPONGE	Cracked	280.00 FL	*86.40 FL
48	1	*FRONT BUMPER REINFORCEMENT	Repair	594.00 FL	*- FL
49	2	*FRONT BUMPER SENSOR	Serviceable	551.20 FL	*- FL
50	2	*FRONT BUMPER DECOUPLING RING	Serviceable	133.60 FL	*- FL
51	1	*FRONT BUMPER LOWER GRILLE	Serviceable	196.00 FL	*- FL
52	1	*FRONT BUMPER LOWER TRIM	Serviceable	222.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
53	1		*FRONT BUMPER CHROME CENTRE TRIM	Serviceable	487.20 FL	*- FL
54	1		*FRONT GRILLE TOP AIR GUIDE	Cracked	88.00 FL	*88.00 FL
55	1		*FRONT GRILLE SIDE AIR GUIDE LH	Dented	65.00 FL	*65.00 FL
56	1		*FRONT SUPPORT PANEL TOP	Buckled	350.00 FL	*350.00 FL
57	1		*REAR BUMPER EXHAUST HOLDER LH	Cracked	75.00 FL	*75.00 FL
58	1		*REAR BUMPER EXHAUST HOLDER RH	Cracked	75.00 FL	*75.00 FL
59	1		*REAR BUMPER HEAT SHIELD	Bent	320.00 FL	*260.00 FL
60	1		*REAR BUMPER SENSOR WIRE	Shorted	420.00 FL	*310.00 FL
61	1		*REAR BUMPER LOWER BRACKET RH	Bent	75.00 FL	*75.00 FL
62	1		*HEAD LAMP LH	Mtg Cracked	3,250.00 FL	*3,250.00 FL
63	1		*TAIL GATE LOCK	Dented	295.00 FL	*295.00 FL
64	1		*BODY SEALANT	Necessary	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	32,246.20	15,883.60
- List Item Discount on L Items 10.00/10.00% (S\$)	3,216.62	1,580.36
Total Parts (S\$)	29,029.58	14,303.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,REFIT & REPAIR AFFECTED DAMAGED PARTS ,INCLUDING TO KNOCK OUT ,WELD & STRAIGHTEN ON THE AFFECTED PARTS	New	1,000.00	800.00
2	TO REMOVE & REFIT REAR END PANEL LINING & GARNISH TO FACILITATE REPAIR	New	100.00	60.00
3	TO REALIGN EXHAUST PIPE	New	60.00	0.00
4	TO REMOVE & INSTALL AIRCON COMPONENT INCLUDING CHARGE UP GAS	New	100.00	0.00
5	TO REMOVE & REPLACE REAR BUMPER SENSORS	New	80.00	60.00
6	TO RESET ENGINE WARNING LIGHT (ABS ,SRS,ECU MEMORY & ETC)	New	250.00	0.00
7	TO CHECK & RECONNECT ALL NECESSARY WIRING	New	120.00	40.00
8	TO APPLY ANTI RUST COATING	New	250.00	0.00
9	TO SPRAY PAINT ON THE AFFECTED AREAS	New	1,600.00	1,000.00
Gross Labour Cost (\$\$)			3,560.00	1,960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >