4/12/2021 Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC4/AIG20002814/QGA3Q2

Date:

12/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1900079445

Claimant Vehicle No :

SLJ1346B

Insured Vehicle No:

SMJ8342D

Date of Loss:

14/02/2020

Nature of Claim:

TP

Claim No: 7203322765SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SLJ1346B

Make & Model: HONDA Reg. Date: 29/11/20

HONDA SHUTTLE HYBRID, 1.5 (A) 29/11/2016 (Man. Year: 2016)

Engine No: Chassis No: LEB4263740 GP71043818

Colour:

Red (Man. Year: 2016

Odometer:

168282 km

Engine Capacity:
Market Value/New Car Price:

1496 cc N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: Front Left Side:

185/60 R15 Rovelo 5 mm Rear Tyre Size: Rear Left Side: Rear Right Side: 185/60 R15 Rovelo 5 mm Rovelo 5 mm

Front Right Side:

Rovelo 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,402.88	3,178.88	2,224.00	41.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,200.00	1,800.00	400.00	18.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,602.88	4,978.88	2,624.00	34.51
Approved Total (Overridden) (S\$)		4,000.00		
(S\$)	7,602.88	4,000.00	3,602.88	47.39
+ GST 7.00/7.00% (S\$)	532.20	280.00	252.20	47.39
Nett Amount (S\$)	8,135.08	4,280.00	3,855.08	47.39
+ Loss of Use (7.0 x	S\$50.00/day) (S\$)	350.00		
+ Do	c/Search Fee (S\$)	2.00		
	Nett Liability (S\$)	4,632.00		

INSPECTION

Date of Assignment:

17/02/2020

Lion City Rentals Pte Ltd (HQ)

Date Inspected: 17/02/2020 Inspected At:

60 Jalan Lam Huat, #04-35/36 Carros Centre

Singapore 737569

Estimated Period of Repair:

5.0 days

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_printrpt&caseid=917182&extid=331868&CFID=83555859&C... 1/4

OI SUN PIN Adjuster: Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*F/L FENDER	Dented	1,100.00 FL	*1,100.00 FL
2	1		*F/L FENDER LINER	Crumpled	240.00 FL	*110.00 FL
3	1		*F/L FENDER HYBRID EMBLEM	Necessary	88.60 FL	*88.60 FL
4	1		*REAR BUMPER	Repair	1,850.00 FL	*- FL
5	1		*F/L DOOR	Dented	1,600.00 FL	*1,250.00 FL
6	1		*R/L DOOR	Dented	1,600.00 FL	*1,250.00 FL
7	1		*SET F/L FENDER CLIPS	Necessary	100.00 FS	*20.00 FS
8	1		*F/L WHEEL CAP	Missing	120.00 FS	*120.00 FS
F=Fra	ınchise	part. S=SpcNett	L=ListItemDisc.			
				Sub Total (S\$)	6,698.60	3,938.60
			- List Item Discount on	L Items 20.00/20.00% (S\$)	1,295.72	759.72
				Total Parts (S\$)	5,402.88	3,178.88
			Report was unsubmitte	d during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO LABOUR CHARGE FOR REMOVING OUT F/L FENDER ,F/L DOOR ,R/L DOOR ,R/L FENDER AND REAR BUMPER OUT TO FACILITATE REPLACEMENT OF DAMAGED PARTS	New	1,000.00	800.00
2	TO RESPRAY F/L FENDER ,F/L DOOR ,R/L DOOR ,LH SIDE SILL PANEL AND R/L FENDER	New	1,200.00	1,000.00
	Gross Labour	r Cost (S\$)	2,200.00	1,800.00
	Report was unsubmitted during this pr	int-out.		

< END OF ESTIMATES >