

TPQBE
khanchua

SMD666D.

Toyota Vellfire 2494 cc
JTNGF3PH908015723

Front Number Plate	Bent	30 (sn) ✓
Front Number Plate Holder	Cracked	30 (sn) ✓
Front Number Plate Garment		
Front Bumper	Deformed	<u>1997.98</u> 905
Front Bumper Lips	NA	30 ✓
Front Bumper Side Holder x02	MP NA	$128 \times 2 = 256$ +
Front Bumper Reinforcement	MP NA	452 +
Front Bumper Sponge	MP/NA	85 +
Front Bumper Lower Grille	Deformed	195 ✓
Front Bumper Chrome Moulding	ut	785
Front Bumper Fog Lamp x02	MP NA	$516 \times 2 = 1032$ +
Front Bumper Fog Lamp Chrome Moulding x02	MP/NA	$285 \times 2 = 570$ +
Front Grille	cracked	1748 ✓
Front Grille Logo	NA	65 ✓
Front Grille Chrome Moulding		
Front Grille Clips	NA	20 ✓
Front Brace Panel	Bent	98 ✓

SMD666D.

Headlamp x 02 lit

$$4951.5 \times 2 = 9903 \checkmark$$

Air Con Condenser ^{NP}
_{new}

$$1450.98 \times$$

Rear Bumper Deformed

~~1871.60~~

30 ✓

Rear Bumper Clips New

Rear Bumper Side Holder x 02 ^{NP}
_{new}

$$135 \times 2 = 270 \times$$

Rear Bumper Reflector x 02 ^{NP}
_{new}

$$58 \times 2 = 116. \times$$

Rear Bumper Tow Cover x 02 ^{NP}
_{new}

$$38 \times 2 = 76 \times$$

~~Rear Bumper Impact Bracket x 02~~

836.

Reverse Sensor

x 02

2 pieces
damaged

$$485 \times 4 = \textcircled{1940}$$

Rear End Panel Dented.

798 ✓

Rear End Panel Top Garnish Deformed

165 ✓

Rear End Panel Antenna Sensor ^{NP}
_{new}

167 x.

Rear End Panel Buzzer crumbed

155 ✓

Rear End Panel Sealant. New

60(SN) ✓

Taillamp Lower Apron Garnish x 02

lit torn

$$325 \times 2 = \textcircled{650} \quad 325.$$

SMD666D.

2080

Tailgate	Dented		
Tailgate Lock	Damaged		
Tailgate Weatherstripe	Not New	357	X.
Tailgate Inner Trim Board	cracked	708	✓
Tailgate Inner Trim Board Clips.	Not	30	✓
Tailgate Glass Moulding.	?	78	✓
Tailgate Glass Sealant.	Not	60(SN)	✓
Vellfire Emblem.		90	✓

Rear Fender Inner Trim Board x 2 ^{LH} Def d 1077 x 2 = 2154 1077

Rear Fender Inner Trim Board Clips ^{Not} 60 X

Spare Tyre Lock Screw. Not New 48 X.

Spare Tyre Top Cover. Def d ~~807~~ 567.

22274
16705.50

S.N: 180

SMD666D.

Panel Beating	2000 1200
Spray Painting.	1600 1100
Wiring.	150 60
To remove front bumper sensor	100 50
To remove condenser and radiator and to top up air-con gas. }	180 X
To remove reverse sensor	100 50
To remove rear camera.	100 50
To remove upholstery.	150 60
To transfer tailgate fittings.	150 80
To remove tailgate glass.	180 120

2770

total 1965.50

L/S: 15.7K ✓

09 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: