Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20002818/QEA3Q2

162127 km

Date: 09/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. 1800049446 Policy No: Claimant Insured Vehicle No: SKH4878K SG5864D Vehicle No:

Date of Loss: 10/02/2020 Nature of Claim: ΤP Claim No: 9820986177SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

SG5864D Reg No:

Make & Model: MAN A95, 10.5 D (A) Engine No: 50344772444486 Reg. Date: 27/12/2017 (Man. Year: 2016) Chassis No: WMAA95ZZ7G7003541 Odometer:

Colour: Multi-colour **Engine Capacity:** 10518 cc

Market Value/New Car

N/A

Price: Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification:

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5 Rear Tyre Size: 275/70 R22.5 Goodyear 5 mm Front Left Side: Rear Left Side: Goodyear 5 mm Front Right Side: Goodyear 5 mm Rear Right Side: Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		2,850.00	0.00	2,850.00	100.00
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,320.00	962.00	358.00	27.12
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Nett Amount (S\$)	4,170.00	962.00	3,208.00	76.93
	+ Loss of Use (2.5 x S	\$300.00/day) (S\$)	750.00		

+ Doc/Search Fee (S\$) 7.00 **Nett Liability (S\$)** 1,719.00

INSPECTION

Date of Assignment: 14/02/2020

Date Inspected: 14/02/2020 Inspected At: SMRT Automotive Services Pte Ltd

(Woodlands)

60 Woodlands Industrial Park E4

Singapore 757705

Estimated Period of Repair: 2.0 days

Adjuster: OI SUN PIN Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 4

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty Part	t No.	Particulars	Condition	Repairer's	Amount	
1	1		*O/S FRP REAR LAMP	Repair	975.00 F	*- F	
2	1		*FRP REAR BUMPER	Repair	1,875.00 F	*- F	
F=Fra	anchise part.			Total Parts (S\$)	2,850.00	0.00	
Report was unsubmitted during this print-out.							

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	New	795.00	530.00
2	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	New	525.00	432.00
	Gross Labour Cost (S\$)		1,320.00	962.00
	Report was unsubmitted durin	a this print-out		

< END OF ESTIMATES >